

Bridge Culvert Inspection				
Bridge File Number	75330 -1 Bridge Culvert		Form Type	CUL1
Year Built	1971		Lot No.	4
Bridge or Town Name	BALZAC		Inspector Name	Garry Roberts
Located Over	SERVICE ROADS;CPR		Inspector Class	BR CLS A
Located On	2:15 R1 49.766;2:15 L1 49.870		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	09-Nov-2011
Legal Land Location	SW SEC 4 TWP 26 RGE 29 W4M		Data Entry By	Erin Roberts
Longitude, Latitude	-114:00:05, 51:11:04		Data Entry Date	19-Nov-2011
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Joel Wozney
Contract Main. Area	CMA29		Review Date	10-Nov-2011
Clear Roadway/Skew	47 /		Dept. Reviewer Name	Tim Davies
AADT/Year	66,090 / 2010 (A)		Dept. Review Date	21-Nov-2011
Road Classification	RFD-616.6-130		Follow-Up By	
Detour Length (km)	1			

Bridge Culvert Information								
Number of Culverts		1						
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	PI./Slab Thickness	Shape
1	MAIN	7300	8830	RPP	142.4	152X51	5.0	PIPE ARCH
Special Features								
Special Features Comment								

Posting Information												
Required Vert. Clearance Posting (m)												
Posted Vertical Clearance (Y/N)			No									
Posted:	Lane	EB	On Bridge (m)		In Advance (Y/N)	No	Lane	WB	On Bridge (m)		In Advance (Y/N)	No
Remarks		Not Req.										

Utilities (Located at)				
Utility Attachments				
Telephone	In East ditch and South.		Gas	Crosses road South of pipe.
Power	Crosses road South and East end		Municipal	
Others	Water line South of pipe.		Problem (Y/N)	No
Remarks		FIBRE OPTICS @ E-2 W POWER @ East		

Approach Road / Embankment					
			Last	Now	Explanation of Condition
Horizontal Alignment			7	7	8.4 m East service road.
Vertical Alignment			8	8	8.7 m West service road. Intersection South
					On service roads East and West.
Roadway Width (m)		47.000			
Embankment			7	7	
Sideslope ( __:1)		3.0			
(Height of Cover(m) : 1.4)					
Guardrail (Y/N)		Yes			
<b>Approach Road / Embankment General Rating</b>			<b>7</b>	<b>7</b>	

Upstream End					
<b>Culvert Component</b>			Last	Now	Explanation of Condition
Direction			W		West end.
End Treatment (Concrete, Steel, Others, None)		CONCRETE			
Headwall			7	7	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Collar		6	6	Wide cracks @ SW
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	
Bevel End		7	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	1000			
Scour Protection		6	6	
(Type : <b>NATURAL</b> )				
(Avg. Rock Size(mm) : )				
Scour/Erosion		6	6	Minor erosion @ SW @ toe
Beavers (Y/N)	No			
<b>Upstream End General Rating</b>		<b>6</b>	<b>6</b>	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 7300, Rise (mm): 8830, Type: RPP)				
Barrel Last Accessible Date	09-Nov-2011			Level 2 inspection completed Jan 28/10 See file for details
<b>Special Features</b>				
Special Feature				(REPAIR SECTIONS RAISED 75mm in center and tie top and bottom -grouted after to form beams)
(Type : )				
Special Feature				
(Type : )				
Roof		6	6	Barrel extended at both ends. Original pipe is Rings 10-36 (from west)  Est
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)	210			
Percent Sag	3			
Sidewall		5	5	Span measured at 3 rings- R16-7227, R20-7143, R26-7090 Lower sidewall plates replaced & grouted on East & West end. Inward cusping at both sidewall seams (3rd seam from ballast) approx. 100mm  Diagonal reference measurement taken at lower South sidewall to upper North sidewall R33=6983
Measured Span (mm)	7090			
Measured At Ring No.	26			
Deflection (mm)	210			
Percent Deflection	3			
Floor		N	N	Floor covered in ballast
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams		6	6	Some seams welded at extensions
Separation (mm)	0			
Longitudinal Seams		5	5	Some seams welded at extensions    1N stagger at roof plates
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams	0			
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	No			
Longitudinal Stagger (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 7300, Rise (mm): 8830, Type: RPP)				
Coating		6	6	Isolated corrosion stains at upper seams
Corrosion By Soil (Y/N)	Yes			
Corrosion By Water (Y/N)	No			
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	No			
Fish Passage Adequacy		X	X	
Baffle		X	X	
(Type : )				
Waterway Adequacy		X	X	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
<b>Barrel General Rating</b>		<b>5</b>	<b>5</b>	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		E		East end.
End Treatment (Concrete, Steel, Others, None)	CONCRETE			
Headwall		7	7	Narrow cracks
Collar		7	7	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	
Bevel End		7	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	1000			
Scour Protection		5	5	Natural with some rock
(Type : <b>NATURAL, RIP RAP</b> )				
(Avg. Rock Size(mm) : )				
Scour/Erosion		5	5	200mm deep undermining @ NE under collar @ toe
Beavers (Y/N)	No			
<b>Downstream End General Rating</b>		<b>5</b>	<b>5</b>	
Structure Usage				
		Last	Now	Explanation of Condition
<b>Grade Separation</b>				
Road Alignment		X	X	Track bends inside barrel.
Roadway Surface		7	7	
(Type : )				
Icing (Y/N)	No			
Traffic Safety Features		X	X	
Type				

Structure Usage				
		Last	Now	Explanation of Condition
Lighting		X	X	
Barrel Leakage (Y/N)	Yes			Some active staining on roof.
Drainage		6	6	
Structure In Use (Y/N)	Yes			
<b>Grade Separation General Rating</b>		<b>7</b>	<b>6</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>55.6/55.6</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>66.6/65.9</b>	Est. Repl. Yr	2030	Maint. Reqd. (Y/N)	No
Special Comments for Next Inspection	No obvious changes from 2010 Level 2 inspection to present level inspection. G.Roberts Nov 9, 2011		Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Garry Roberts		Previous Assistant's Name	Rex Davidson			
Next Inspection Date	09-Aug-2013		Previous Inspection Date	28-Jan-2010			
Inspection Cycle (Default) (months)	21						
Comment							