

Bridge Inspection										
Bridge File Number	75337 N-1 Bridge				Form Type	SG				
Year Built/Year Supstr	1962/1962				Lot No.	1				
Bridge or Town Name	RED DEER				Inspector Name	Randy Bredo				
Located Over	CNR				Inspector Class	BR CLS A				
Located On	2:26 R1 2.369				Assistant Name					
Water Body Cl./Year					Assistant Class					
Navigabil. Cl./Year					Inspection Date	18-Oct-2012				
Legal Land Location	SE SEC 8 TWP 39 RGE 27 W4M				Data Entry By	Marcia Chavez				
Longitude, Latitude	-113:51:04, 52:20:15				Data Entry Date	05-Nov-2012				
Road Authority	Alberta Transportation (AIT)				Reviewer Name	John O'Brien				
Contract Main. Area	CMA19				Review Date	01-Nov-2012				
Clear Roadway/Skew	12.2 / 41 deg. (RHF)				Dept. Reviewer Name	Chris Black				
AADT/Year	35,980 / 2011 (A)				Dept. Review Date	30-Nov-2012				
Road Classification	RFD-412.4-130				Follow-Up By					
Detour Length (km)	1									
Allowable Load (t):	Single	CS1 57 GIRDER		Semi	CS2 75 GIRDER		Train	CS3 90 GIRDER		----> On Critical Spans ---->Critical Member
Design Loading:	HS20								----> Primary Span	

Posting Information											
Required Vert. Clearance Posting (m)											
Posted Vertical Clearance (Y/N)		No									
Posted:	Lane	NB	On Bridge (m)		In Advance (Y/N)	No	Lane	SB	On Bridge (m)	In Advance (Y/N)	No
Remarks	Not required										
Required Load Posting (t)		Single				Semi				Truck Train	
Posted Loading (t)		Single				Semi				Truck Train	
Posted:	Lane	NB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No			
Posted:	Lane	SB	At Junction (Y/N)		In Advance (Y/N)		At Bridge (Y/N)				
Remarks	Not required										
Hazard Marker At Bridge (Y/N)		No									
Remarks											
Other Sign Types											

Utilities (Located at)										
Utility Attachments										
Telephone	Yes - no marker.				Gas					
Power					Municipal					
Others					Problem (Y/N)	No				
Remarks										

Approach Road				
		Last	Now	Explanation of Condition
Horizontal Alignment		8	8	Highway crests over RR.
Vertical Alignment		7	7	
Roadway Width (m)	12.100			No rail @ NW corner. Accident damage at NW creasing transition section & shearing 2 splice bolts. Not fully a PL2 standard.
Approach Bump		7	7	
Guardrail (Y/N)	Yes			
Guardrail		7	4	
Length (m)	99.000			
Current Standard (Y/N)	No			NW ditch has caused a shallow slide of the fill which now appears stabilized - monitor.
Termination Type	Turn Down			
Drainage		5	4	
Approach Road General Rating		7	7	

Superstructure					
Bridge Component		Last	Now	Explanation of Condition	
(Primary Span : RB, 3 Spans, Lengths(m): 17.7-22.6-17.7, A-Ident Number: A0385-02)					
Special Features					
Special Feature			X		
(Type :)					
Special Feature			X		
(Type :)					
Wearing Surface/Deck Top Detail Ratings					
	N (%)	1 (%)	2 (%)	3 (%)	
Last	0	0	0	0	
Now	0.0	0.0	0.0	0.0	
Wearing Surface			7	4	Shallow rutting in wheel paths - monitor.
(Material Type : ACP - CONVENTIONAL CHIP SEAL COAT)					
(Thickness(mm) : 50)					
Deck Top			N	N	
Deck Rideability			7	7	
Deck Joints			6	6	7 missing plow deflectors @ S, 6 missing @ N.
Temperature (deg. C)		9			
(Expansion Type : GLAND (SILICON SEAL))					
(Fixed Type :)					
Gap Size (mm)		Gap Location			
75		S. abut			
69		N. abut			
Deck Drainage			7	7	
Drains Clogged (Y/N)		No			
Curbs/Median			5	5	0.3mm to 0.5mm wide transverse cracks @ 0.3 to 1m spacing.
(Curb Type : Standard)					
Scaling (Percent Area)		3			
Bridge Rail			5	5	Retrofit rail installed. Total 7 panels have minor damage. SE parapet vertically cracked, initiated at old approach anchorage at S end & rail anchorage at N end - monitor. Anchor bolts do not offer enough thread for 68 post nuts. 40% have approx 2 threads below top of nut.
(Type : GALVANIZED STEEL VERTICAL BAR)					
Bridge Rail Posts		4	4		
(Type : GALVANIZED POST STEEL; GALVANIZED POST STEEL)					
Bridge Rail/Posts Coating		7	7		
(Type : GALVANIZED)					
Sidewalk			X	X	
Girder/Beam					
Cover Plate		7	7	Griders viewed from ground level.	
Flange		7	7		
Web		7	7		
Stiffeners		7	7		
Splice		7	7		
Weld		7	7		
Diaphragms/Cross Frame		6	7		

Superstructure				
Bridge Component		Last	Now	Explanation of Condition
(Primary Span : RB, 3 Spans, Lengths(m): 17.7-22.6-17.7, A-Ident Number: A0385-02)				
Paint Condition		6	5	1% of topcoat peeled leaving primer. Yellow.
(Colour Description :)				
(Colour Code :)				
Touchup Required (Y/N)	No			
Bearings		5	4	Neoprene pad bearings on curb girders are bulged partly out from under shoe plates. Expansion: abutments. Fixed: piers. Ear retainer plates are cracked through btwn bottom flange & top of rocker at A1G3 side A, A2G1 side A, A2G2 side A & A2G3 side A. Rev'd by consultant and "4" rating is recommended. Bearing contact surfaces left uncoated. Masonry plates pitted from previous corrosion.
Temperature (deg. C)	9			
(Expansion Type : ROCKER BEARING)				
(Fixed Type : REINFORCED PAD BEARING)				
Coating Adequate (Y/N)	No			
Functioning (Y/N)	Yes			
Deck Underside		5	5	Efflorescence @ cracks & corrosion staining @ S2-3. Crack in cold joint of S3. Deck has many narrow flexural cracks; soffits have developed 3% delam cracks, another 10% soon to follow.
Stains (Percent Area)	2			
Span Alignment Problems				
Vertical (Y/N)	No			
Horizontal (Y/N)	No			
Superstructure General Rating		5	4	
Substructure				
Bridge Component		Last	Now	Explanation of Condition
Abutments				
Bearing Seats/Caps		6	6	Abuts have moved slightly from skew pressures.
(Type : CONCRETE)				
Backwalls/Breastwalls		6	6	
Wingwalls		7	7	
Piles		N	N	
Paint/Coating		X	X	
Abutment Stability		7	7	
Scour/Erosion		X	X	
Piers/Bents				
(Type : PIER-COLUMN)				
Bearing Seats/Caps		8	7	2 columns each pier.
(Type : CONCRETE)				
(Total Number of Bearing Piles : 0:0)				
Pier Shaft/Piles		8	7	
Bracing/Struts/Sheathing		X	X	
Nose Plate		X	X	
Paint/Coating		X	X	
(Colour Description :)				
(Colour Code :)				
Pier Stability		8	7	Concrete slope protection sliding against piers.
Scour		X	X	
Debris (Y/N)	No			

Substructure				
Bridge Component		Last	Now	Explanation of Condition
Substructure General Rating		6	6	
Structure Usage				
		Last	Now	Explanation of Condition
Grade Separation				
Road Alignment		X	X	
Traffic Safety Features		X	X	
Type				
Slope Protection		5	5	Gaps between concrete sections but ok. Several wide cracks.
(Type : CONCRETE; CONCRETE)				
Bank Stability		7	7	N fill btwn structures has slide which appears stabilized.
Drainage		7	7	
Grade Separation General Rating		7	7	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
REPAIR/REPLACE BRIDGE RAIL							
GALVANIZE/PAINT BRIDGE RAIL							
RETROFIT BRIDGE RAIL							
SEAL CURBS							
PATCH DECK							
SEAL DECK							
OVERLAY DECK							
REPAIR/REPLACE DECK JOINTS							
RESET/ PAINT BEARINGS							
REPAINT SUPERSTRUCTURE							
STRAIGHTEN/REPLACE MEMBERS							
WASHING							
SHOTCRETE REPAIRS							
REPAIR ABUTMENT SCOUR/EROSION							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
OTHER ACTION	2013	Replace 1 transition section & install 2 splice bolts (approach rail).					
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	61.1/55.6	Sufficiency Rating (Last/Now) (%)	71.9/67.4	Est. Repl. Yr	2037	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection	Monitor for any more cracked bearing ear plates & notify Donald Saunders with AT if found. Girders deflect substantially with skew putting additional strain on deck & diaphragms.		Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)	Y						
Proposed Action	2008.01.29 ACP overlay and membrane in 2008. Chip seal North Bound in 2009.						
Previous Inspector's Name	Owen Salava		Previous Assistant's Name				
Next Inspection Date	18-Jul-2014		Previous Inspection Date	14-Sep-2011			
Inspection Cycle (Default) (months)	21						
Comment	Brng retainer plates are crckd at A1G3 side A, A2G1 side A, A2G2 side A and A2G3 side A. Rev'd by cnsltnt and "4" rating recomended.Monitor other retainer plates for new crcks C.Black_2012.11.05.						