

Level 2 Inspection - Concrete Deck						
Bridge File Number	75946 -1 Bridge			Form Type	CDK	
Year Built/Year Supstr	1968/1968			Lot No.		
Bridge or Town Name	PEACE RIVER			Inspector Name	Jason Saly	
Located Over	90 STREET IN PEACE RIVER;94 STREET IN PEACE RIVER;PEACE RIVER, 8.10, WATERCRS-ST			Inspector Class	BR CLS A	
Located On	2:62 C1 0.311			Assistant Name		
Water Body Cl./Year				Assistant Class		
Navigabil. Cl./Year				Inspection Date	12-Sep-2012	
Legal Land Location	SE SEC 31 TWP 83 RGE 21 W5M			Data Entry By	Jason Saly	
Longitude, Latitude	-117:18:16, 56:14:24			Data Entry Date	27-Feb-2013	
Road Authority	Alberta Transportation (AIT)			Reviewer Name	Paul Carter	
Contract Main. Area	CMA04			Review Date	28-Feb-2013	
Clear Roadway/Skew	8.5 /			Dept. Reviewer Name		
AADT/Year	16,890 / 2012 (A)			Dept. Review Date		
Road Classification	RAU-213.0-120			Follow-Up By		
Detour Length (km)	40			Visual Inspection?	Y	
Allowable Load (t):	Single		Semi		Train	
Design Loading:	HS20					----> On Critical Spans ---->Critical Member
(Primary Span : SSA, Spans: 4,5,6,7, Lengths(m): 124.7-124.7-124.7-92.4)						
(Secondary Span : RB, Spans: 1,2,3,8, Lengths(m): 19.8-28.6-29.2-29)						
(Total Length : 19.8-28.6-29.2-124.7-124.7-124.7-92.4-29 = 573.1)						

Concrete Deck Inspection

		Last	Now	Explanation of Condition		
Wearing Surface						
Polymer? (Y/N)		Y				
ACP? (Y/N)		N				
Chip Seal Coat? (Y/N)		Y				
Seal Coat	Type	Year Installed	Avg. Total Thickness (mm)		Area (m²)	
	CONVENTIONAL CHIP SEAL COAT	2008			4871.4	
Polymer Rating (% Area)						
	9-7	6/5	4	3	2/1	N/X
Last						
Now	0	0	0	0	0	100
ACP Rating (% Area)						
	9-7	6/5	4	3	2/1	N/X
Last						
Now	0	0	0	0	0	100
Chip Seal Coat Rating (% Area)						
	9-7	6/5	4	3	2/1	N/X
Last						
Now	0	90	10	0	0	0
Polymer Total Debonded /Lost Area (m²)						1500
ACP Total Debonded /Lost Area (m²)						X
ACP Average Measured Depth (mm)						X
ACP Crack Frequency (m/m²)						X
Chip Seal Coat Total Lost Area (m²)						18
Random areas of lost seal coat. Some areas weraing smooth.						

Concrete Overlay						
Overlay? (Y/N)		Y				
(Span Type : RB)						
(Span Numbers : 1, 2, 3, 8)						
(Overlay type : CONCRETE (HIGH DENSITY))						

Concrete Deck Inspection						
		Last	Now	Explanation of Condition		
(Area(m ²) : 906.1)						
(Year Installed : 1982)						
(Thickness(mm) : 50)						
(Average Cylinder Strength(Mpa) :)						
Overlay Rating (% Area)						
	9-7	6/5	4	3	2/1	N/X
Last						
Now						
	0	0	0	0	0	100
Total Crack Length - Medium/Wide (m)						N
Total Scaled Area - Light (m ²)						N
Total Scaled Area -Moderate/Heavy/Severe (m ²)						N
Debonded Area (m ²)						18
Spalled Area (m ²)						N
Patched Area (m ²)						N
Average Measured Cover Depth (mm)						110
Standard Deviation of Measured Cover Depth (mm)						16
Covered by epoxy and a chip seal coat wearing surface.						
(Span Type : SSA)						
(Span Numbers : 4, 5, 6, 7)						
(Overlay type : CONCRETE (HIGH DENSITY))						
(Area(m ²) : 3965.3)						
(Year Installed : 1982)						
(Thickness(mm) : 50)						
(Average Cylinder Strength(Mpa) :)						
Overlay Rating (% Area)						
	9-7	6/5	4	3	2/1	N/X
Last						
Now						
	0	0	0	0	0	100
Total Crack Length - Medium/Wide (m)						N
Total Scaled Area - Light (m ²)						N
Total Scaled Area -Moderate/Heavy/Severe (m ²)						N
Debonded Area (m ²)						18
Spalled Area (m ²)						N
Patched Area (m ²)						N
Average Measured Cover Depth (mm)						112
Standard Deviation of Measured Cover Depth (mm)						10
Covered with epoxy and a chip seal coat wearing surface.						
Deck						
(Span Type : RB)						
(Span Numbers : 1, 2, 3, 8)						
(Deck Type : CONCRETE (CLASS C))						
(Area(m ²) : 906.1)						
(Year Constructed : 1968)						
(Year Widened :)						
(Thickness(mm) : 150)						
(Average Cylinder Strength(MPa) :)						
	Type	Size		Design Cover (mm)	Spacing (mm)	
Long. Reinforcing	REINFORCING STEEL	10		40	450	
Trans. Reinforcing	REINFORCING STEEL	15		40	125	

Concrete Deck Inspection									
						Last	Now	Explanation of Condition	
Deck Top Rating (% Area)									Transverse cracking in the deck underside. Plate below snow grate significantly corroded.
	9-7	6/5	4	3	2/1	N/X			
Last									
Now	0	0	0	0	0	100			
Total Crack Length - Medium/Wide (m)							N		
Total Scaled Area - Light (m ²)							N		
Total Scaled Area - Moderate/Heavy/Severe (m ²)							N		
Delaminated Area (m ²)							N		
Spalled Area (m ²)							N		
Patched Area (m ²)							N		
Average Measured Cover Depth (mm)							N		
Standard Deviation of Measured Cover Depth (mm)							N		
Deck Underside Rating (% Area)									
	9-7	6/5	4	3	2/1	N/X			
Last									
Now	0	100	0	0	0	0			
Total Stained Area - Moderate (m ²)							1		
Total Stained Area - Heavy/Severe (m ²)							0		
Total Crack Length - Medium/Wide (m)							75		
% of Medium/Wide Cracks Stained							35		
(Span Type : SSA)									
(Span Numbers : 4, 5, 6, 7)									
(Deck Type : CONCRETE (CLASS C))									
(Area(m ²) : 3965.3)									
(Year Constructed : 1968)									
(Year Widened :)									
(Thickness(mm) : 150)									
(Average Cylinder Strength(MPa) :)									
	Type				Size	Design Cover (mm)	Spacing (mm)		
Long. Reinforcing	REINFORCING STEEL				10	40	450		
Trans. Reinforcing	REINFORCING STEEL				15	40	125		
Deck Top Rating (% Area)									
	9-7	6/5	4	3	2/1	N/X			
Last									
Now	0	0	0	0	0	100			
Total Crack Length - Medium/Wide (m)							N		
Total Scaled Area - Light (m ²)							N		
Total Scaled Area - Moderate/Heavy/Severe (m ²)							N		
Delaminated Area (m ²)							N		
Spalled Area (m ²)							N		
Patched Area (m ²)							N		
Average Measured Cover Depth (mm)							N		
Standard Deviation of Measured Cover Depth (mm)							N		
Deck Underside Rating (% Area)									
	9-7	6/5	4	3	2/1	N/X			
Last									
Now	0	10	0	0	0	90			
Total Stained Area - Moderate (m ²)							0		
Total Stained Area - Heavy/Severe (m ²)							0		
Total Crack Length - Medium/Wide (m)							35		
% of Medium/Wide Cracks Stained							95		
Edge Elements									

Concrete Deck Inspection						
		Last	Now	Explanation of Condition		
Curbs? (Y/N)		N				
Parapets? (Y/N)		Y				
Medians? (Y/N)		N				
Sidewalks? (Y/N)		Y				
Parapets						
Parapet Rating (% Length)						
	9-7	6/5	4	3	2/1	N/X
Last						
Now	0	75	24	1	0	0
Total Crack Length - Medium/Wide (m)					1203	There is vertical cracking along the parapets. There are areas of light to heavy scalling. There are rondon spalls, some spalls have exposed rebar.
Total Scaled Length - Light (m)					139	
Total Scaled Length - Moderate/Heavy/Severe (m)					38	
Delaminated Length (m)					5	
Spalled Length (m)					7.2	
Patched Length (m)					0	
Average Measured Cover Depth (mm)					53	
Standard Deviation of Measured Cover Depth (mm)					12	
Sidewalks						
(Type : CONCRETE)						
(Total Length(m) : 573.1)						
(Height(mm) :)						
(Width(mm) :)						
(Average Cylinder Strength(MPa) :)						
Reinforcement Type			Size	Design Cover (mm)	Spacing (mm)	
Sidewalk Rating (% Length)						
	9-7	6/5	4	3	2/1	N/X
Last						
Now	0	80	15	5	0	0
Total Crack Length - Medium/Wide (m)					726	There is transverse and rondon cracking along the outside edge of the sidewalk there are areas of light to heavy scalling along the sidewalk.
Total Scaled Area - Light (m ²)					125	
Total Scaled Area - Moderate/Heavy/Severe (m ²)					6	
Delaminated Area (m ²)					2	
Spalled Area (m ²)					1	
Patched Area (m ²)					82	
Average Measured Cover Depth (mm)					N	
Standard Deviation of Measured Cover Depth (mm)					N	Not required to take cover measurements along the sidewalk.
Deck Joints						
(Type : COMPRESSION SEAL (ACME SEALS))						
(Number of Joints : 3)						
(Expansion / Fixed? : FIXED)						
(Location : A2, P4, P6)						
% Inspected			100	Could not determine pier joint leakage due to night time testing and height of bridge.		
% Joints Leaks			N			
% Joint Length Leaks			N			
Superstructure Damage Rating			5			
Substructure Damage Rating			5			
Level 1 Joint Rating			5	Abutments have been repaired. Piers are currently under repair.		
(Type : FINGER PLATES)						
(Number of Joints : 3)						
(Expansion / Fixed? : EXPANSION)						
(Location : P3, P5, P7)						

Concrete Deck Inspection									
		Last	Now	Explanation of Condition					
% Inspected			100	Could not determine pier joint leakage due to night time testing and location of piers. Pier repairs currently underway.					
% Joints Leaks			N						
% Joint Length Leaks			N						
Superstructure Damage Rating			5						
Substructure Damage Rating			5						
Level 1 Joint Rating			5						
(Type : WATER STOP)									
(Number of Joints : 1)									
(Expansion / Fixed? : FIXED)									
(Location : A1)									
% Inspected			0	Covered by chipseal coat. Abutment has been repaired.					
% Joints Leaks			0						
% Joint Length Leaks			0						
Superstructure Damage Rating			5						
Substructure Damage Rating			5						
Level 1 Joint Rating			N						
CSE Testing									
Testing Date		14-Jun-2012			Previous Testing Date		17-Jul-2009		
Weather Information									
Temperature (°C)		17							
Conditions		Clear							
Equipment Information									
Test Equipment Make and Model		Corexco CDL - 200 EA/512							
Electrical Ground Location and Type		1AB, second span from the west abutment							
Measurement Locations Information									
Origin for Data		south west							
		Number		Length of Each (m)		Length of Last (m)			
X Increments (Length)		200		1.219		1.200			
Y Increments (Width)		7		1.219		1.200			
CSE Results									
Span Numbers		1,2,3,4,5,6,7,8							
Span Type		RB, SSA							
Wearing Surface		CONVENTIONAL CHIP SEAL COAT, CONCRETE (HIGH DENSITY)							
Testing Year	% Deck Area 0 to -0.1 V	% Deck Area < -0.1 to -0.2 V	% Deck Area < -0.2 to -0.3 V	% Deck Area < -0.3 to -0.4 V	% Deck Area < -0.4 V	Avg. Deck Reading (V)	Std. Dev. Deck Reading	Avg. Curb Reading (V)	Std. Dev. Curb Reading
2012	0.0	6.0	28.9	47.9	17.2	-0.330	0.092	-0.515	0.083
2009	0.0	10.0	56.0	32.0	2.0	-0.274	-0.075	-0.494	-0.068
2005	0.0	4.0	41.0	49.0	6.0	-0.309	0.086	-0.473	0.080
CSE Prediction Model Optimum 5 year Rehab Start Year		2014							
Comments									

Maintenance Recommendations										
Inspector Recommendations	Year	Inspector Comments			Department Comments			Target Year	Est. Cost	Cat #
SEAL CURBS										
PATCH DECK										
SEAL DECK										
OVERLAY DECK										
REPAIR/REPLACE DECK JOINTS										
WASHING										
CRACK REPAIRS/TREATMENT										
PATCH CURBS/PARPETS										
OTHER ACTION										
OTHER ACTION										
OTHER ACTION										
OTHER ACTION										
Structural Condition Rating (%)	38.9	Sufficiency Rating (%)			35.1			Est Repl Year	2043	
Level 1 Insp Date	06-Dec-2011	Next Level 1 Insp Date			06-Sep-2013	Current Level 1 Insp Cycle (Default) (Months)			21	
Special Comments for Next Insp	Observe deck underside for deterioration-span 1 and 8. Observe erosion at West river bank. Monitor concrete sidewalk deterioration.									
Snooper? (Y/N)	No	Lift? (Y/N)	No	Traffic Control? (Y/N)	Yes	Boat? (Y/N)	No	Ladder? (Y/N)	No	
Other Special Requirements Comments	Converted from CDIS									
Previous Level 2 Inspector's Name	Jason Saly			Previous Level 2 Insp Date	17-Jul-2009					
Next Level 2 Insp Date	12-Sep-2016			Discontinue Level 2 Insp? (Y/N)	No					
Level 2 Insp Previously Completed	10			Level 2 Insp Cycle (Default) (Months)	48					
Detailed Report/Diagram? (Y/N)	Yes									
Level 2 Insp Comments	damaged bridgerail along the south parapet on span 1									
Next Level 2 Inspection/Test	Concrete Deck Insp? (Y/N)			Yes	CSE Testing? (Y/N)	Yes	Chloride Testing? (Y/N)		No	
Department Reviewer Comments										