

Bridge Culvert Inspection				
Bridge File Number	76367 -1 Bridge Culvert		Form Type	CUL1
Year Built	1967		Lot No.	2
Bridge or Town Name	NORDEGG		Inspector Name	Owen Salava
Located Over	TRIBUTARY TO NORTH SASKATCHEWAN RIVER, 6.177.1, WATERCRS-ST		Inspector Class	BR CLS A
Located On	11:04 C1 9.172		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	07-Feb-2012
Legal Land Location	NE SEC 1 TWP 38 RGE 18 W5M		Data Entry By	Marcia Chavez
Longitude, Latitude	-116:26:23, 52:14:37		Data Entry Date	06-Mar-2012
Road Authority	Alberta Transportation (AIT)		Reviewer Name	John O'Brien
Contract Main. Area	CMA18		Review Date	22-Feb-2012
Clear Roadway/Skew	13.3 / 30 deg. (RHF)		Dept. Reviewer Name	Andrew Smikles
AADT/Year	840 / 2010 (A)		Dept. Review Date	09-Mar-2012
Road Classification	RAU-213.4-120		Follow-Up By	
Detour Length (km)	300			

Bridge Culvert Information								
Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	2489	1752	RP	54.3	152X51	3.5	PIPE ARCH
Special Features	CONC FLOOR							
Special Features Comment								

Utilities (Located at)			
Utility Attachments			
Telephone	East r/w.	Gas	
Power		Municipal	
Others		Problem (Y/N)	No
Remarks			

Approach Road / Embankment				
		Last	Now	Explanation of Condition
Horizontal Alignment		6	6	In-between two curves limiting sight distance.
Vertical Alignment		7	7	
Roadway Width (m)	13.300			
Embankment		7	7	
Sideslope ( __:1)	2.5			
(Height of Cover(m) : 4)				
Guardrail (Y/N)	Yes			South side only.
<b>Approach Road / Embankment General Rating</b>		<b>6</b>	<b>6</b>	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		W		
End Treatment (Concrete, Steel, Others, None)	CONCRETE			
Headwall		6	6	
Collar		7	7	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		7	7	Minor superficial rust.
Heaving (mm)	0			
Invert Above/Below Stream Bed				
Above/Below (mm)	0			
Scour Protection		4	4	(Concrete being undermined & wide 10mm cracks. 05May2010).
(Type : <b>CONCRETE</b> )				
(Avg. Rock Size(mm) : )				
Scour/Erosion		4	4	
Beavers (Y/N)	No			
<b>Upstream End General Rating</b>		<b>4</b>	<b>4</b>	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 2489, Rise (mm): 1752, Type: RP)				
Barrel Last Accessible Date	07-Feb-2012			
<b>Special Features</b>				
Special Feature		3	3	Sections of concrete floor missing.
(Type : <b>CONC FLOOR</b> )				
Special Feature				
(Type : )				
Roof		7	7	
Measured Rise (mm)	1735			
Measured At Ring No.	4			
Sag (mm)	17			
Percent Sag	0			
Sidewall		7	7	Damage to corrugation, minor abrasion. Superficial rust.
Measured Span (mm)	2510			
Measured At Ring No.	4			
Deflection (mm)	21			
Percent Deflection	0			
Floor		5	5	Approx 60% of concrete floor gone exposing culvert floor, surface corrosion.
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	Yes			
Circumferential Seams		7	7	
Separation (mm)	0			
Longitudinal Seams		7	7	Stagger 1N roof & upper walls only.
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	No			
Longitudinal Stagger (Y/N)	No			
Coating		6	6	Superficial rust.
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 2489, Rise (mm): 1752, Type: RP)				
Fish Passage Adequacy		3	3	Very steep with large turbulence weirs; perched.
Baffle		7	7	H-pile installed across bottom @ 2.5m intervals. Does not protect floor, spaced too far apart - photo.
(Type : WEIR)				
Waterway Adequacy		5	5	Built up behind HP baffles.
Icing (Y/N)	No			
Silting (Y/N)	Yes			
Drift (Y/N)	Yes			
<b>Barrel General Rating</b>		<b>7</b>	<b>7</b>	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		E		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls (Shape : )		X	X	
Cutoff Wall		X	X	Minor superficial rust, minor damage from abrasion.
Bevel End		5	5	
Heaving (mm)	0			
Invert Above/Below Stream Bed	ABOVE			
Above/Below (mm)	1500			
Scour Protection		3	3	Bed is degrading taking away streambed at outlet. 2.0m x 4m x 5m scour hole - photo.
(Type : RIP RAP) (Avg. Rock Size(mm) : 250)				
Scour/Erosion		3	3	
Beavers (Y/N)		No		
<b>Downstream End General Rating</b>		<b>3</b>	<b>3</b>	
Structure Usage				
		Last	Now	Explanation of Condition
<b>Channel (U/S and D/S)</b>				
Alignment		7	7	
Bank Stability		5	5	Some vertical banks D/S of culvert.
HWM (m below Top of Culvert)				HWM not visible. Small drift 100mm diameter.
Drift (Y/N)		Yes		
Channel Bottom Degrading/Aggrading		DEGRADING		
Beavers (Y/N)		No		
(Fish Compensation Measure 1 : NONE) (Fish Compensation Measure 2 : NONE)				
<b>Channel General Rating</b>		<b>7</b>	<b>7</b>	

Maintenance Recommendations										
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #				
SHOTCRETE REPAIRS										
PLACE ADDITIONAL RIP RAP	2012	Class 3, 30m3 @ D/S.								
REMOVE DRIFT ACCUMULATION										
INSTALL CONCRETE/STEEL LINING										
INSTALL STRUTS										
INSTALL CONCRETE COLLAR/CUTOFF										
REPAIR SEAMS										
OTHER ACTION	2012	Replace concrete floor.								
OTHER ACTION	2012	Repair concrete slope protection @ U/S, 5m3.								
OTHER ACTION										
OTHER ACTION										
<b>Structural Condition Rating (Last/Now)</b>	<b>77.8/77.8</b>	<b>Sufficiency Rating (Last/Now)</b>	<b>53.1/53.1</b>	<b>Est. Repl. Yr</b>	<b>2030</b>	<b>Maint. Req. (Y/N)</b>	<b>Yes</b>			
Special Comments for Next Inspection	Department Comments									
Maintenance Reviewed By	Date								Estimated Total	0
Proposed Long-Term Strategy										
On 3-Year Program (Y/N)										
Proposed Action										
Previous Inspector's Name	Owen Salava	Previous Assistant's Name								
Next Inspection Date	07-Nov-2013	Previous Inspection Date	05-May-2010							
Inspection Cycle (Default) (months)	21									
Comment										

**Maintenance Recommendations**

Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #
SHOTCRETE REPAIRS						
PLACE ADDITIONAL RIP RAP	2012	Class 3, 30m3 @ D/S.	Programmed and completed	2012		
REMOVE DRIFT ACCUMULATION						
INSTALL CONCRETE/STEEL LINING						
INSTALL STRUTS						
INSTALL CONCRETE COLLAR/CUTOFF						
REPAIR SEAMS						
OTHER ACTION	2012	Replace concrete floor.	Programmed and completed	2012		
OTHER ACTION	2012	Repair concrete slope protection @ U/S, 5m3.	Programmed and completed	2012		
OTHER ACTION						
OTHER ACTION						
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>77.8/77.8</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>53.1/53.1</b>	Est. Repl. Yr	2030	Maint. Req. (Y/N) Yes
Special Comments for Next Inspection			Department Comments	DA		
Maintenance Reviewed By	Darron Ahlstedt		Date	05-Nov-2012	Estimated Total	0
Proposed Long-Term Strategy						
On 3-Year Program (Y/N)						
Proposed Action						
Previous Inspector's Name	Owen Salava		Previous Assistant's Name			
Next Inspection Date	07-Nov-2013		Previous Inspection Date	05-May-2010		
Inspection Cycle (Default) (months)	21					
Comment						