

Bridge Inspection										
Bridge File Number	77252 -1 Bridge				Form Type	TH TT				
Year Built/Year Supstr	1949/1949				Lot No.	6				
Bridge or Town Name	NORDEGG				Inspector Name	Kris Bosters				
Located Over	BLACKSTONE RIVER, 6.149.8, WATERCRS-ST				Inspector Class	BR CLS A				
Located On	734:20 C1 33.674				Assistant Name	Todd Warshawski				
Water Body Cl./Year					Assistant Class	BR CLS B				
Navigabil. Cl./Year					Inspection Date	21-Aug-2012				
Legal Land Location	NW SEC 18 TWP 43 RGE 16 W5M				Data Entry By	Marcia Chavez				
Longitude, Latitude	-116:19:13, 52:42:45				Data Entry Date	26-Nov-2012				
Road Authority	Alberta Transportation (AIT)				Reviewer Name	John O'Brien				
Contract Main. Area	CMA18				Review Date	01-Nov-2012				
Clear Roadway/Skew	6.7 / 0 deg.				Dept. Reviewer Name	Andrew Smikles				
AADT/Year	180 / 2011 (A)				Dept. Review Date	28-Nov-2012				
Road Classification	RCU-208G-90				Follow-Up By					
Detour Length (km)	20									
Allowable Load (t):	Single	CS1 33 STRINGER		Semi	CS2 52 U2L3		Train	CS3 62		----> On Critical Spans ---->Critical Member
Design Loading:	HS20								----> Primary Span	

Posting Information												
Required Vert. Clearance Posting (m)												
Posted Vertical Clearance (Y/N)			Yes									
Posted:	Lane	NB	On Bridge (m)	4.7	In Advance (Y/N)	Yes	Lane	SB	On Bridge (m)	4.7	In Advance (Y/N)	Yes
Remarks	Slight damage to South VC sign on portal.											
Required Load Posting (t)			Single				Semi				Truck Train	
Posted Loading (t)			Single				Semi				Truck Train 61.0	
Posted:	Lane	NB	At Junction (Y/N)	Yes	In Advance (Y/N)	No	At Bridge (Y/N)	No				
Posted:	Lane	SB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No				
Remarks	NE missing, SW broken & others faded.											
Hazard Marker At Bridge (Y/N)	Yes											
Remarks												
Other Sign Types	Narrow Bridge, Max One Truck, 35 km/hr, "Blackstone River" ID. Steep hill. "Stop if Oncoming Traffic".											

Utilities (Located at)			
Utility Attachments			
Telephone			Gas
Power			Municipal
Others			Problem (Y/N) No
Remarks			

Approach Road				
		Last	Now	Explanation of Condition
Horizontal Alignment		5	5	Curve both ends. 8% grade to N.
Vertical Alignment		4	4	
Roadway Width (m)	7.000			
Approach Bump		5	5	
Guardrail (Y/N)	No			High abuts & steep sideslopes create hazard. 1.5 to 2.1 sideslope & lack of guardrail create safety hazard.
Guardrail		X	X	
Length (m)				
Current Standard (Y/N)	No			
Termination Type	None			
Drainage		4	5	
Approach Road General Rating		4	4	

Superstructure					
Bridge Component		Last	Now	Explanation of Condition	
(Primary Span : TH, 3 Spans, Lengths(m): 45.7-45.7-8.5, A-Ident Number: A0649-01;A0649-02)					
Special Features					
Special Feature			X		
(Type :)					
Special Feature			X		
(Type :)					
Wearing Surface/Deck Top Detail Ratings					
	N (%)	1 (%)	2 (%)	3 (%)	Gravel covered.
Last	100	0	0	0	
Now	40.0	0.0	0.0	0.0	
Wearing Surface/Deck Top			N	6	Ekki wood holding up very well. (1 plank has localized wear 15mm deep. 30Jun2010).
(Material Type : EKKI WOOD)					
(Plank Thickness(mm) : 75)					
(Plank Width(mm) : 200)					
Deck Rideability			7	7	
Deck Joints			X	X	
Temperature (deg. C)		16			
(Expansion Type :)					
(Fixed Type :)					
Gap Size (mm)		Gap Location			
Curbs/Wheel Guards			N	4	9 - 4.5m sectionw with damage/splits; approx. 15 wheel guard blocks are split.
(Curb Type : Standard)					
(Type : TREATED TIMBER)					
(Thickness(mm) : 100)					
(Width(mm) : 300)					
Bridge Rail			4	4	8 panels have minor bends; SW panel of S3 has cracked lower angle by end post. Total of 33 hook bolts missing (32 on bottom). Truss verticals used for support. 1 rail to post rivet missing. Not connected over P2. WLD to lattice rail: S3 panel 1 E, 2W,4W S2 panel 4W. End panels @ corner typically have WLD. Minor corrosion; dirty.
(Type : LATTICE)					
Bridge Rail Posts/Blocking			4	X	
(Type : POST STEEL;POST STEEL)					
Bridge Rail/Posts Coating			4	4	
(Type : PAINT)					
Sidewalk			X	X	

Superstructure						
Bridge Component		Last	Now	Explanation of Condition		
(Primary Span : TH, 3 Spans, Lengths(m): 45.7-45.7-8.5, A-Ident Number: A0649-01;A0649-02)						
Wide Load Damage (Y/N)	No			See UT 2010 report for all missing bolts, fabricating errors and damage to steel; many areas have had heat straightening. To all portals. Diagonals repaired 2011 (3 portals have HLD, 2 have localized cracks & 3 have bolts sheared off - 2010 UT) - Not confirmed. Various bolts missing, see 2010 UT report. Bottom panel points & bottom chords are dirty. 13 stringer X 7 panels X 2 spans.		
High Load Damage (Y/N)	Yes					
Top Chord		5	5			
Batter Posts		6	6			
Sway Bracings		6	6			
Diagonals		3	5			
Verticals		6	6			
Portals		3	N			
Connections		4	4			
Floor Beams		5	5			
Bottom Chord		5	5			
(No. of Stringers : 91;91)						
Stringer Detail Ratings						
	N (count)	1 (count)	2 (count)	3 (count)		
Last						
Now						
Stringers		5	5			
(Type : STEEL)						
(Width(mm) : 135)						
(Depth(mm) : 380)						
(Spacing(mm) : 560)						
Paint Condition		4	4	Up to 30% paint failed.		
(Colour Description : BLUE)						
(Colour Code : 15182;)						
Touchup Required (Y/N)	No					
Bearings		4	4	Expansion bearings have skewed rollers due to corrosion & flattened contact surfaces. Bearings are covered by dirt @ N abut. S2P2 is overexpanded 11mm; S3P2 is over-expanded 40mm. Exp=P2; Fixed=P1, A2 Trusses jammed. Corbels & bearings are nto level.		
Temperature (deg. C)	16					
(Expansion Type : ROLLER NEST BEARING)						
(Fixed Type : PINNED BEARING)						
Functioning (Y/N)	No					
Sub Deck/Deck Underside		6	6			
(Material Type : TREATED TIMBER)						
(Plank Thickness(mm) : 100)						
(Plank Width(mm) : 300)						
Defects (Percent Area)	0					
Span Alignment Problems						
Vertical (Y/N)	No					
Horizontal (Y/N)	No					
Superstructure General Rating		3	3	GR carried forward from 03Dec2010 due to portal rating.		
Superstructure						
Bridge Component		Last	Now	Explanation of Condition		
(Secondary Span : TT)						
Special Features						
Special Feature			X			
(Type :)						
Special Feature			X			
(Type :)						

Superstructure					
Bridge Component		Last	Now	Explanation of Condition	
(Secondary Span : TT)					
Wearing Surface/Deck Top Detail Ratings					
	N (%)	1 (%)	2 (%)	3 (%)	Gravel covered.
Last	100	0	0	0	
Now	20.0	0.0	0.0	0.0	
Wearing Surface/Deck Top			N	7	
(Material Type : EKKI WOOD)					
(Plank Thickness(mm) : 75)					
(Plank Width(mm) : 200)					
Deck Rideability			7	7	
Wheel Guards			N	4	150x300x450 TT blocking. E side has 1 bolt btwn 2 planks @ 2 locations. 2 damaged planks & 6 wheel guard blocks damaged.
(Curb Type : Standard)					
(Type : TREATED TIMBER)					
(Thickness(mm) : 100)					
(Width(mm) : 300)					
Bridge Rail			4	4	Single layer. Not connected to lattice. (3 rail to WG nuts loose. N end rail X posts rotten. 30Jun2010). SW X SE posts leaning.
(Type : FLEX BEAM;GALVANIZED STEEL FLEX BEAM)					
Bridge Rail Posts			3	N	
(Type : TREATED TIMBER;TREATED TIMBER)					
Bridge Rail/Posts Coating			5	5	
(Type : GALVANIZED)					
(No. of Stringers : 13)					
Stringer Detail Ratings					
	N (count)	1 (count)	2 (count)	3 (count)	Wide horizontal checks on outer stringer.
Last	0	0	0	0	
Now	0	0	0	0	
Stringers			7	7	
(Type : TREATED TIMBER)					
(Width(mm) : 200)					
(Depth(mm) : 500)					
(Spacing(mm) : 565)					
Sub Deck/Deck Underside			6	6	Stains at isolated locations.
(Material Type : TREATED TIMBER)					
(Plank Thickness(mm) : 100)					
(Plank Width(mm) : 300)					
Defects (Percent Area)		0			
Span Alignment Problems					
Vertical (Y/N)		No			
Horizontal (Y/N)		No			
Superstructure General Rating			6	6	
Substructure					
Bridge Component		Last	Now	Explanation of Condition	
Abutments					
(Extended Backwall Piles (Y/N) : Y)					0+2 ext. N abut only S cap tilted plywood shim in front. S abut - 1 full length 305 x 305 TT cap. N abut - 8 HP 250 x 62 corbel, 2 full length 305 x 305 TT caps, 2 short 305 x 305 caps.
(Extended Backwall Piles Spacing(mm) : 1000)					

Substructure						
Bridge Component		Last	Now	Explanation of Condition		
(Total Number of Caps/Corbels : 1:12)				Cored in 2012.		
Bearing Seats/Caps/Corbels Detail Ratings						
	N (count)	1 (count)	2 (count)			3 (count)
Last	0	0	0			0
Now	0	0	0			2
Bearing Seats/Caps/Corbels		4	3	N abut, top W backwall cap is rotated. W breastwall cap is rotated. Top N backwall cap is only bearing 50% on 3 piles. S backwall caps are shimmed. S abut cap has minor split in E end. Cap under E corbels on N abut is rotten. Upper W cap on N abut is split.		
(Type : TREATED TIMBER)						
(Depth(mm) : 305)						
(Width(mm) : 350)						
Backwalls/Breastwalls		4	4	1 broken plank at N abut.		
Greatest Height (m)		2.30				
Wingwalls		5	4	Top plank missing at SE with vegetation growing at missing plank.		
(Total Number of Bearing Piles : 5:17)				S abut 5 - HP 250x62. Cored in 2012.		
Piles Detail Ratings						
	N (count)	1 (count)	2 (count)			3 (count)
Last	0	0	0			0
Now	0	0	0			7
Piles		6	3	Several split piles with single bands. 3 centre piles on N backwall have <1/2 cap supported, but floor beam takes the load. Vertical blocks above P1,3,9 on N backwall are rotten.		
Paint/Coating		X	4			
Abutment Stability		5	4	Backwalls pushing in. N backwall & breastwall caps rotating.		
Scour/Erosion		7	7			
Piers/Bents						
(Type : PIER-COLUMN)				P2 concrete. P1: 6 - HP 250 x 62 corbels, 1 full length HP 310 x 94, 2 short HP 310 x 94, 1 short 305 x 305 TT, 1 full length 305 x 350 TT. P1 TT & HP.		
(Total Number of Caps/Corbels : 11:2)						
Bearing Seats/Caps/Corbels Detail Ratings						
	N (count)	1 (count)	2 (count)			3 (count)
Last	0	0	0			0
Now	2	0	0	0		
Bearing Seats/Caps/Corbels		5	5	P1S1 top spacer plank notched at each stringer.		
(Type : CONCRETE)						
(Total Number of Bearing Piles : 18:0)				P1 piles with steel capitals. "H" shaped concrete, P2.		
Piles Detail Ratings						
	N (count)	1 (count)	2 (count)			3 (count)
Last	100	0	0			0
Now	0	0	0			3
Pier Shaft/Piles			N	3	Piles in P2 encased in concrete, not counted. Top corners of P2 spalling but adequate. P1, N caps have rotated & are shimmed with plywood. P1 has 1 rotten block & 2 split blocks. Tops of piles with capitals are not treated.	
Greatest Height (m)		10.40				
Bracing/Struts/Sheathing		6	6	Small holes cut into TT sheathing at P1. No problem		
Nose Plate		6	6			
Paint/Coating		X	4	Steel caps, corbels & piles not painted & have light surface rust.		
(Colour Description :)						
(Colour Code :)						

Substructure				
Bridge Component		Last	Now	Explanation of Condition
Pier Stability		7	7	
Scour		7	7	
Debris (Y/N)	No			
Substructure General Rating		4	3	
Structure Usage				
		Last	Now	Explanation of Condition
Channel				
(U/S Direction : W)				Curves U/S & D/S. Creek enters river at NW. Flow forced against N side due to gravel bed.
(D/S Direction : E)				
Alignment		6	6	
Bank Stability		6	6	
HWM (m below Top of Curb)				(HWM 4m.) 94/06/21. HWM not visible.
Drift (Y/N)	Yes			Minor drift.
Slope Protection		7	7	Class 3 rock placed @ toe of N hslp only.
(Type : NATURAL; RIP RAP)				
Guidebank/Spurs		7	7	Appears to be very long guidebank to SW along right bank, several hundred metres long.
Adequacy of Opening		8	8	
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		6	6	

Proposed Long-Term Strategy			
On 3-Year Program (Y/N)			
Proposed Action			
Previous Inspector's Name	Owen Salava	Previous Assistant's Name	
Next Inspection Date	21-Nov-2015	Previous Inspection Date	03-Dec-2010
Inspection Cycle (Default) (months)	39		
Comment			