

Bridge Culvert Inspection								
Bridge File Number	77266 -1 Bridge Culvert				Form Type	CUL1		
Year Built	1970				Lot No.	1		
Bridge or Town Name	WRENTHAM				Inspector Name	Jon Davies		
Located Over	MIDDLE COULEE, 11.9.4, WATERCRS-ST				Inspector Class	BR CLS B		
Located On	36:02 C1 18.774				Assistant Name			
Water Body Cl./Year					Assistant Class			
Navigabil. Cl./Year					Inspection Date	06-Dec-2011		
Legal Land Location	NW SEC 2 TWP 6 RGE 17 W4M				Data Entry By	Anne Roberts		
Longitude, Latitude	-112:12:09, 49:26:55				Data Entry Date	14-Jan-2012		
Road Authority	Alberta Transportation (AIT)				Reviewer Name	Garry Roberts		
Contract Main. Area	CMA24				Review Date	18-Dec-2011		
Clear Roadway/Skew	10.8 /				Dept. Reviewer Name	Tim Davies		
AADT/Year	540 / 2010 (A)				Dept. Review Date	18-Jan-2012		
Road Classification	RAU-211.8-110				Follow-Up By			
Detour Length (km)	3							
Bridge Culvert Information								
Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	PI./Slab Thickness	Shape
1	MAIN	2316	2560	SPE	30.5	152X51	2.8	ELLIPSE
Special Features								
Special Features Comment								
Utilities (Located at)								
Utility Attachments								
Telephone					Gas			
Power					Municipal			
Others					Problem (Y/N)	No		
Remarks								
Approach Road / Embankment								
			Last	Now	Explanation of Condition			
Horizontal Alignment			9	9	Rise to N			
Vertical Alignment			7	7				
Roadway Width (m)	10.800							
Embankment			3	3	4m long by 1.5m DP x 2 m wide erosion hole at South side of D/S barrel- starts just behind the bevel West end. U/S East end has 3 m long x 2 m wide x 1 m deep erosion hole of embankment.			
Sideslope (:1)	3.0							
(Height of Cover(m) : 2.2)								
Guardrail (Y/N)	Yes							
Approach Road / Embankment General Rating			7	7				
Upstream End								
Culvert Component			Last	Now	Explanation of Condition			
Direction			E					
End Treatment (Concrete, Steel, Others, None)	STEEL							
Headwall			X	X				
Collar			X	X				
Wingwalls			X	X				
(Shape :)								
Cutoff Wall			X	X				

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		N	4	Damage at crown extending down bevel side. Dent pushed in 300 mm.
Heaving (mm)	500			
Invert Above/Below Stream Bed	ABOVE			
Above/Below (mm)	100			
Scour Protection		N	4	Rip rap not complete at South side bevel.
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		N	4	
Beavers (Y/N)	No			
Upstream End General Rating		6	4	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 2316, Rise (mm): 2560, Type: SPE)				
Barrel Last Accessible Date	06-Dec-2011			
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		N	6	
Measured Rise (mm)	2484			
Measured At Ring No.	3			
Sag (mm)	76			
Percent Sag	3			
Sidewall		N	3	Cracked seams
Measured Span (mm)	2411			
Measured At Ring No.	3			
Deflection (mm)	95			
Percent Deflection	4			
Floor		N	N	300 mm of water and ice.
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		N	6	longit seam.]
Separation (mm)	20			
Longitudinal Seams		N	3	90mm remaining steel @ ring 3 South wall seam Rings 2,3,4 have cracks on south wall longit seam.
Total No. of Cracked Rings	3			
Total No. of Rings with Two Cracked Seams	0			
Min. Remaining Steel Between Cracks (mm)	90			
Proper Lap (Y/N)	No			
Longitudinal Stagger (Y/N)	No			
Coating		N	4	Corrosion with some pitting at floor & @ lower haunches and bevel end floors.
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 2316, Rise (mm): 2560, Type: SPE)				
Fish Passage Adequacy		4	5	
Baffle (Type :)		X	X	
Waterway Adequacy		4	4	(HWM to top of pipe at U/S end) 24 June 2010 D/S is scouring at side of bevel and South side of barrel
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		3	3	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		W		
End Treatment (Concrete, Steel, Others, None)		STEEL		
Headwall		X	X	
Collar		X	X	
Wingwalls (Shape :)		X	X	
Cutoff Wall		X	X	
Bevel End		3	5	
Heaving (mm)	0			
Invert Above/Below Stream Bed		ABOVE		
Above/Below (mm)	500			
Scour Protection (Type : RIP RAP) (Avg. Rock Size(mm) : 300)		3	3	No rock or fill at sides of bevel Approx 16m diameter scour hole
Scour/Erosion		3	3	[D/S 12 x 18 x 0.5 m, scour hole is well rip rapped] 10 May 2008 Erosion hole 4m long by 1.5m wide x 1.5m deep @ South side of barrel
Beavers (Y/N)		No		
Downstream End General Rating		3	3	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		5	5	2 channels-1 aligns well with pipe 1 @ 45 deg to pipe
Bank Stability		N	4	Some erosion on the banks at u/s and d/s.
HWM (m below Top of Culvert)	0.0			HWM not visible
Drift (Y/N)		No		
Channel Bottom Degrading/Aggrading		DEGRADING		
Beavers (Y/N)		No		
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		5	5	GR carried forward

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP	2012	Repair scour at stream, sides of bevel and South side of barrel. Est 30m3 clay and 50m3 class 2 rock					
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	33.3/33.3	Sufficiency Rating (Last/Now) (%)	35.4/39.7	Est. Repl. Yr	2015	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Tom Carey		Previous Assistant's Name				
Next Inspection Date	06-Sep-2013		Previous Inspection Date	24-Jun-2010			
Inspection Cycle (Default) (months)	21						
Comment							