

Bridge Culvert Inspection			
Bridge File Number	77420 -1 Bridge Culvert	Form Type	CULM
Year Built	1971	Lot No.	2
Bridge or Town Name	WESTLOCK	Inspector Name	Todd Warshawski
Located Over	TRIBUTARY TO WABASH CREEK, 8.11.84.17.7, WATERCRS-ST	Inspector Class	BR CLS B
Located On	44:00 C1 62.628	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	16-Apr-2013
Legal Land Location	NW SEC 21 TWP 59 RGE 26 W4M	Data Entry By	Theresa Lacusta
Longitude, Latitude	-113:51:03, 54:07:13	Data Entry Date	22-Apr-2013
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Eric Carcoux
Contract Main. Area	CMA10	Review Date	21-Apr-2013
Clear Roadway/Skew	11.5 /	Dept. Reviewer Name	Brent Herrick
AADT/Year	3,890 / 2012 (A)	Dept. Review Date	23-Apr-2013
Road Classification	RAU-211.8-110	Follow-Up By	
Detour Length (km)	8		

Bridge Culvert Information

Number of Culverts	2							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	1600	MP	30	125X26	2.8	ROUND
2	MAIN	-	1600	MP	30	125X26	2.8	ROUND
Special Features								
Special Features Comment								

Utilities (Located at)

Utility Attachments			
Telephone	East r/w.	Gas	West r/w.
Power		Municipal	
Others		Problem (Y/N)	No
Remarks	S pipe tagged on u/s crown		

Approach Road / Embankment

		Last	Now	Explanation of Condition
Horizontal Alignment		7	7	Curve to the south. Field entrance 20m SE.
Vertical Alignment		9	9	
Roadway Width (m)	11.500			Wide crack in ACP over North pipe.
Embankment		8	8	
Sideslope (__:1)	6.0			
(Height of Cover(m) : 0.8)				
Guardrail (Y/N)	No			
Approach Road / Embankment General Rating		7	7	

Upstream End

Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Span Type: Secondary Span)				
Direction		E		South pipe.
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Span Type: Secondary Span)				
Cutoff Wall		X	X	
Bevel End		7	N	Snow covered
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	200			
Scour Protection		5	N	Fillcrete lined inlet channel. Cracked. Bevel end detached from fillcrete by 75mm.
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				Snow covered
Scour/Erosion		6	N	
Beavers (Y/N)	No			
Upstream End General Rating		5	5	GR carried fwd from July, 2011
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Secondary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1600, Type: MP)				
Barrel Last Accessible Date	06-Jul-2011			Unstable ice. Viewed from ends, shape and condition appear ok.
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		8	N	At c/l.
Measured Rise (mm)	1580			
Measured At Ring No.				
Sag (mm)	20			
Percent Sag	1			
Sidewall		8	N	At c/l.
Measured Span (mm)	1589			Inward deflection.-July,2011
Measured At Ring No.				
Deflection (mm)	11			
Percent Deflection				
Floor		8	N	
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		7	N	
Separation (mm)	30			
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		5	N	0.5m under strip along invert.-July, 2011
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Secondary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1600, Type: MP)				
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	No			
Fish Passage Adequacy		X	X	
Baffle		X	X	
(Type :)				
Waterway Adequacy		8	8	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		8	N	GR was 8 from July, 2011
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Span Type: Secondary Span)				
Direction		W		South pipe. Snow covered
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls (Shape :)		X	X	
Cutoff Wall		X	X	
Bevel End		7	N	
Heaving (mm)	0			
Invert Above/Below Stream Bed				
Above/Below (mm)	0			
Scour Protection (Type : RIP RAP) (Avg. Rock Size(mm) : 300)		8	N	
Scour/Erosion		8	N	
Beavers (Y/N)	No			
Downstream End General Rating		7	7	GR carried fwd from July, 2011
Upstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Span Type: Primary Span)				
Direction		E		North pipe. SNOW covered
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls (Shape :)		X	X	
Cutoff Wall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Span Type: Primary Span)				
Bevel End		5	N	
Heaving (mm)	100			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	200			
Scour Protection		4	N	Fillcrete lined inlet channel. Fillcrete cracked. Bevel end detached from fillcrete. Approx 200mm gap under bevel. This is potential scour problem.-Jul-2011
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		5	N	
Beavers (Y/N)	No			
Upstream End General Rating		4	4	GR carried fwd from Jul, 2011
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1600, Type: MP)				
Barrel Last Accessible Date	06-Jul-2011			Unstable ice Viewed from ends, shape and vondition appear ok.
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		8	N	At c/l.
Measured Rise (mm)	1584			
Measured At Ring No.				
Sag (mm)	16			
Percent Sag	0			
Sidewall		8	N	At c/l.
Measured Span (mm)	1600			
Measured At Ring No.				
Deflection (mm)	0			
Percent Deflection	0			
Floor		8	N	
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		7	N	
Separation (mm)	30			
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		7	N	
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	NEG			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1600, Type: MP)				
Ponding (Y/N)	No			
Fish Passage Adequacy		X	X	
Baffle		X	X	
(Type :)				
Waterway Adequacy		8	8	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		8	N	GR was 8 from July, 2011.
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Span Type: Primary Span)				
Direction		W		North pipe. Snow covered
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		7	N	
Heaving (mm)	0			
Invert Above/Below Stream Bed				
Above/Below (mm)	0			
Scour Protection		8	N	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		8	N	
Beavers (Y/N)	No			
Downstream End General Rating		8	8	GR carried fwd from July, 2011
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		5	5	U/S end @ 90 degree angle to ditch.
Bank Stability		8	8	
HWM (m below Top of Culvert)				HWM not visible.
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading				Stable.
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		5	5	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION	2013	Seal cracks in ACP					
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	88.9/55.6	Sufficiency Rating (Last/Now) (%)	79.4/61.4	Est. Repl. Yr	2056	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Kris Bosters		Previous Assistant's Name				
Next Inspection Date	16-Jan-2015		Previous Inspection Date	06-Jul-2011			
Inspection Cycle (Default) (months)	21						
Comment							