

Bridge Culvert Inspection			
Bridge File Number	77455 -1 Bridge Culvert	Form Type	CUL1
Year Built	1972	Lot No.	2
Bridge or Town Name	GOODRIDGE	Inspector Name	Wade Nanninga
Located Over	TRIBUTARY TO BEAVER RIVER, 7.15, WATERCRS-ST	Inspector Class	BR CLS A
Located On	55:16 C1 0.122	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	09-Apr-2012
Legal Land Location	NE SEC 28 TWP 63 RGE 9 W4M	Data Entry By	Lisa Fairhurst
Longitude, Latitude	-111:17:50, 54:29:05	Data Entry Date	25-Apr-2012
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Eric Carcoux
Contract Main. Area	CMA08	Review Date	25-Apr-2012
Clear Roadway/Skew	13.5 /	Dept. Reviewer Name	Brent Herrick
AADT/Year	1,590 / 2011 (A)	Dept. Review Date	04-May-2012
Road Classification	RAU-211.8-110	Follow-Up By	
Detour Length (km)	5		

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	2314	SP	52.4	152X51	3.0,3.0,3.5	ROUND
Special Features	VERT STEEL STRUTS							
Special Features Comment								

Utilities (Located at)

Utility Attachments			
Telephone		Gas	
Power	N Row - buried	Municipal	
Others		Problem (Y/N)	No
Remarks			

Approach Road / Embankment

		Last	Now	Explanation of Condition
Horizontal Alignment		7	7	Intersection with SH 881 (S) is 100 m west. Crest curve to east. Acceleration / deceleration lanes over pipe.
Vertical Alignment		7	7	
Roadway Width (m)	13.500			
Embankment		7	7	
Sideslope (__:1)	3.5			
(Height of Cover(m) : 4)				
Guardrail (Y/N)	Yes			
Approach Road / Embankment General Rating		7	7	

Upstream End

Culvert Component		Last	Now	Explanation of Condition
Direction		N		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		6	6	
Heaving (mm)	300			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	300			
Scour Protection		N	N	Beaver dam @ u/s end covering slope protection
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		5	5	
Beavers (Y/N)	Yes			Large dam @ U/S opening.
Upstream End General Rating		4	4	G.R. carried over from 15/Nov/2006.
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1 , Primary Span, Location Code: MAIN , Span (mm): , Rise (mm): 2314 , Type: SP)				
Barrel Last Accessible Date	11-Aug-2008			Barrel half full and thin ice
Special Features				
Special Feature		3	N	(Top horizontal strut across North opening is broken & bent - photo. Vertical struts are bending under load - photo. 13Jun10)
(Type : VERT STEEL STRUTS)				
Special Feature				
(Type :)				
Roof		N	N	Roof starting to exhibit reverse curvature @ 10:00 seam -11-Aug-2008
Measured Rise (mm)	2330			(Measurement taken prior to strutting?)
Measured At Ring No.				
Sag (mm)	222			
Percent Sag	10			
Sidewall		N	N	16.5%-11-Aug-2008
Measured Span (mm)	2695			
Measured At Ring No.				
Deflection (mm)	381			
Percent Deflection	17			
Floor		N	N	
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		N	N	
Separation (mm)	0			
Longitudinal Seams		N	N	(There are 13 rings in total. Of the 10 with cracks, 8 have 2 cracked seams 25 mm of steel remaining. Water leaking into barrel @ longitudinal seam, U/S end. Superficial rusting. Cracked seams @ 4 & 8 o'clock.-11-Aug-2008)
Total No. of Cracked Rings	10			
Total No. of Rings with Two Cracked Seams	8			
Min. Remaining Steel Between Cracks (mm)	25			
Proper Lap (Y/N)	No			
Longitudinal Stagger (Y/N)	No			
Coating		4	N	(Lower half scaling. 13Jun10)
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2314, Type: SP)				
Fish Passage Adequacy		3	4	Hampered by large dam @ U/S end.
Baffle		X	X	
(Type :)				
Waterway Adequacy		5	5	(Has flown 3/4 full. 99/07/01) (Iced to within 900mm of roof. 13Jun10)
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	Yes			
Barrel General Rating		2	2	General Rating carried over from 11Aug08
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		S		
End Treatment (Concrete, Steel, Others, None)		STEEL		
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		5	5	
Heaving (mm)	200			
Invert Above/Below Stream Bed		ABOVE		
Above/Below (mm)	500			
Scour Protection		4	4	Bevel unsupported for 1.0m.
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		4	4	Scour hole 5.0m x 5.0m x .6m off bevel. Outfall of 500 mm.
Beavers (Y/N)		Yes		Beaver dam 30 m D/S is okay as is.
Downstream End General Rating		4	4	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		7	7	
Bank Stability		8	8	
HWM (m below Top of Culvert)				HWM not visible.
Drift (Y/N)		Yes		(Drift / debris to 1.5m above crown. Not sure if from HW or dam removal.- 13Jul10)
Channel Bottom Degrading/Aggrading		DEGRADING		
Beavers (Y/N)		Yes		
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		7	7	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION	2012	Repair damaged struts and install additional struts.					
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	22.2/22.2	Sufficiency Rating (Last/Now) (%)	31.0/31.9	Est. Repl. Yr	2013	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection	Monitor long. seams leaking into barrel, possibly piping outside barrel - 10Dec02 Monitor scour/erosion @ outlet. Inspect @ 12 month cycle until replaces (LRS issued via email to Brent Herrick on 11Aug08) LRA issued to Brent Herrick on 20Jun10		Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Shane Hall		Previous Assistant's Name				
Next Inspection Date	09-Jan-2014		Previous Inspection Date	14-Jul-2010			
Inspection Cycle (Default) (months)	21						
Comment							