

Bridge Inspection									
Bridge File Number	77547 E-1 Bridge				Form Type	PSR			
Year Built/Year Supstr	1974/1974				Lot No.	1			
Bridge or Town Name	MIDNAPORE				Inspector Name	Garry Roberts			
Located Over	BOW RIVER, 2.13, WATERCRS-ST				Inspector Class	BR CLS A			
Located On	22X:04 R1 2.534				Assistant Name				
Water Body Cl./Year					Assistant Class				
Navigabil. Cl./Year					Inspection Date	28-Jan-2013			
Legal Land Location	SE SEC 25 TWP 22 RGE 1 W5M				Data Entry By	Erin Roberts			
Longitude, Latitude	-114:00:40, 50:53:37				Data Entry Date	19-Feb-2013			
Road Authority	Alberta Transportation (AIT)				Reviewer Name	Tom Carey			
Contract Main. Area	DEERFOOT/STONE Y				Review Date	06-Feb-2013			
Clear Roadway/Skew	12.2 /				Dept. Reviewer Name	Tim Davies			
AADT/Year	15,870 / 2011 (A)				Dept. Review Date	21-Feb-2013			
Road Classification					Follow-Up By				
Detour Length (km)	1								
Allowable Load (t):	Single	CS1 28	Semi	CS2 49	Train	CS3 62	----> On Critical Spans ---->Critical Member		
Design Loading:	HS25						----> Primary Span		

Posting Information									
Required Load Posting (t)	Single		Semi		Truck Train				
Posted Loading (t)	Single		30.0	Semi	47.0	Truck Train	63.0		
Posted:	Lane	EB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	Yes	
Posted:	Lane	WB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No	
Remarks	On temporary signs. Carries EB traffic only. Appears posting not required.								
Hazard Marker At Bridge (Y/N)	No								
Remarks									
Other Sign Types	City file tag 3118 on P1.								

Utilities (Located at)									
Utility Attachments									
Telephone	In area.				Gas				
Power	Underground in area.				Municipal	Sewage forcemain at SW.			
Others	Street lights.				Problem (Y/N)	No			
Remarks									

Approach Road									
			Last	Now	Explanation of Condition				
Horizontal Alignment			7	7					
Vertical Alignment			6	6					
Roadway Width (m)	13.000								
Approach Bump			7	7					
Guardrail (Y/N)					Wrong lap at SW and NW.				
Guardrail			8	3	Accident damage to 1 w-beam and 1 post at NW.				
Length (m)	30.000								
Current Standard (Y/N)	Yes								
Termination Type	TURNED DOWN								
Drainage			8	7					
Approach Road General Rating			7	6					

Superstructure							
Bridge Component		Last	Now	Explanation of Condition			
(Primary Span : VF, 6 Spans, Lengths(m): 36.6-36.6-36.6-36.6-30.5-30.5, A-Ident Number:)							
Special Features							
Special Feature			7	Dwydag bars.			
(Type : EXT LATER POST TENS)							
Special Feature			X				
(Type :)							
Wearing Surface/Deck Top Detail Ratings							
	N (%)	1 (%)	2 (%)	3 (%)			
Last							
Now	10.0	0.0	0.0	0.0			
Wearing Surface				6	8		
(Material Type : ACP)							
(Thickness(mm) : 50)							
Lateral Connection Problem (Y/N)		No					
Deck Top				N	N		
Deck Rideability				7	8		
Deck Joints					4		
Temperature (deg. C)		-1		Sealed glands at abuts. Koch joints at all piers. Staining at abuts and piers may be previous to joint installments or may indicate joint leakage. Wide cracks in koch joints at P3 and P4. Pier gaps measured at sidewalk. A2=90mm.			
(Expansion Type : ARMoured GLAND (WABO UNDER FINGER OR SLIDING PLATES);GLAND (WABO-MAUER, TRANSFLEX, ETC))							
(Fixed Type :)							
Gap Size (mm)		Gap Location					
100		West abut					
50		P1					
45		P2					
80		P3					
50		P4					
45		P5					
Deck Drainage				8	4		
Drains Clogged (Y/N)		No					
Curbs/Median				7	7		
(Curb Type : NEW JERSEY;Standard)							
Scaling (Percent Area)		5					
Bridge Rail				8	8		
(Type : GALVANIZED STEEL VERTICAL BAR)							
Bridge Rail Posts				8	4		
(Type : GALVANIZED POST STEEL)							
Bridge Rail/Posts Coating				7	7		
(Type : GALVANIZED)							
Sidewalk				6	3		
Heavy scaling. Span 1 south fascia is spalling over path and road. Also spalled at P4 and at SE.							
Girder Detail Ratings							
	N (count)	1 (count)	2 (count)	3 (count)			
Last							
Now	18	0	0	12			
Span 3 and 4 not accessible for full inspection. Span 1 - G9 has high load damage with visible corroding strand and rebar.							

Superstructure				
Bridge Component		Last	Now	Explanation of Condition
(Primary Span : VF, 6 Spans, Lengths(m): 36.6-36.6-36.6-36.6-30.5-30.5, A-Ident Number:)				
Girders		8	3	Corrosion cracks and heavy staining at NW underside from weep tubes. Wide vertical cracks at NW and at South over P3, P4, P5 exterior girders. Typical chamfer cracks extending into deck underside. Span 5- G1 wide cracks, G2 wide crack and spall, Span 6- G1 wide crack and spall, G2 wide crack, G8 and G9 high load damage with spalling at G9.
Cracking (Y/N)	No			
Spalling (Percent Area)	10			
(Number Of Girders : 54)				
Diaphragms/Cross Frame		8	8	
Bearings		7	7	(Expansion Type : REINFORCED NEOPRENE BEARING WITH TEFLON AND STAINLESS STEEL) (Fixed Type :)
Temperature (deg. C)	-1			
Coating Adequate (Y/N)	Yes			
Functioning (Y/N)	Yes			
(Expansion Type : REINFORCED NEOPRENE BEARING WITH TEFLON AND STAINLESS STEEL)				
(Fixed Type :)				
Deck Underside		7	7	
Stains (Percent Area)	0			
Span Alignment Problems				
Vertical (Y/N)	No			
Horizontal (Y/N)	No			
Superstructure General Rating		5	3	
Substructure				
Bridge Component		Last	Now	Explanation of Condition
Abutments				
Bearing Seats/Caps		6	4	Spall at NW from low cover rebar.
(Type : CONCRETE)				
Backwalls/Breastwalls		7	7	
Wingwalls		7	4	Minor spall at SW.
Piles		N	N	Buried.
Paint/Coating		3	5	
Abutment Stability		8	8	
Scour/Erosion		8	5	Minor erosion at SE headslope and wing.
Piers/Bents				
(Type : PIER-SOLID)				P2 and P3 are patched at North ends.
Bearing Seats/Caps		4	7	
(Type : CONCRETE)				Wide vertical settlement cracks in all shafts.
(Total Number of Bearing Piles : 0:0:0:0:0)				
Pier Shaft/Piles		4	6	
Bracing/Struts/Sheathing		X	X	Minor spall at SW.
Nose Plate		5	7	
Paint/Coating		5	5	(Colour Description :) (Colour Code :)
(Colour Description :)				
(Colour Code :)				
Pier Stability		9	8	
Scour		N	N	Water too deep at P2, P3, P4. P1 and P5 are dry.

Substructure				
Bridge Component		Last	Now	Explanation of Condition
Debris (Y/N)	No			
Substructure General Rating		4	4	
Structure Usage				
		Last	Now	Explanation of Condition
Channel				
(U/S Direction : N)				Local roads and paths under span 1 and 6. Posted V.C. at 5.0 m.
(D/S Direction : S)				
Alignment		8	8	
Bank Stability		8	8	
HWM (m below Top of Curb)				No visible HWM.
Drift (Y/N)	No			
Slope Protection		8	8	
(Type : RIP RAP; RIP RAP)				
Guidebank/Spurs		X	X	
Adequacy of Opening		9	8	
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		8	8	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
REPAIR/REPLACE BRIDGE RAIL	2013	1 post 1 rail at NW approach.					
GALVANIZE/PAINT BRIDGE RAIL							
SEAL CURBS	2013	Path South fascia approx 10m2.					
PATCH DECK							
SEAL DECK	2013	Epoxy sealer on sidewalk					
OVERLAY DECK							
REPAIR/REPLACE DECK JOINTS	2013	Seal koch joints P3, P4. Flood test all joints.					
RESET/ PAINT BEARINGS							
WASHING							
SHOTCRETE REPAIRS							
REPAIR ABUTMENT SCOUR/EROSION							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
OTHER ACTION	2013	Level 2 girder inspection. Investigate and repair girder cracks and spalls. Repair high load damage at Sp 1 - G9, Sp 6- G8, G9.					
OTHER ACTION	2013	Install V.C. signs at SW and SE and in advance.					
OTHER ACTION	2013	Repair NW abutment spall approx 0.5m2.					
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	50.0/38.9	Sufficiency Rating (Last/Now) (%)	72.4/51.0	Est. Repl. Yr	2025	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Keith Holliston		Previous Assistant's Name				
Next Inspection Date	28-Oct-2014		Previous Inspection Date	04-Dec-1987			
Inspection Cycle (Default) (months)	21						
Comment							