

Bridge Culvert Inspection			
Bridge File Number	77880 -1 Bridge Culvert	Form Type	CUL1
Year Built	1974	Lot No.	4
Bridge or Town Name	ATHABASCA	Inspector Name	Wade Nanninga
Located Over	2ND ORDER TRIBUTARY TO ATHABASCA RIVER, 8.11.65.2, WATERCRS-ST	Inspector Class	BR CLS B
Located On	813:02 C1 10.304	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	06-Jan-2011
Legal Land Location	NW SEC 16 TWP 67 RGE 22 W4M	Data Entry By	Theresa Lacusta
Longitude, Latitude	-113:18:38, 54:48:08	Data Entry Date	02-Feb-2011
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Arnold Assenheimer
Contract Main. Area	CMA10	Review Date	12-Jan-2011
Clear Roadway/Skew	8.2 / 50 deg. (RHF)	Dept. Reviewer Name	Brent Herrick
AADT/Year	990 / 2009 (A)	Dept. Review Date	02-Feb-2011
Road Classification	RCU-209-110	Follow-Up By	
Detour Length (km)	5		

Bridge Culvert Information								
Number of Culverts		1						
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	1724	1901	SPE	37.2	152X51	3.0	ELLIPSE
Special Features								
Special Features Comment								

Utilities (Located at)			
Utility Attachments			
Telephone	West r/w.	Gas	
Power	2 wires East r/w.	Municipal	
Others	Fibre optic West r/w.	Problem (Y/N)	No
Remarks	BF tag installed on top of East bevel end.		

Approach Road / Embankment				
		Last	Now	Explanation of Condition
Horizontal Alignment		7	7	Farm entrances N & S.
Vertical Alignment		8	8	
Roadway Width (m)	8.200			
Embankment		8	8	
Sideslope (__:1)	4.0			
(Height of Cover(m) : 1)				
Guardrail (Y/N)	No			
Approach Road / Embankment General Rating		7	7	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		E		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Cutoff Wall		X	X	
Bevel End		7	7	
Heaving (mm)	100			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	100			
Scour Protection		6	6	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 250)				
Scour/Erosion		7	6	Grassed in.
Beavers (Y/N)	No			
Upstream End General Rating		7	6	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 1724, Rise (mm): 1901, Type: SPE)				
Barrel Last Accessible Date	06-Jan-2010			200mm ice along floor
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		7	7	
Measured Rise (mm)				
Measured At Ring No.				est
Sag (mm)	10			
Percent Sag	1			
Sidewall		7	7	
Measured Span (mm)	1750			
Measured At Ring No.	4			
Deflection (mm)	26			
Percent Deflection	2			
Floor		6	N	Medium scaling, flaking.
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		7	7	
Separation (mm)	0			
Longitudinal Seams		7	7	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	No			
Longitudinal Stagger (Y/N)	No			
Coating		4	4	Rust lower 1/4, scaling.
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	NEG			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 1724, Rise (mm): 1901, Type: SPE)				
Ponding (Y/N)	No			
Fish Passage Adequacy		X	6	
Baffle		X	X	
(Type :)				
Waterway Adequacy		8	8	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		7	7	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		W		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		4	4	Tear in bevel end, North side.
Heaving (mm)	100			
Invert Above/Below Stream Bed				
Above/Below (mm)	0			
Scour Protection		6	6	Grassed in.
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 250)				
Scour/Erosion		7	6	
Beavers (Y/N)	No			
Downstream End General Rating		4	4	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		8	8	
Bank Stability		8	8	
HWM (m below Top of Culvert)				HWM not visible.
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading				
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		8	8	

Structure Usage				
		Last	Now	Explanation of Condition

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	77.8/77.8	Sufficiency Rating (Last/Now) (%)	76.9/75.9	Est. Repl. Yr	2024	Maint. Req'd. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Dave Lam		Previous Assistant's Name				
Next Inspection Date	06-Apr-2014		Previous Inspection Date	08-Aug-2007			
Inspection Cycle (Default) (months)	39						
Comment							