

Bridge Inspection									
Bridge File Number	78154 -1 Bridge				Form Type	SG			
Year Built/Year Supstr	2003/2003				Lot No.	4			
Bridge or Town Name	FORT MCMURRAY				Inspector Name	Wade Nanninga			
Located Over	63:11 L1 9.520;63:11 R1 9.492				Inspector Class	BR CLS A			
Located On	25154:02 L1 0.009;25154:02 R1 0.009				Assistant Name				
Water Body Cl./Year					Assistant Class				
Navigabil. Cl./Year					Inspection Date	16-Nov-2011			
Legal Land Location	NW SEC 10 TWP 89 RGE 9 W4M				Data Entry By	Theresa Lacusta			
Longitude, Latitude	-111:21:22, 56:42:22				Data Entry Date	12-Dec-2011			
Road Authority	Alberta Transportation (AIT)				Reviewer Name	Eric Carcoux			
Contract Main. Area	CMA07				Review Date	23-Nov-2011			
Clear Roadway/Skew	11.4 /				Dept. Reviewer Name	Brent Herrick			
AADT/Year	1,000 / 2011 (E)				Dept. Review Date	15-Dec-2011			
Road Classification	RLU-208-110				Follow-Up By				
Detour Length (km)	1								
Allowable Load (t):	Single	CS1 28	Semi	CS2 49	Train	CS3 62	----> On Critical Spans ---->Critical Member		
Design Loading:							----> Primary Span		

Posting Information												
Required Vert. Clearance Posting (m)												
Posted Vertical Clearance (Y/N)		Yes										
Posted:	Lane	NB	On Bridge (m)	5.6	In Advance (Y/N)	Yes	Lane	SB	On Bridge (m)	5.6	In Advance (Y/N)	Yes
Remarks												
Required Load Posting (t)		Single			Semi			Truck Train				
Posted Loading (t)		Single			Semi			Truck Train				
Posted:	Lane	WB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No				
Posted:	Lane	EB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No				
Remarks		Not required.										
Hazard Marker At Bridge (Y/N)		No										
Remarks		Not required.										
Other Sign Types		Information, 30kph										

Utilities (Located at)									
Utility Attachments									
Telephone					Gas				
Power					Municipal				
Others	Street lights.				Problem (Y/N)	No			
Remarks									

Approach Road				
		Last	Now	Explanation of Condition
Horizontal Alignment		6	6	On / off ramps.
Vertical Alignment		7	7	Crest curve. Traffic circle immediately East. Bridge posted for 30km/h
Roadway Width (m)	11.400			
Approach Bump		8	8	
Guardrail (Y/N)	Yes			Jersey barriers at 4 corners - in between tube rail and flexbeam. Minor creasing to rail on NE ramp.
Guardrail		7	7	
Length (m)	99.000			
Current Standard (Y/N)	Yes			
Termination Type	Turn down			
Drainage		8	8	

Approach Road					
			Last	Now	Explanation of Condition
<b>Approach Road General Rating</b>			6	6	
Superstructure					
Bridge Component			Last	Now	Explanation of Condition
(Primary Span : <b>WG, 2 Spans, Lengths(m): 36-32, A-Ident Number: )</b>					
Special Features					
Special Feature				X	
(Type : )					
Special Feature				X	
(Type : )					
Wearing Surface/Deck Top Detail Ratings					
	N (%)	1 (%)	2 (%)	3 (%)	Dirt/snow along curbs.
<b>Last</b>	20	0	0	0	
<b>Now</b>	20.0	0.0	0.0	0.0	
Wearing Surface			6	6	Transverse and longitudinal cracking.
(Material Type : <b>ACP</b> )					
(Thickness(mm) : <b>80</b> )					
Deck Top			N	N	
Deck Rideability			8	8	
Deck Joints			7	7	
Temperature (deg. C)		-15			
(Expansion Type : <b>GLAND (WABO-MAUER, TRANSFLEX, ETC)</b> )					
(Fixed Type : )					
Gap Size (mm)		Gap Location			
80		East abutment			
105		West Abutment			
Deck Drainage			7	7	No deck drains.
Drains Clogged (Y/N)					
Curbs/Median			7	N	Typical transverse cracking.
(Curb Type : <b>Standard</b> )					
Scaling (Percent Area)		0			
Bridge Rail			8	8	
(Type : <b>GALVANIZED STEEL TUBE BEAM TYPE 2</b> )					
Bridge Rail Posts			8	8	
(Type : <b>GALVANIZED POST STEEL;GALVANIZED POST STEEL</b> )					
Bridge Rail/Posts Coating			8	8	
(Type : <b>GALVANIZED</b> )					
Sidewalk			X	X	
Girder/Beam					
Cover Plate			X	X	
Flange			9	9	
Web			9	9	
Stiffeners			9	9	
Splice			9	9	
Weld			9	9	

Superstructure				
Bridge Component		Last	Now	Explanation of Condition
(Primary Span : <b>WG, 2 Spans, Lengths(m): 36-32, A-Ident Number: )</b>				
Diaphragms/Cross Frame		8	8	
Paint Condition		7	6	Weathering steel.
(Colour Description : )				
(Colour Code : )				
Touchup Required (Y/N)	No			
Bearings		8	8	
Temperature (deg. C)	-15			
(Expansion Type : <b>REINFORCED NEOPRENE BEARING WITH TEFLON AND STAINLESS STEEL</b> )				
(Fixed Type : <b>REINFORCED NEOPRENE BEARING WITH TEFLON AND STAINLESS STEEL</b> )				
Coating Adequate (Y/N)	Yes			
Functioning (Y/N)	Yes			
Deck Underside		7	7	Couple of transverse cracks with efflorescence.
Stains (Percent Area)	0			
<b>Span Alignment Problems</b>				
Vertical (Y/N)	No			
Horizontal (Y/N)	No			
<b>Superstructure General Rating</b>		<b>7</b>	<b>7</b>	
Substructure				
Bridge Component		Last	Now	Explanation of Condition
<b>Abutments</b>				
Bearing Seats/Caps		8	8	
(Type : <b>CONCRETE</b> )				
Backwalls/Breastwalls		8	8	
Wingwalls		7	7	SW corner has minor cracks with efflorescence
Piles		N	N	
Paint/Coating		7	7	
Abutment Stability		9	9	
Scour/Erosion		9	8	
<b>Piers/Bents</b>				
(Type : <b>PIER-COLUMN</b> )				Viewed from headslopes
Bearing Seats/Caps		9	9	
(Type : <b>CONCRETE</b> )				
(Total Number of Bearing Piles : <b>0</b> )				
Pier Shaft/Piles		9	9	
Bracing/Struts/Sheathing		X	X	
Nose Plate		X	X	
Paint/Coating		9	9	
(Colour Description : )				
(Colour Code : )				
Pier Stability		9	9	
Scour		9	9	

Substructure				
Bridge Component		Last	Now	Explanation of Condition
Debris (Y/N)	No			
<b>Substructure General Rating</b>		<b>8</b>	<b>8</b>	
Structure Usage				
		Last	Now	Explanation of Condition
<b>Grade Separation</b>				
Road Alignment		8	8	High load warning system in advance.
Traffic Safety Features		8	8	
Type	W flexbeam			
Slope Protection		6	6	Top of East concrete slope protection pulled away 70mm.
(Type : <b>CONCRETE; CONCRETE</b> )				
Bank Stability		8	8	
Drainage		6	7	
<b>Grade Separation General Rating</b>		<b>6</b>	<b>6</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
REPAIR/REPLACE BRIDGE RAIL							
GALVANIZE/PAINT BRIDGE RAIL							
RETROFIT BRIDGE RAIL							
SEAL CURBS							
PATCH DECK							
SEAL DECK							
OVERLAY DECK							
REPAIR/REPLACE DECK JOINTS							
RESET/ PAINT BEARINGS							
REPAINT SUPERSTRUCTURE							
STRAIGHTEN/REPLACE MEMBERS							
WASHING							
SHOTCRETE REPAIRS							
REPAIR ABUTMENT SCOUR/EROSION							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>83.3/83.3</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>75.3/73.5</b>	Est. Repl. Yr	2078	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Arnold Assenheimer		Previous Assistant's Name	Wade Nanninga			
Next Inspection Date	16-Aug-2013		Previous Inspection Date	09-Mar-2010			
Inspection Cycle (Default) (months)	21						
Comment							