

Bridge Culvert Inspection			
Bridge File Number	78510 -1 Bridge Culvert	Form Type	CUL1
Year Built	1979	Lot No.	1
Bridge or Town Name	MORLEY	Inspector Name	Jon Davies
Located Over	TRIBUTARY TO LITTLE JUMPINGPOUND CREEK, 2.13.43.3.2, WATERCRS-ST	Inspector Class	BR CLS B
Located On	68:04 C1 35.812	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	12-Sep-2012
Legal Land Location	NW SEC 7 TWP 25 RGE 5 W5M	Data Entry By	Lauren Korte
Longitude, Latitude	-114:41:55, 51:07:14	Data Entry Date	10-Oct-2012
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Garry Roberts
Contract Main. Area	CMA28	Review Date	21-Sep-2012
Clear Roadway/Skew	12.3 /	Dept. Reviewer Name	Tim Davies
AADT/Year	310 / 2011 (A)	Dept. Review Date	11-Oct-2012
Road Classification	RAU-211.8-110	Follow-Up By	
Detour Length (km)	16		

**Bridge Culvert Information**

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	2317	2561	SPE	42.1	152X51	3.0	ELLIPSE
Special Features	BEAVR CTRL DEV							
Special Features Comment								

**Utilities (Located at)**

Utility Attachments							
Telephone	East ditch.			Gas	x-ing 100m South.		
Power	West row.			Municipal			
Others				Problem (Y/N)	No		
Remarks							

**Approach Road / Embankment**

	Last	Now	Explanation of Condition
Horizontal Alignment	6	6	Located in curve.
Vertical Alignment	7	7	
Roadway Width (m)	12.300		
Embankment	7	7	
Sideslope ( __:1)	3.0		
(Height of Cover(m) : 3.3)			
Guardrail (Y/N)	Yes		
<b>Approach Road / Embankment General Rating</b>	<b>6</b>	<b>6</b>	

**Upstream End**

Culvert Component	Last	Now	Explanation of Condition
Direction	E		
End Treatment (Concrete, Steel, Others, None)	STEEL		
Headwall	X	X	
Collar	X	X	
Wingwalls	X	X	
(Shape : )			
Cutoff Wall	X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		7	5	
Heaving (mm)	100			
Invert Above/Below Stream Bed	ABOVE			
Above/Below (mm)	300			
Scour Protection		7	7	
(Type : <b>NATURAL</b> )				
(Avg. Rock Size(mm) : <b>250</b> )				
Scour/Erosion		7	7	
Beavers (Y/N)	No			
<b>Upstream End General Rating</b>		<b>7</b>	<b>7</b>	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 2317, Rise (mm): 2561, Type: SPE)				
Barrel Last Accessible Date	12-Sep-2012			
<b>Special Features</b>				
Special Feature		6	4	Removed at U/S East bevel.
(Type : <b>BEAVR CTRL DEV</b> )				
Special Feature				
(Type : )				
Roof		5	5	
Measured Rise (mm)	2495			
Measured At Ring No.	7			
Sag (mm)	66			
Percent Sag	2			
Sidewall		3	3	Rated 3 due to cracked seam.
Measured Span (mm)	2430			
Measured At Ring No.	7			
Deflection (mm)	113			
Percent Deflection	4			
Floor		N	N	Water up to 400mm.
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		5	5	Roof bolt pulling through 2nd seam @ u/s end.
Separation (mm)	0			
Longitudinal Seams		3	3	3,4,5,6,7,8 & 9 from U/S end cracked on North side - 58 mm steel @ ring #7 Ends of all cracks marked in R7 for future monitoring
Total No. of Cracked Rings	7			
Total No. of Rings with Two Cracked Seams	0			Bolts pulling through.
Min. Remaining Steel Between Cracks (mm)	58			In stagger.
Proper Lap (Y/N)	No			
Longitudinal Stagger (Y/N)	Yes			
Coating		5	6	Superficial corrosion @ lower sidewalls.
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 2317, Rise (mm): 2561, Type: SPE)				
Fish Passage Adequacy		7	7	
Baffle		X	X	
(Type : )				
Waterway Adequacy		7	7	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
<b>Barrel General Rating</b>		<b>3</b>	<b>3</b>	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		W		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	
Bevel End		7	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	ABOVE			
Above/Below (mm)	200			
Scour Protection		5	4	Displaced rip rap and fill at SW.
(Type : <b>NATURAL</b> )				
(Avg. Rock Size(mm) : <b>250</b> )				
Scour/Erosion		5	4	Minor scour at SW bevel scope.
Beavers (Y/N)	No			
<b>Downstream End General Rating</b>		<b>5</b>	<b>4</b>	
Structure Usage				
		Last	Now	Explanation of Condition
<b>Channel (U/S and D/S)</b>				
Alignment		7	7	Curves to the North on the d/s end.
Bank Stability		7	7	Shallow banks.
HWM (m below Top of Culvert)	0.2			No visible HWM.
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading	DEGRADING			
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : <b>NONE</b> )				
(Fish Compensation Measure 2 : <b>NONE</b> )				
<b>Channel General Rating</b>		<b>7</b>	<b>7</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING	2012	2200 diameter lining.					
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>33.3/33.3</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>54.9/53.8</b>	Est. Repl. Yr	2020	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Garry Roberts		Previous Assistant's Name				
Next Inspection Date	12-Jun-2014		Previous Inspection Date	07-Jan-2011			
Inspection Cycle (Default) (months)	21						
Comment							