

Bridge Culvert Inspection				
Bridge File Number	78878 -1 Bridge Culvert		Form Type	CULM
Year Built	1977		Lot No.	2
Bridge or Town Name	Millarville		Inspector Name	Calvin Roberts
Located Over	TRAIL-ANIMAL, OVER SP		Inspector Class	BR CLS B
Located On	549:02 C1 8.513		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	30-Jan-2013
Legal Land Location	NW SEC 1 TWP 21 RGE 4 W5M		Data Entry By	Lauren Korte
Longitude, Latitude	-114:25:59, 50:45:21		Data Entry Date	01-Mar-2013
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Garry Roberts
Contract Main. Area	CMA27		Review Date	03-Feb-2013
Clear Roadway/Skew	9 / 0 deg.		Dept. Reviewer Name	Tim Davies
AADT/Year	1,510 / 2011 (A)		Dept. Review Date	04-Mar-2013
Road Classification	RCU-209-110		Follow-Up By	
Detour Length (km)	1			

Bridge Culvert Information								
Number of Culverts	2							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	2134	MP	22	68X13	3.5	ROUND
2	MAIN	-	914	MP	88.4	68X13	1.6	ROUND
Special Features								
Special Features Comment								

Posting Information										
Required Vert. Clearance Posting (m)										
Posted Vertical Clearance (Y/N)			No							
Posted:	Lane	NB	On Bridge (m)		In Advance (Y/N)		Lane	SB	On Bridge (m)	In Advance (Y/N)
Remarks	Not Required.									

Utilities (Located at)				
Utility Attachments				
Telephone	South ditch.		Gas	
Power			Municipal	
Others			Problem (Y/N)	No
Remarks				

Approach Road / Embankment				
		Last	Now	Explanation of Condition
Horizontal Alignment		7	7	
Vertical Alignment		7	7	
Roadway Width (m)	9.000			
Embankment		4	4	Sloughin @ D/S @ Secondary but 25m from road. 3.5m cover over secondary.
Sideslope (___:1)	3.0			
(Height of Cover(m) : 0.8)				
Guardrail (Y/N)	Yes			
Approach Road / Embankment General Rating		7	7	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Span Type: Primary Span)				
Direction				South.
End Treatment (Concrete, Steel, Others, None)	NONE			

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Span Type: Primary Span)				
Headwall		X	X	
Collar		X	X	
Wingwalls (Shape :)		X	X	
Cutoff Wall		X	X	
Bevel End		X	X	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	200			
Scour Protection (Type : NATURAL) (Avg. Rock Size(mm) :)		7	N	Snow covered.
Scour/Erosion		7	N	
Beavers (Y/N)	No			
Upstream End General Rating		7	N	P.R 7.
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2134, Type: MP)				
Barrel Last Accessible Date	30-Jan-2013			
Special Features				
Special Feature (Type :)				
Special Feature (Type :)				
Roof		7	7	Estimate.
Measured Rise (mm)	2180			
Measured At Ring No.	1			
Sag (mm)	47			
Percent Sag	2			
Sidewall		6	7	Inward.
Measured Span (mm)	2080			
Measured At Ring No.	1			
Deflection (mm)	54			
Percent Deflection	3			
Floor		N	N	150mm gravel on floor.
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		5	5	255mm @ haunch, 120mm @ roof. Misaligned @ install at R2.
Separation (mm)	255			

Bridge Culvert Barrel					
Culvert Component		Last	Now	Explanation of Condition	
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2134, Type: MP)					
Longitudinal Seams		X	X		
Total No. of Cracked Rings	0				
Total No. of Rings with Two Cracked Seams	0				
Min. Remaining Steel Between Cracks (mm)	0				
Proper Lap (Y/N)					
Longitudinal Stagger (Y/N)					
Coating		4	4	Isolated Scaling and Pitting @ Haunches.	
Corrosion By Soil (Y/N)	No				
Corrosion By Water (Y/N)	Yes				
Camber POS/ZERO/NEG	ZERO				
Ponding (Y/N)	No				
Fish Passage Adequacy		X	X		
Baffle		X	X		
(Type :)					
Waterway Adequacy		7	X		
Icing (Y/N)	No				
Silting (Y/N)	No				
Drift (Y/N)	No				
Barrel General Rating		6	7		
Downstream End					
Culvert Component		Last	Now	Explanation of Condition	
(Pipe # : 1, Span Type: Primary Span)					
Direction				North.	
End Treatment (Concrete, Steel, Others, None)	NONE				
Headwall		X	X		
Collar		X	X		
Wingwalls		X	X		
(Shape :)					
Cutoff Wall		X	X		
Bevel End		X	X		
Heaving (mm)	0				
Invert Above/Below Stream Bed	ABOVE				
Above/Below (mm)	100				
Scour Protection		7	N	Snow covered.	
(Type : NATURAL)					
(Avg. Rock Size(mm) :)					
Scour/Erosion		7	N		
Beavers (Y/N)	No				
Downstream End General Rating		7	N	P.R 7.	

Upstream End					
Culvert Component		Last	Now	Explanation of Condition	
(Pipe # : 2, Span Type: Secondary Span)					
Direction				South. Located 10m west of primary.	
End Treatment (Concrete, Steel, Others, None)		NONE			
Headwall		X	X		
Collar		X	X		
Wingwalls (Shape :)		X	X		
Cutoff Wall		X	X		
Bevel End		X	X		
Heaving (mm)					
Invert Above/Below Stream Bed		BELOW			
Above/Below (mm)		400			
Scour Protection (Type : NATURAL) (Avg. Rock Size(mm) :)		5	N	(Small scourhole) (260mm DP). October 11, 2009. Snow Covered.	
Scour/Erosion		5	N		
Beavers (Y/N)		No			
Upstream End General Rating		5	N	P.R 5.	
Bridge Culvert Barrel					
Culvert Component		Last	Now	Explanation of Condition	
(Pipe # : 2, Secondary Span, Location Code: MAIN, Span (mm): , Rise (mm): 914, Type: MP)					
Barrel Last Accessible Date		19-Sep-2006		Pipe too small to enter.	
Special Features					
Special Feature (Type :)				Runs @ 45 Deg under primary. Viewed from Ends.	
Special Feature (Type :)					
Roof		2	N	(Entered d/s 5m to roof sag measured @ ring #3 from North Local roof sag 1m long @ 5m from D/S) Sept 19/06 Remaining 95% of pipe appears good. Likely from construction.	
Measured Rise (mm)		750			
Measured At Ring No.		2			
Sag (mm)		164			
Percent Sag		17			
Sidewall		N	N		
Measured Span (mm)		970			
Measured At Ring No.		2			
Deflection (mm)		56			
Percent Deflection		6			
Floor		N	N	Corrosion with pitting @ floor.	
Bulge (mm)					
Measured At Ring No.					
Abrasion (Y/N)		No			
Circumferential Seams		N	N		
Separation (mm)					

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Secondary Span, Location Code: MAIN, Span (mm): , Rise (mm): 914, Type: MP)				
Longitudinal Seams		X	X	
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams	0			
Min. Remaining Steel Between Cracks (mm)	0			
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		4	4	Corrosion at floor with light pitting.
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	No			
Fish Passage Adequacy		X	5	
Baffle		X	X	
(Type :)				
Waterway Adequacy		3	3	Under sized for flow that caused D/S scour.
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		2	2	Carried forward.
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Span Type: Secondary Span)				
Direction				North.
End Treatment (Concrete, Steel, Others, None)	NONE			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		X	X	
Heaving (mm)				
Invert Above/Below Stream Bed	ABOVE			2m of pipe hanging unsupported over scour hole.
Above/Below (mm)	200			
Scour Protection		3	3	25m x 6m x 2m Deep severe scour @ d/s end.
(Type : NATURAL)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		3	3	
Beavers (Y/N)	No			
Downstream End General Rating		3	3	

Structure Usage				
		Last	Now	Explanation of Condition
Grade Separation				
Road Alignment		X	X	No visible HWM at secondary.
Roadway Surface		5	5	
(Type :)				
Icing (Y/N)	Yes			Approximately 150mm ice in pipe.
Traffic Safety Features		X	X	
Type				
Lighting		X	X	
Barrel Leakage (Y/N)	No			
Drainage		5	5	
Structure In Use (Y/N)	No			
Grade Separation General Rating		5	5	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP	2013	20m³ Class 2 @ d/s secondary and 30m³ pit run.					
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION	2013	Replace damaged 2nd from D/S section of 914mm secondary					
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	22.2/22.2	Sufficiency Rating (Last/Now) (%)	31.8/31.8	Est. Repl. Yr	2025	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Garry Roberts		Previous Assistant's Name				
Next Inspection Date	30-Apr-2016		Previous Inspection Date	01-Oct-2009			
Inspection Cycle (Default) (months)	39						
Comment							