

Bridge Culvert Inspection				
Bridge File Number	78994 -1 Bridge Culvert		Form Type	CUL1
Year Built	1981		Lot No.	1
Bridge or Town Name	BUCK LAKE		Inspector Name	Owen Salava
Located Over	TRAIL-ANIMAL, OVER SP		Inspector Class	BR CLS A
Located On	22:28 C1 10.570		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	25-Jun-2012
Legal Land Location	SE SEC 6 TWP 47 RGE 6 W5M		Data Entry By	Marcia Chavez
Longitude, Latitude	-114:51:34, 53:01:29		Data Entry Date	15-Jul-2012
Road Authority	Alberta Transportation (AIT)		Reviewer Name	John O'Brien
Contract Main. Area	CMA17		Review Date	05-Jul-2012
Clear Roadway/Skew	11.3 /		Dept. Reviewer Name	Andrew Smikles
AADT/Year	2,380 / 2011 (A)		Dept. Review Date	19-Jul-2012
Road Classification	RAU-211.8-110		Follow-Up By	
Detour Length (km)	35			

Bridge Culvert Information								
Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	PI./Slab Thickness	Shape
1	MAIN	-	2120	MP	26.8	68X13	2.8	ROUND
Special Features								
Special Features Comment								

Posting Information									
Required Vert. Clearance Posting (m)									
Posted Vertical Clearance (Y/N)									
Posted:	Lane	EB	On Bridge (m)	In Advance (Y/N)	Lane	WB	On Bridge (m)	In Advance (Y/N)	
Remarks									

Utilities (Located at)			
Utility Attachments			
Telephone	Plowed in W r/w.		Gas
Power	3 wire o/h, E r/w.		Municipal
Others			Problem (Y/N) No
Remarks			

Approach Road / Embankment				
		Last	Now	Explanation of Condition
Horizontal Alignment		8	8	Curve to the North.
Vertical Alignment		8	8	
Roadway Width (m)	11.300			
Embankment		8	8	Measurement on W side, 4:1 on East side.
Sideslope (__:1)	3.0			
(Height of Cover(m) : 1.3)				
Guardrail (Y/N)	Yes			Minor collision damage.
Approach Road / Embankment General Rating		8	8	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		W		
End Treatment (Concrete, Steel, Others, None)	NONE			
Headwall		X	X	
Collar		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Wingwalls (Shape :)		X	X	
Cutoff Wall		X	X	
Bevel End		X	X	
Heaving (mm)	0			
Invert Above/Below Stream Bed	ABOVE			
Above/Below (mm)	250			
Scour Protection (Type : NONE) (Avg. Rock Size(mm) :)		N	4	Culvert takes flow from W pipe 250mm above ground causing ponding - minor.
Scour/Erosion		N	4	Minor erosion at culvert invert area.
Beavers (Y/N)	No			
Upstream End General Rating		4	4	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2120, Type: MP)				
Barrel Last Accessible Date	26-Jun-2012			
Special Features				
Special Feature (Type :)				
Special Feature (Type :)				
Roof		3	3	Minor damage from grass cutter at W end of pipe. Deformation at R2/3 coupler. 1st joint from E deformed, stable. R3 1840 to dirt, approx. 150mm of dirt on floor. R2 1950 steel to steel (170mm, 8%).
Measured Rise (mm)	1863			
Measured At Ring No.	3			
Sag (mm)	257			
Percent Sag	12			
Sidewall		3	3	10.8%
Measured Span (mm)	2350			
Measured At Ring No.	2			
Deflection (mm)	230			
Percent Deflection	11			
Floor		N	N	Dirt covered.
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		4	5	40mm vert @ circ. 1 & circ 3. No infiltration.
Separation (mm)	120			
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		7	7	
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2120, Type: MP)				
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			
Fish Passage Adequacy		X	X	
Baffle		X	X	
(Type :)				
Waterway Adequacy		X	X	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		3	3	

Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		E		Gate across end.
End Treatment (Concrete, Steel, Others, None)	NONE			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		X	X	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	80			
Scour Protection		N	7	
(Type : NATURAL)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		N	7	
Beavers (Y/N)	No			
Downstream End General Rating		7	7	

Structure Usage				
		Last	Now	Explanation of Condition
Grade Separation				
Road Alignment		6	6	Approach @ W. 250mm low causing ponding.
Roadway Surface		5	5	
(Type : GRAVEL)				
Icing (Y/N)	No			
Traffic Safety Features		X	X	
Type	NONE			
Lighting		X	X	
Barrel Leakage (Y/N)	No			

Structure Usage				
		Last	Now	Explanation of Condition
Drainage		N	4	Ponding @ W. side.
Structure In Use (Y/N)	Yes			
Grade Separation General Rating		4	4	

Maintenance Recommendations										
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #				
SHOTCRETE REPAIRS										
PLACE ADDITIONAL RIP RAP										
REMOVE DRIFT ACCUMULATION										
INSTALL CONCRETE/STEEL LINING										
INSTALL STRUTS										
INSTALL CONCRETE COLLAR/CUTOFF										
REPAIR SEAMS										
OTHER ACTION	2012	Place 5m(cubed) fill @ W. end approach.		2020						
OTHER ACTION										
OTHER ACTION										
OTHER ACTION										
Structural Condition Rating (Last/Now) (%)	33.3/33.3	Sufficiency Rating (Last/Now) (%)	53.8/53.6	Est. Repl. Yr	2020	Maint. Req. (Y/N)	Yes			
Special Comments for Next Inspection	No action for I=3, roof & sidewall ratings.									
Maintenance Reviewed By	2006.09.05 Cattlepass being used. There is some damage/wear that should be investigated. Arrange for inspection by Bridge Branch.									
Proposed Long-Term Strategy	2006.09.05 Cattlepass being used. There is some damage/wear that should be investigated. Arrange for inspection by Bridge Branch.									
On 3-Year Program (Y/N)										
Proposed Action										
Previous Inspector's Name	Owen Salava	Previous Assistant's Name								
Next Inspection Date	25-Mar-2014	Previous Inspection Date		02-Feb-2011						
Inspection Cycle (Default) (months)	21									
Comment										

Maintenance Recommendations

Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #
SHOTCRETE REPAIRS						
PLACE ADDITIONAL RIP RAP						
REMOVE DRIFT ACCUMULATION						
INSTALL CONCRETE/STEEL LINING						
INSTALL STRUTS						
INSTALL CONCRETE COLLAR/CUTOFF						
REPAIR SEAMS						
OTHER ACTION	2012	Place 5m(cubed) fill @ W. end approach.	To operations			
OTHER ACTION						
OTHER ACTION						
OTHER ACTION						
Structural Condition Rating (Last/Now) (%)	33.3/33.3	Sufficiency Rating (Last/Now) (%)	53.8/53.6	Est. Repl. Yr	2020	Maint. Req. (Y/N) Yes
Special Comments for Next Inspection	No action for r=3, roof & sidewall ratings.		Department Comments	Roof sag is static. Monitor on 21 month cycle. Tentatively programmed to be replaced in 2022. AS		
Maintenance Reviewed By	Andrew Smikles		Date	23-Aug-2012	Estimated Total	0
Proposed Long-Term Strategy	2006.09.05 Cattlepass being used. There is some damage/wear that should be investigated. Arrange for inspection by Bridge Branch.					
On 3-Year Program (Y/N)						
Proposed Action						
Previous Inspector's Name	Owen Salava		Previous Assistant's Name			
Next Inspection Date	25-Mar-2014		Previous Inspection Date	02-Feb-2011		
Inspection Cycle (Default) (months)	21					
Comment						