

Bridge Culvert Inspection			
Bridge File Number	08017 -1 Bridge Culvert	Form Type	CUL1
Year Built	1963	Lot No.	1
Bridge or Town Name	CLUNY	Inspector Name	Jason Rusu
Located Over	TRIBUTARY TO CROWFOOT CREEK, 2.13.14.5, WATERCRS-ST	Inspector Class	BR CLS A
Located On	842:08 C1 9.505	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	16-Feb-2012
Legal Land Location	NW SEC 10 TWP 23 RGE 21 W4M	Data Entry By	Alyssa Boynton
Longitude, Latitude	-112:51:54, 50:56:56	Data Entry Date	16-Mar-2012
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Garry Roberts
Contract Main. Area	CMA30	Review Date	24-Feb-2012
Clear Roadway/Skew	7.7 /	Dept. Reviewer Name	Tim Davies
AADT/Year	140 / 2010 (A)	Dept. Review Date	22-Mar-2012
Road Classification	RLU-207G-60	Follow-Up By	
Detour Length (km)	2		

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	1737	1920	SPE	25	152X51	2.8	ELLIPSE
Special Features								
Special Features Comment								

Utilities (Located at)

Utility Attachments							
Telephone	20m West	Gas	x-ing 100m North				
Power	X-ing 250m N.	Municipal					
Others		Problem (Y/N)	No				
Remarks							

Approach Road / Embankment

		Last	Now	Explanation of Condition
Horizontal Alignment		4	4	POSTED FOR 70 KM/H ON HORIZ CURVE Hills N and S
Vertical Alignment		5	5	
Roadway Width (m)	8.000			
Embankment		N	6	
Sideslope (:1)	1.5			
(Height of Cover(m) : 3.1)				
Guardrail (Y/N)	Yes			West side only
Approach Road / Embankment General Rating		4	4	

Upstream End

Culvert Component		Last	Now	Explanation of Condition
Direction				West
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Cutoff Wall		X	X	
Bevel End		4	4	(End bent 100mm) ice at floor. (Perf in floor 50mm, 70mm) 20-Mar-2007 (Water piping through bevel end - photo 3) 20-Mar-2007
Heaving (mm)	100			2 nuts and 2 bolts missing at 1st circ seam
Invert Above/Below Stream Bed	BELOW			(No evidence of piping from U/S through to D/S end) Feb 8 2010.
Above/Below (mm)	200			
Scour Protection		N	5	
(Type : NATURAL)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		N	5	
Beavers (Y/N)	No			
Upstream End General Rating		4	4	G.R. carried over.
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 1737, Rise (mm): 1920, Type: SPE)				
Barrel Last Accessible Date	16-Feb-2012			
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		3	3	RI Roof perfs - photo - isolated unable to measure. 400mm ice on floor R6 @ 11 o'clock longit seam bulging 100mm
Measured Rise (mm)	1830			
Measured At Ring No.	4			Est.
Sag (mm)	90			
Percent Sag	5			
Sidewall		3	3	R1 perfs in S. wall - photo- isolated
Measured Span (mm)	1880			
Measured At Ring No.	4			
Deflection (mm)	143			
Percent Deflection	8			
Floor		N	N	(ALKALI STAINS IN FLOOR) & (BOLT HOLES 2 NUTS MISSING ON 8TH RING) 21-Feb-2002
Bulge (mm)	0			ice
Measured At Ring No.				
Abrasion (Y/N)	Yes			
Circumferential Seams		4	4	3 NUTS MISSING, MANY LOOSE ON 3RD RING & 5th ring 105mm long crack at circ. seam R4
Separation (mm)	0			
Longitudinal Seams		4	4	5th & 7th ring has loose bolts also @ long seams & 4 missing
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams	0			
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	No			
Longitudinal Stagger (Y/N)	Yes			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 1737, Rise (mm): 1920, Type: SPE)				
Coating		3	3	Ring 1 small perfs s. swell - & roof - photo Deep pitting and scalling in haunches. Staining through numerous bolt holes.
Corrosion By Soil (Y/N)	Yes			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			
Fish Passage Adequacy		5	5	
Baffle		X	X	
(Type :)				
Waterway Adequacy		5	5	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		3	3	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction				East
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		6	6	
Heaving (mm)	150			
Invert Above/Below Stream Bed	ABOVE			
Above/Below (mm)	300			
Scour Protection		N	6	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 500)				
Scour/Erosion		N	6	
Beavers (Y/N)	No			
Downstream End General Rating		6	6	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		6	6	Meanders @ u/s & d/s
Bank Stability		N	5	
HWM (m below Top of Culvert)				No visible HWM
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading				DEGRADING
Beavers (Y/N)	No			

Structure Usage				
		Last	Now	Explanation of Condition
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		6	6	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	33.3/33.3	Sufficiency Rating (Last/Now) (%)	37.8/37.8	Est. Repl. Yr	2020	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Tom Carey		Previous Assistant's Name				
Next Inspection Date	16-May-2015		Previous Inspection Date	08-Feb-2010			
Inspection Cycle (Default) (months)	39						
Comment							