

Bridge Culvert Inspection			
Bridge File Number	81223 -1 Bridge Culvert	Form Type	CUL1
Year Built	1988	Lot No.	4
Bridge or Town Name	CALLING LAKE	Inspector Name	Wade Nanninga
Located Over	3RD ORDER TRIBUTARY TO CALLING RIVER, 8.11.53.8.3.4, WATERCRS-ST	Inspector Class	BR CLS B
Located On	813:08 C1 3.630	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	06-Jan-2011
Legal Land Location	SE SEC 14 TWP 76 RGE 23 W4M	Data Entry By	Theresa Lacusta
Longitude, Latitude	-113:27:11, 55:34:45	Data Entry Date	04-Feb-2011
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Arnold Assenheimer
Contract Main. Area	CMA06	Review Date	12-Jan-2011
Clear Roadway/Skew	12 / -24 deg. (LHF)	Dept. Reviewer Name	Brent Herrick
AADT/Year	520 / 2009 (A)	Dept. Review Date	08-Feb-2011
Road Classification	RCU-210-110	Follow-Up By	
Detour Length (km)	250		

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	2200	MP	37	125X26	2.8	ROUND
Special Features								
Special Features Comment								

Utilities (Located at)

Utility Attachments			
Telephone		Gas	
Power		Municipal	
Others		Problem (Y/N)	No
Remarks	BF tag installed on top of West bevel.		

Approach Road / Embankment

	Last	Now	Explanation of Condition
Horizontal Alignment	7	7	On a curve.
Vertical Alignment	7	7	
Roadway Width (m)	11.000		
Embankment	7	7	
Sideslope (__:1)	3.0		
(Height of Cover(m) : 2.5)			
Guardrail (Y/N)	No		
Approach Road / Embankment General Rating	7	7	

Upstream End

Culvert Component	Last	Now	Explanation of Condition
Direction	W		
End Treatment (Concrete, Steel, Others, None)	STEEL		
Headwall	X	X	
Collar	X	X	
Wingwalls	X	X	
(Shape :)			
Cutoff Wall	X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		7	N	Ice 200mm from crown.
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			Drift piled to crown.
Above/Below (mm)	600			
Scour Protection		7	N	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		7	N	
Beavers (Y/N)	No			
Upstream End General Rating		7	7	GR carried forward.
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2200, Type: MP)				
Barrel Last Accessible Date	10-Nov-1999			Inlet blocked by drift. 0.2 ice from crown at outlet. Pipe viewed from D/S end looks o.k.
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		N	N	
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)				
Percent Sag				
Sidewall		N	N	(Span 2164. 1999/11/10)
Measured Span (mm)				(1.6%. 1999/11/10)
Measured At Ring No.				
Deflection (mm)	36			
Percent Deflection				
Floor		N	N	
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams		N	N	
Separation (mm)	50			
Longitudinal Seams		N	N	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		N	N	
Corrosion By Soil (Y/N)				
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	ZERO			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2200, Type: MP)				
Ponding (Y/N)	Yes			
Fish Passage Adequacy		X	7	
Baffle		N	N	
(Type :)				
Waterway Adequacy		6	6	(0.4 from crown. 2001/03/22)
Icing (Y/N)	Yes			Approx. 0.5 - 1.0 deep deposits.-08-Aug-2007
Silting (Y/N)	Yes			
Drift (Y/N)	No			
Barrel General Rating		N	N	(G.R. was 6 from 10/Nov/1999)
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		E		0.2m from crown to ice level.
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		7	N	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	600			
Scour Protection		7	N	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 250)				
Scour/Erosion		7	N	
Beavers (Y/N)	No			
Downstream End General Rating		7	7	GR carried fwd.
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		7	7	
Bank Stability		7	7	
HWM (m below Top of Culvert)	0.1			Drift up to crown.
Drift (Y/N)	Yes			
Channel Bottom Degrading/Aggrading	AGGRADING			
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		7	7	

Structure Usage				
		Last	Now	Explanation of Condition

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	55.6/55.6	Sufficiency Rating (Last/Now) (%)	61.0/60.6	Est. Repl. Yr	2029	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection	\pipe ok from ends.-no level II recommendation at this time.		Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Dave Lam		Previous Assistant's Name				
Next Inspection Date	06-Apr-2014		Previous Inspection Date	08-Aug-2007			
Inspection Cycle (Default) (months)	39						
Comment							