

Bridge Culvert Inspection			
Bridge File Number	81517 -1 Bridge Culvert	Form Type	CUL1
Year Built	1989	Lot No.	4
Bridge or Town Name	IMPERIAL MIL	Inspector Name	Wade Nanninga
Located Over	TRIBUTARY TO PICHE RIVER, 8.11.55.9.6.2.2, WATERCRS-ST	Inspector Class	BR CLS B
Located On	881:20 C1 26.432	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	16-Sep-2010
Legal Land Location	NW SEC 10 TWP 70 RGE 11 W4M	Data Entry By	Theresa Lacusta
Longitude, Latitude	-111:36:25, 55:02:47	Data Entry Date	05-Oct-2010
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Arnold Assenheimer
Contract Main. Area	CMA08	Review Date	20-Sep-2010
Clear Roadway/Skew	11.2 / -45 deg. (LHF)	Dept. Reviewer Name	Brent Herrick
AADT/Year	1,290 / 2009 (A)	Dept. Review Date	05-Oct-2010
Road Classification	RCU-209-110	Follow-Up By	
Detour Length (km)	250		

Bridge Culvert Information								
Number of Culverts		1						
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	1810	SP	115.8	152X51	3.0	ROUND
Special Features								
Special Features Comment								

Utilities (Located at)			
Utility Attachments			
Telephone		Gas	
Power		Municipal	
Others	Fibre optic East r/w.	Problem (Y/N)	No
Remarks	File tag installed on top of West end roof.		

Approach Road / Embankment				
		Last	Now	Explanation of Condition
Horizontal Alignment		6	6	Roadway curves across pipe. In slight sag. No passing SB.
Vertical Alignment		6	6	
Roadway Width (m)	9.800			
Embankment		8	8	
Sideslope (__:1)	3.0			
(Height of Cover(m) : 10)				
Guardrail (Y/N)	Yes			
Approach Road / Embankment General Rating		6	6	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		W		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Wingwalls (Shape :)		X	X	
Cutoff Wall		X	X	
Bevel End		7	6	
Heaving (mm)	300			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	0			
Scour Protection (Type : RIP RAP) (Avg. Rock Size(mm) : 200)		5	5	
Scour/Erosion		5	5	
Beavers (Y/N)	No			
Upstream End General Rating		7	5	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1810, Type: SP)				
Barrel Last Accessible Date	09-Sep-2010			
Special Features				
Special Feature (Type :)				
Special Feature (Type :)				
Roof		6	5	
Measured Rise (mm)	1710			
Measured At Ring No.				
Sag (mm)	100			
Percent Sag	6			
Sidewall		5	3	Perforation in lower sidewall 20m from d/s end. (North side)
Measured Span (mm)	1910			
Measured At Ring No.				
Deflection (mm)	100			
Percent Deflection	6			
Floor		6	6	Minor.
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	Yes			
Circumferential Seams		7	7	
Separation (mm)	0			
Longitudinal Seams		6	6	No signs of buckling, bottom row of longitudinal seams. Bolts on bottom seam rusting & leaking.
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	Yes			
Longitudinal Stagger (Y/N)	No			
Coating		5	3	Some corrosion on sidewalls. Perforation in lower sidewall.
Corrosion By Soil (Y/N)	Yes			
Corrosion By Water (Y/N)	Yes			

Bridge Culvert Barrel					
Culvert Component		Last	Now	Explanation of Condition	
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1810, Type: SP)					
Camber POS/ZERO/NEG	NEG				
Ponding (Y/N)	No				
Fish Passage Adequacy		6	6		
Baffle		X	X		
(Type :)					
Waterway Adequacy		7	7	(11/Oct/2000)	
Icing (Y/N)	Yes			200mm silt in last 1/3 of pipe.	
Silting (Y/N)	Yes				
Drift (Y/N)	No				
Barrel General Rating		5	3		
Downstream End					
Culvert Component		Last	Now	Explanation of Condition	
Direction		E			
End Treatment (Concrete, Steel, Others, None)	STEEL				
Headwall		X	X		
Collar		X	X		
Wingwalls		X	X		
(Shape :)					
Cutoff Wall		X	X		
Bevel End		7	7		
Heaving (mm)	0				
Invert Above/Below Stream Bed	BELOW				
Above/Below (mm)	300				
Scour Protection		5	4	Scour hole at outlet 4mWx1mDx3mL	
(Type : RIP RAP)					
(Avg. Rock Size(mm) : 200)					
Scour/Erosion		5	4		
Beavers (Y/N)	No				
Downstream End General Rating		7	4		
Structure Usage					
		Last	Now	Explanation of Condition	
Channel (U/S and D/S)					
Alignment		7	7		
Bank Stability		7	7		
HWM (m below Top of Culvert)				HWM not visible. Willows in channel.	
Drift (Y/N)	Yes				
Channel Bottom Degrading/Aggrading	DEGRADING				
Beavers (Y/N)	No				
(Fish Compensation Measure 1 : NONE)					
(Fish Compensation Measure 2 : NONE)					

Structure Usage				
		Last	Now	Explanation of Condition
Channel General Rating		7	7	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	55.6/33.3	Sufficiency Rating (Last/Now) (%)	63.7/47.3	Est. Repl. Yr	2029	Maint. Req. (Y/N)	No
Special Comments for Next Inspection	Monitor deflections and perforations.		Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Dave Lam		Previous Assistant's Name				
Next Inspection Date	16-Dec-2013		Previous Inspection Date	13-Jun-2007			
Inspection Cycle (Default) (months)	39						
Comment							