

Bridge Culvert Inspection			
Bridge File Number	81586 -1 Bridge Culvert	Form Type	CUL1
Year Built	1989	Lot No.	2
Bridge or Town Name	WATERCOURSE CULVERT ON HIGHWAY 2, 6 KM W OF PEACE RIVER	Inspector Name	Brian Pientsch
Located Over	STRONG CREEK, 8.10.59, WATERCRS-ST	Inspector Class	BR CLS A
Located On	2:62 C1 9.959	Assistant Name	Clem Guenette
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	06-Dec-2011
Legal Land Location	NE SEC 30 TWP 83 RGE 22 W5M	Data Entry By	Theresa Lacusta
Longitude, Latitude	-117:27:27, 56:13:59	Data Entry Date	04-Feb-2012
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Eric Carcoux
Contract Main. Area	CMA04	Review Date	29-Jan-2012
Clear Roadway/Skew	13 /	Dept. Reviewer Name	David Morrison
AADT/Year	4,440 / 2011 (A)	Dept. Review Date	05-Apr-2012
Road Classification	RAU-211.8-110	Follow-Up By	
Detour Length (km)	3		

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	1200	SSP	83.28		3.0	ROUND
Special Features								
Special Features Comment								

Utilities (Located at)

Utility Attachments			
Telephone		Gas	
Power	3 wire O/H - 20m North.	Municipal	
Others		Problem (Y/N)	No
Remarks			

Approach Road / Embankment

	Last	Now	Explanation of Condition
Horizontal Alignment		7	Approach 30m West and 250m East.
Vertical Alignment		7	
Roadway Width (m)	12.200		
Embankment		5	
Sideslope (__:1)	3.0		
(Height of Cover(m) :)			
Guardrail (Y/N)	Yes		
Approach Road / Embankment General Rating		7	

Upstream End

Culvert Component	Last	Now	Explanation of Condition
Direction	N		
End Treatment (Concrete, Steel, Others, None)	NONE		
Headwall		X	
Collar		X	
Wingwalls		X	
(Shape :)			
Cutoff Wall		X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End			X	
Heaving (mm)				
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	50			
Scour Protection			4	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 200)				
Scour/Erosion			4	4mx3mx0.8m scour on East side. 2mx2mx1m scour on West side.
Beavers (Y/N)	No			
Upstream End General Rating			4	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1 , Primary Span, Location Code: MAIN , Span (mm): , Rise (mm): 1200 , Type: SSP)				
Barrel Last Accessible Date				900mm clearance in pipe, has gravel, silt and ice on floor.
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof			N	
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)				
Percent Sag				
Sidewall			N	
Measured Span (mm)				
Measured At Ring No.				
Deflection (mm)				
Percent Deflection				
Floor			N	
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams			N	
Separation (mm)				
Longitudinal Seams			N	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating			N	
Corrosion By Soil (Y/N)				
Corrosion By Water (Y/N)				
Camber POS/ZERO/NEG				
Ponding (Y/N)	Yes			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1200, Type: SSP)				
Fish Passage Adequacy			5	
Baffle			N	
(Type :)				
Waterway Adequacy			5	
Icing (Y/N)	Yes			
Silting (Y/N)	Yes			
Drift (Y/N)	No			
Barrel General Rating			N	No other inspections on system.
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		S		
End Treatment (Concrete, Steel, Others, None)	NONE			
Headwall			X	
Collar			X	
Wingwalls			X	
(Shape :)				
Cutoff Wall			X	
Bevel End			X	
Heaving (mm)				
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	700			
Scour Protection			7	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion			7	
Beavers (Y/N)	No			
Downstream End General Rating			7	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment			7	
Bank Stability			7	
HWM (m below Top of Culvert)				HWM not visible
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading	DEGRADING			Dam 30m downstream
Beavers (Y/N)	Yes			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating			7	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP	2012	Repair scour at u/s end caused by poly pipe.					
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	/55.6	Sufficiency Rating (Last/Now) (%)	/53.5	Est. Repl. Yr	2025	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name			Previous Assistant's Name				
Next Inspection Date	06-Sep-2013		Previous Inspection Date				
Inspection Cycle (Default) (months)	21						
Comment							