Bridge Inspection																
Bridge File Number 81702 -1 Bridge									Form Type			TH				
Year Built/Year 1993/1993 Supstr									Lot No.			2				
Bridge or Town Name CALGARY					ľ				Inspector Name			Garry Roberts				
Located Over BOW RIVER, 2.13, 1					WATERCRS-ST				Inspector Class			BR CLS A				
									Assistant Name							
,								Ass	Assistant Class							
Water Body Cl./Year								Ins	Inspection Date			01-Oct-2010				
Navigabil. Cl./Year					00 14/41	4		Dat	Data Entry By			Erin Roberts				
				22 RGE 29 W4M					Data Entry Date			22-Oct-2010				
Longitude, Latitude -114:00:03,					<del>_</del> `			Re	Reviewer Name			Tom Carey				
Road Authority			Fransport		1)		Re	Review Date			06-Oct-2010					
Contract Main. A			NED CM	Α				De	pt. Revie	ewer	Name	Lorenz Bohn	ert			
Clear Roadway/S	Skew	3.5 /						De	pt. Revie	ew Da	ate	27-Oct-2010				
AADT/Year								Fol	low-Up I	Ву						
Road Classificat								_								
Detour Length (k																
Allowable Load (	t): Sin	igle			Semi					Train	)			> On Critic	cal Spai	าร
Design Loading:																
Design Loading:						Po	osting	Infor	nation					> Primary	opan	
Required Vert. C	learan	nce Postir	ng (m)													
Posted Vertical (	Cleara	nce (Y/N)		No						_						
Posted: Lane	WB	On B	ridge (m)					No	No Lane EB O			On Bridge (m) In Advance (Y/N) No			No	
Remarks																
Required Load F	osting	(t)		Single					Semi			Truck Train				
				Single					Semi			Truck Train				
Posted:	Lane	WB		At Junction (Y/N)			No		In Advance (Y/N)		No	At Bridge (Y/N)		No		
Posted:	Lane	EB		At Junction (Y/N)		No			n Advance (Y/N)		No	At Bridge (Y/N)		No		
Remarks Not Required				At Juliction (1714)			110		minave	idvarioc (1714)			/ (C D)	iago (1/11)	110	
Hazard Marker At Bridge (Y/N) No																
Remarks																
Other Sign Types Not Required																
						Ut	ilities	Loca	ted at)							
Utility Attachmer	Utility Attachments															
Telephone									S							
Power	·				ed to P1 and P4			Mu	Municipal							
Others									Problem (Y/N) No							
Remarks																
							Appro									
III i dian					L	ast	Now		Explanation of Condition							
Horizontal Alignment  Vertical Alignment						5	5	⊟Paı	Pedestrian Bridge Park file #1622 Erosion 200m west of Bridge @ Side of pathway - 30m le					long		
Roadway Width (m) 3.000												5.0m to 3.0m v			iong	
Approach Bump					5	6		ago Enu	Jila	.0.0	, to 0.0111 V	nue A	o. ratii			
Guardrail (Y/N) No																
Guardrail					Χ	X										
Length (m)																
Current Standard (Y/N)																
Termination Type																
Drainage						7	7									
								-								
Approach Road General Rating						5	5									

Superstructure										
Bridge Comp	onent			_		Explanation of Condition				
		ns, Lengths(r	n): 8.9-30.7-38			-Ident Number: A1229-01)				
Special Feat	ıres									
Special Featu	re				Х					
(Type:)										
Special Featu	Special Feature									
(Type : )										
Wearing Surfa	Wearing Surface/Deck Top Detail Ratings									
	N (%)	1 (%)	2 (%)	3 (%)						
Last										
Now	0.0	0.0	0.0	0	0.0					
Wearing Surfa				7	7	Isolated cracks are routed and sealed				
	pe : CONCRI									
	kness(mm) : 5	50)								
(Plank Widt	<del>'</del>			1	1					
Deck Rideabi	lity			7	7					
Deck Joints				3	3	West Abut Gland is fallen out @ s end. No extrusion				
Temperatur	e (deg. C)	20								
		D (WABO-MA	UER, TRANS	FLEX,	ETC))					
(Fixed Type										
Gap Size (n	nm)		ocation							
	70 East Abut									
40		West	Abut							
Curbs/Wheel				X	X					
(Curb Type	:)									
(Type:)										
(Thickness(										
(Width(mm)	:)				T -					
Bridge Rail				8 8		steel plate blocking				
(Type:)	. /5! !:			0 0						
Bridge Rail Po	osts/Blocking			8 8		Galvanized				
(Type:)	nata Os atim			0 7						
Bridge Rail/Po	osts Coating			8	7					
(Type:)				V						
Sidewalk				X	X					

Last   Now   Explanation of Condition	Superstructure												
Primary Span : TH, 5 Spans, Lengths(m): 8,9-30.7-38.8-30.7-8.9, A-Ident Number: A1229-01)   Wide Load Damage (Y/N)	Bridge Comp	onent											
Wide Load Damage (Y/N)         No           High Load Damage (Y/N)         No           Top Chord         8         8           Batter Posts         X         8           Sway Bracings         8         8           Diagonals         8         8           Verticals         8         8           Portals         8         8           Connections         X         8           Floor Beams         8         8           Bottom Chord         8         8           (No. of Stringers: 0)         0           Stringer Betall Ratings         8           Instrumental Response of the Count of the Co			ns, Lengths	s(m): 8.9-30.7-3	38.8-30.7								
High Load Damage (Y/N)													
Top Chord	High Load Damage (Y/N) No						Concrete Deck only						
Batter Posts					8	8	Dwydag rods						
Sway Bracings   8						8							
Diagonals													
Verticals													
Portals						8							
Connections							HSS Floor Beam Members @ Bearings						
South Chord													
Section Chord   Same   Same													
(No. of Stringers : 0)							-						
Stringer Detail Ratings													
N (count)													
Last   Now   Stringers   X   X	Camigor Dota	_	1 (count)	2 (count)	3 (co.	ınt)							
Now   Stringers	Last	it (ocum)	i (ocurr)	2 (000111)	0 (000		-						
Stringers													
(Type : STEEL) (Width(mm) : ) (Depth(mm) : ) (Spacing(mm) : )  Paint Condition					X	X							
(Width(mm):) (Depth(mm):) (Spacing(mm):)  Paint Condition		EL)											
(Depth(mm):) (Spacing(mm):)  Paint Condition													
(Spacing(mm):)  Paint Condition	, , ,												
Paint Condition													
(Colour Description:)       (Colour Code:)         Touchup Required (Y/N)       8         Bearings       8         Temperature (deg. C)       2         (Expansion Type: REINFORCED NEOPRENE BEARING WITH TEFLON AND STAINLESS STEEL)       (Fixed Type:)         Functioning (Y/N)       Sub Deck/Deck Underside         (Material Type: CONCRETE)       (Plank Thickness(mm): 150)         (Plank Width(mm):)       Defects (Percent Area)         Ospan Alignment Problems       Vertical (Y/N)         Vertical (Y/N)       No         Horizontal (Y/N)       No						X	Weathering Steel						
(Colour Code:) Touchup Required (Y/N)  Bearings							Troumoning Steel						
Touchup Required (Y/N)  Bearings	-						_						
Bearings													
Temperature (deg. C) 2  (Expansion Type : REINFORCED NEOPRENE BEARING WITH TEFLON AND STAINLESS STEEL)  (Fixed Type :)  Functioning (Y/N)  Sub Deck/Deck Underside 8 8 8  (Material Type : CONCRETE)  (Plank Thickness(mm) : 150)  (Plank Width(mm) :)  Defects (Percent Area) 0  Span Alignment Problems  Vertical (Y/N) No  Horizontal (Y/N) No		oquilou (1714)			0	0							
(Expansion Type : REINFORCED NEOPRENE BEARING WITH TEFLON AND STAINLESS STEEL)  (Fixed Type : ) Functioning (Y/N)  Sub Deck/Deck Underside 8 8  (Material Type : CONCRETE)  (Plank Thickness(mm) : 150)  (Plank Width(mm) : ) Defects (Percent Area) 0  Span Alignment Problems  Vertical (Y/N) No Horizontal (Y/N) No		o (dog C)	2		0	0							
(Fixed Type:) Functioning (Y/N)  Sub Deck/Deck Underside 8 8  (Material Type: CONCRETE)  (Plank Thickness(mm): 150)  (Plank Width(mm):)  Defects (Percent Area) 0  Span Alignment Problems  Vertical (Y/N) No  Horizontal (Y/N) No	(Expansion	Type : <b>REINI</b>	ORCED NE	OPRENE BEA	ARING W								
Functioning (Y/N)  Sub Deck/Deck Underside 8 8  (Material Type : CONCRETE)  (Plank Thickness(mm) : 150)  (Plank Width(mm) : )  Defects (Percent Area) 0  Span Alignment Problems  Vertical (Y/N) No  Horizontal (Y/N) No	(Fixed Type	e : )	,										
Sub Deck/Deck Underside 8 8  (Material Type : CONCRETE)  (Plank Thickness(mm) : 150)  (Plank Width(mm) : )  Defects (Percent Area) 0  Span Alignment Problems  Vertical (Y/N) No  Horizontal (Y/N) No													
(Material Type : CONCRETE) (Plank Thickness(mm) : 150) (Plank Width(mm) : ) Defects (Percent Area) 0  Span Alignment Problems Vertical (Y/N) No Horizontal (Y/N) No					8	8							
(Plank Thickness(mm) : 150) (Plank Width(mm) : )  Defects (Percent Area) 0  Span Alignment Problems  Vertical (Y/N) No  Horizontal (Y/N) No			ETE)										
(Plank Width(mm):)  Defects (Percent Area) 0  Span Alignment Problems  Vertical (Y/N) No  Horizontal (Y/N) No		•											
Defects (Percent Area) 0  Span Alignment Problems  Vertical (Y/N) No  Horizontal (Y/N) No													
Span Alignment Problems  Vertical (Y/N) No  Horizontal (Y/N) No			0										
Vertical (Y/N) No No No													
Horizontal (Y/N) No													
ouperstructure deficial reading		•			8	8							
Substructure						Subst	ructure						
Bridge Component Last Now Explanation of Condition	Bridge Com	onent			l ast								
Abutments		JOHOH			Lasi	14000	Expandion of Condition						
(Extended Backwall Piles (Y/N):) End of Bridge just connects to concrete grade beam @ Abuts	(Extended E			m) : )		Bridge End Spans are cantilever design and hang from piers on							

		5	re Usage	
				Explanation of Condition
Channel				
(U/S Direction : N)				7
(D/S Direction : S)				
Alignment		7	7	
Bank Stability			7	
HWM (m below Top of Curb)	2.0			No visible HWM
Drift (Y/N)	rift (Y/N) No			
Slope Protection		7	6	
(Type: NATURAL; NATURAL	)			
Guidebank/Spurs				
Adequacy of Opening		7	7	
(Fish Compensation Measure 1 :	NONE)			
(Fish Compensation Measure 2 :	NONE)			
Channel General Rating		7	7	

				Maintena	nce Recommer	datio	ns					
Inspector Recommendations	Ye	ear	Inspecto	r Comments		De	partment Comm	Target Year	Est. Cost	Cat #		
REPAIR/REPLACE BRIDGE RAIL												
RETROFIT BRIDGE RAIL												
SEAL CURBS												
PATCH DECK												
SEAL DECK												
OVERLAY DECK												
REPLACE STRIP DECK												
REPLACE SUB DECK												
RESET/ PAINT BEARINGS												
REPAINT SUPERSTRUCTURE												
STRAIGHTEN/REPLACE MEMBERS												
WASHING												
SHOTCRETE REPAIRS												
CORE TIMBER CAPS/CORBELS												
REPAIR/REPLACE TIMBER CAPS												
REPAIR ABUTMENT SCOUR/EROSIG	NC											
PLACE ADDITIONAL RIP RAP												
REMOVE DRIFT ACCUMULATION												
OTHER ACTION	201	10	Glue We	st Abut deck joint gla	and in place							
OTHER ACTION												
OTHER ACTION												
OTHER ACTION												
Structural Condition Rating (Last/No. (%)	ow) 83.	.3/83.3	3	Sufficiency Rating (%)	(Last/Now)	71.8/	/86.1	Est. Repl. Yr	2055	Maint. Red	qd. (Y/N)	Yes
Special Comments for Next Inspection	·					De	partment mments					
Maintenance Reviewed By						Da	te		E	stimated Total	0	
Proposed Long-Term Strategy												
On 3-Year Program (Y/N)												
Proposed Action												
Previous Inspector's Name	Tom Care	y			Previous	s Assis	stant's Name					
Next Inspection Date	01-Jul-201	15			Previous	s Inspe	ection Date	07-Jul-2005				
Inspection Cycle (Default) (months)	57											
Comment												