

Bridge Inspection									
Bridge File Number	81802 S-2 Bridge				Form Type	PSR			
Year Built/Year Supstr	2002/2002				Lot No.	3			
Bridge or Town Name	CALGARY				Inspector Name	Garry Roberts			
Located Over	BOW RIVER, 2.13, WATERCRS-ST				Inspector Class	BR CLS A			
Located On	2:15 L1 6.672				Assistant Name				
Water Body Cl./Year					Assistant Class				
Navigabil. Cl./Year					Inspection Date	30-Jan-2013			
Legal Land Location	SW SEC 9 TWP 22 RGE 29 W4M				Data Entry By	Erin Roberts			
Longitude, Latitude	-113:58:17, 50:51:11				Data Entry Date	19-Feb-2013			
Road Authority	Alberta Transportation (AIT)				Reviewer Name	Tom Carey			
Contract Main. Area	DEERFOOT/STONE Y				Review Date	06-Feb-2013			
Clear Roadway/Skew	12.9 / -10 deg. (LHF)				Dept. Reviewer Name	Tim Davies			
AADT/Year	33,500 / 2011 (A)				Dept. Review Date	21-Feb-2013			
Road Classification	RFD-412.4-130				Follow-Up By				
Detour Length (km)	1								
Allowable Load (t):	Single	CS1 28	Semi	CS2 49	Train	CS3 62	----> On Critical Spans ---->Critical Member		
Design Loading:	CS750						----> Primary Span		
Posting Information									
Required Load Posting (t)	Single				Semi		Truck Train		
Posted Loading (t)	Single				Semi		Truck Train		
Posted:	Lane	NB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No	
Posted:	Lane	SB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No	
Remarks	Not req.								
Hazard Marker At Bridge (Y/N)	No								
Remarks									
Other Sign Types	River ID								
Utilities (Located at)									
Utility Attachments									
Telephone					Gas				
Power	In West ROW				Municipal				
Others	Light standards				Problem (Y/N)	No			
Remarks									
Approach Road									
			Last	Now	Explanation of Condition				
Horizontal Alignment			7	7	Wrong lap at NE and NW. Minor damage at SW but still functioning.				
Vertical Alignment			7	7					
Roadway Width (m)	13.000								
Approach Bump			7	6					
Guardrail (Y/N)	Yes								
Guardrail			4	4					
Length (m)	99.000								
Current Standard (Y/N)	Yes								
Termination Type	TERMINAL ENDS								
Drainage			5	4	Minor erosion along NE wing				
<b>Approach Road General Rating</b>			<b>7</b>	<b>7</b>					

Superstructure					
Bridge Component		Last	Now	Explanation of Condition	
(Primary Span : <b>NU, 4 Spans, Lengths(m): 53-65-65-53, A-Ident Number: )</b>					
<b>Special Features</b>					
Special Feature					
(Type : )					
Special Feature					
(Type : )					
Wearing Surface/Deck Top Detail Ratings					
	N (%)	1 (%)	2 (%)	3 (%)	
<b>Last</b>	0	0	0	0	
<b>Now</b>	20.0	0.0	0.0	0.0	
Wearing Surface			7	7	Chip coat placed in 2004 over ACP
(Material Type : <b>ACP - CONVENTIONAL CHIP SEAL COAT</b> )					
(Thickness(mm) : <b>50</b> )					
Lateral Connection Problem (Y/N)		No			
Deck Top			N	N	
Deck Rideability			8	7	
Deck Joints			7	7	Both joints noisy but do not appear to be loose.
Temperature (deg. C)		-9			
(Expansion Type : <b>FINGER PLATES</b> )					
(Fixed Type : )					
Gap Size (mm)		Gap Location			
170		N abut			
160		S abut			
Deck Drainage			7	7	Galvanized containment system under east curb
Drains Clogged (Y/N)		No			
Curbs/Median			7	7	Typ. narrow vert. cracks at curb face between control joints. 50% snow covered.
(Curb Type : <b>Standard</b> )					
Scaling (Percent Area)		0			
Bridge Rail			8	8	
(Type : <b>STEEL BRIDGE TUBE</b> )					
Bridge Rail Posts			8	8	
(Type : <b>GALVANIZED POST STEEL; GALVANIZED POST STEEL</b> )					
Bridge Rail/Posts Coating			7	7	
(Type : )					
Sidewalk			X	X	
Girder Detail Ratings					
	N (count)	1 (count)	2 (count)	3 (count)	
<b>Last</b>	0	0	0	0	
<b>Now</b>	0	0	0	0	
Girders			7	7	Narrow cracks at girder ends. Hairline to narrow width horizontal and diagonal cracks at webs. 4 continuous girder lines
Cracking (Y/N)		Yes			
Spalling (Percent Area)		0			
(Number Of Girders : <b>16</b> )					

Superstructure				
Bridge Component		Last	Now	Explanation of Condition
(Primary Span : <b>NU, 4 Spans, Lengths(m): 53-65-65-53, A-Ident Number: )</b>				
Diaphragms/Cross Frame		8	8	
Bearings		8	8	P2 is integral
Temperature (deg. C)	-9			
(Expansion Type : <b>POT BEARING</b> )				
(Fixed Type : <b>POT BEARING</b> )				
Coating Adequate (Y/N)	Yes			
Functioning (Y/N)	Yes			
Deck Underside		8	8	
Stains (Percent Area)	0			
<b>Span Alignment Problems</b>				
Vertical (Y/N)	No			
Horizontal (Y/N)	No			
<b>Superstructure General Rating</b>		<b>7</b>	<b>7</b>	
Substructure				
Bridge Component		Last	Now	Explanation of Condition
<b>Abutments</b>				
Bearing Seats/Caps		8	8	
(Type : <b>CONCRETE</b> )				
Backwalls/Breastwalls		8	8	
Wingwalls		8	8	
Piles		N	N	Buried
Paint/Coating		X	X	
Abutment Stability		8	8	
Scour/Erosion		5	4	Erosion at NE wing.
<b>Piers/Bents</b>				
(Type : <b>PIER-COLUMN</b> )				
Bearing Seats/Caps		8	8	
(Type : <b>CONCRETE</b> )				
(Total Number of Bearing Piles : <b>0:0:0</b> )				
Pier Shaft/Piles		8	8	
Bracing/Struts/Sheathing		X	X	
Nose Plate		X	X	
Paint/Coating		X	X	
(Colour Description : )				
(Colour Code : )				
Pier Stability		8	8	
Scour		6	6	
Debris (Y/N)	No			
<b>Substructure General Rating</b>		<b>8</b>	<b>8</b>	

Structure Usage				
		Last	Now	Explanation of Condition
<b>Channel</b>				
(U/S Direction : <b>W</b> )				
(D/S Direction : <b>E</b> )				
Alignment		7	7	
Bank Stability		6	6	Steep cut banks @ D/S
HWM (m below Top of Curb)	8.0			No visible HWM
Drift (Y/N)	No			
Slope Protection		7	7	Rock at north only.
(Type : <b>RIP RAP</b> )				
Guidebank/Spurs		8	8	
Adequacy of Opening		7	7	
(Fish Compensation Measure 1 : <b>NONE</b> )				
(Fish Compensation Measure 2 : <b>NONE</b> )				
<b>Channel General Rating</b>		<b>7</b>	<b>7</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
REPAIR/REPLACE BRIDGE RAIL							
GALVANIZE/PAINT BRIDGE RAIL							
SEAL CURBS							
PATCH DECK							
SEAL DECK							
OVERLAY DECK							
REPAIR/REPLACE DECK JOINTS							
RESET/ PAINT BEARINGS							
WASHING							
SHOTCRETE REPAIRS							
REPAIR ABUTMENT SCOUR/EROSION	2013	Repair NE erosion approx 5m3 pit run.					
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>83.3/83.3</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>71.5/71.5</b>	Est. Repl. Yr	2071	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Garry Roberts		Previous Assistant's Name				
Next Inspection Date	30-Oct-2014		Previous Inspection Date	07-May-2011			
Inspection Cycle (Default) (months)	21						
Comment							