Bridge Inspection																	
Bridge File Number 82020 -1 Bridge								For	Form Type			CON					
Year Built/Year 2003/2003 Supstr 2003/2003									Lot No.			2					
<b>-</b>	Vame	SOUT	HI AND DI	ILAND DRIVE RAMP					Inspector Name			Garry Roberts					
Located Over	HLAND DI	AND DRIVE COLLECTOR					Inspector Class Assistant Name			BR CLS A							
Located On	RIBUTOR	UTUR					Assistant Class										
Located On	CIPAL						Inspection Date			24-Jan-2013							
Water Body CI./							Data Entry By			Lauren Korte							
Navigabil. Cl./Ye	FO 00 TW	D 00 D0	E 4 \\/	- N 4			Data Entry Date			17-Feb-2013							
				23 TWP 23 RGE 1 W5M					viewer N			Tom Carey					
			· · · · · · · · · · · · · · · · · · ·	28, 50:58:34					Review Date			30-Jan-2013					
Road Authority Alberta T  Contract Main. Area DEERFO			FOOT/ST	•	.11)			Dei	Dept. Reviewer Name								
									Dept. Review Date			21-Feb-2013					
Clear Roadway/S	skew		45 deg. (R	нг)					Follow-Up By								
	ion		/ 2007 (E)					+	. Glow-op by								
Road Classificat			209-60					+									
Detour Length (k	1	999			00.00	;			   <b>T</b>					\ \Om \Om!!!	nal Crans		
Allowable Load (	t): Sin	igie		Semi						Train				> On Critical N	1ember		
Design Loading:									> Primary	Span							
									nation				_				
Required Vert. C					R: SOI	JTHL/	AND DI	RIVE	IVE COLLECTOR DIST			RIBUTOR 5.5	ōm				
Posted Vertical (				Yes			I										
	NB		Bridge (m	)	In Adv	ance	(Y/N)	No	Lane	SB	0	n Bridge (m)	5.6	In Advance	(Y/N) No		
Remarks		affic onl	у.						1								
Required Load F	<u>_</u>	(t)			Single				Semi					Fruck Train			
Posted Loading	(t)			Single			10.0		Semi			Truck Train					
Posted:	Lane	WE		At Junction (Y						dvance (Y/N)				idge (Y/N)			
Posted:	Lane	EB		At Jun	ction (\	Y/N)	No		In Adva	ance (	Y/N)	No	At Br	idge (Y/N)	No		
Remarks		quired															
Hazard Marker A	At Brid	ge (Y/N															
Remarks				Not required.													
Other Sign Type	S		Route	Route, curve.  Utilities (Located at)													
Liche Arr I	,					Ut	ilities	(Loca	ted at)								
Utility Attachmen	nts																
Telephone									Gas								
Power			at SW.	<i>N</i>					Municipal Problem (Y/N) No								
Others		Standa					Problem (Y/N) No										
Remarks	Unaei	rsiae ae	eck lighting				Annro	aab D	lood								
						Last	Now		ch Road Explanation of Condition								
Horizontal Alignr	nent					5	5		On super elevated curve.								
Vertical Alignment					5	5		очрог о	iovato	a oa.							
Roadway Width (m) 12.000			)														
Approach Bump			,		7	7											
Guardrail (Y/N) Yes							Concrete parapets.										
Guardrail (1714)				8	8		.0.010 pr	a. apc									
			70.000	)		3	J										
Current Standard (Y/N)			Yes														
			sloped														
Drainage	70		Siopoc			7	7										

						Annroa	nch Road					
						Now						
Approach Road General Rating					5	5	Explanation of condition					
л.рр. сас		9										
					_		structure					
Bridge Con						Now	Explanation of Condition					
	an : <b>CT, 1 Spa</b> i	ns, Lenç	gths(r	n): 13.5, A-Id	ent Nun	nber: )						
Special Fea						T						
Special Fea	ture					X						
(Type:)						T						
Special Fea	ture					X						
(Type:)												
Wearing Sui	rface/Deck Top		Rating									
N (%) 1 (%) 2 (%)					3 (%)							
Last	0	0		0		0						
Now	10.0	0.	0	0.0		0.0						
Wearing Su					4 4		Pothole @ North Lane @ west abut deck joint - 6 m long x 150 wide. Also 1m2 delam at NW deck.					
	Гуре : <b>АСР</b> )						Rest of ACP Rates "7"					
(Thickness(mm): 50)												
Deck Top					N	N						
Deck Rideal	Deck Rideability				7	5						
Deck Joints	Deck Joints					8						
Temperature (deg. C) -3												
(Expansio			-									
	oe : <b>GLAND (W</b>	ABO-M	AUEF	R. TRANSFLE	X. ETC	<b>)</b> )						
Gap Size				_ocation	,,	,,						
70 East abut												
85 West abut												
Deck Draina	age				8	7						
	gged (Y/N)	N	lo									
Curbs/Media					8	8	Pigmented sealer is peeling at both exteriors.					
	e : NEW JERS	EY)					- igoned coalor to pooming at some enterior					
	ercent Area)	0										
Bridge Rail					Х	Х						
(Type:)												
Bridge Rail I	Posts				X	Х						
(Type:)												
	Posts Coating				X	X						
(Type:)												
Sidewalk					Х	Х						
Girders					X	8	Voided slab.					
Diaphragms	Diaphragms/Cross Frame				X	X						
Bearings					8	8						
Temperature (deg. C) -3					J	J						
	n Type : <b>POT E</b>											
(Fixed Typ		, <u> </u>	<b>J</b> )									
		V	′oc									
Coating Adequate (Y/N) Yes Functioning (Y/N) Yes												
		Y	'es									
Deck Underside					8	8	Cast Slab.					
Stains (Pe	ercent Area)	0										

				tructure
Bridge Component		Last	Now	Explanation of Condition
(Primary Span : CT, 1 Spans, Le	ngths(m): 13.5, A-Ide	nt Nur	nber: )	
Span Alignment Problems				
Vertical (Y/N)	No			
Horizontal (Y/N)	No			
Superstructure General Rating		8	8	
			Subst	ructure
Bridge Component		Last	Now	Explanation of Condition
Abutments				
Bearing Seats		8	8	
Backwalls/Breastwalls		8	8	MSE walls.
Wingwalls		8	8	
Piles		N	N	
Paint/Coating		5	5	Isolated peeling.
Abutment Stability		8	8	
Scour/Erosion		Х	Х	
Piers/Bents		-		
(Type:)				
Bearing Seats/Caps		Х	X	
(Type:)				
Pier Shaft/Piles		Х	Х	
Nose Plate		Х	Х	
Paint/Coating		Х	Х	
(Colour Description : )				
(Colour Code : )				
Pier Stability		Х	Х	
Scour		Х	Х	
Debris (Y/N)	No			
Substructure General Rating		8	8	
			Structu	re Usage
		Last	Now	Explanation of Condition
Grade Separation				
Road Alignment		7	6	
Traffic Safety Features		7	7	
Туре	parapets			
Slope Protection		8	8	Level area at top of MSE walls.
(Type : CONCRETE; CONCRE	TE)			
Bank Stability		8	8	
Drainage		8	7	
Grade Separation General Rating			6	

82020 -1 Bridge

			Maintenance Recor	nmenda	ations					
Inspector Recommendations	Year	Inspector Commo	ents		Department Com	ments		Target Year	Est. Cost	Cat #
REPAIR/REPLACE BRIDGE RAIL		·								
GALVANIZE/PAINT BRIDGE RAIL										
RETROFIT BRIDGE RAIL										
SEAL CURBS										
PATCH DECK	2013	Patch @ West at	but deck joint approx 3n	n2.						
SEAL DECK			, ,							
OVERLAY DECK										
REPAIR/REPLACE DECK JOINTS										
RESET/ PAINT BEARINGS										
WASHING										
SHOTCRETE REPAIRS										
REPAIR ABUTMENT SCOUR/EROS	ION									
PLACE ADDITIONAL RIP RAP										
REMOVE DRIFT ACCUMULATION										
OTHER ACTION										
OTHER ACTION										
OTHER ACTION										
OTHER ACTION										
Structural Condition Rating (Last/N (%)	low) 88.9/8	8.9 Sufficie	ency Rating (Last/Now	<i>ı</i> ) 5	8.6/69.9	Est. Repl. Yr	2073	Maint. Re	qd. (Y/N)	Yes
Special Comments for Next Inspection	,			<u>'</u>	Department Comments					
Maintenance Reviewed By					Date		E	Estimated Tota	I 0	
Proposed Long-Term Strategy										
On 3-Year Program (Y/N)										
Proposed Action										
Previous Inspector's Name	Garry Robert	8	Pre	evious <i>P</i>	ssistant's Name					
Next Inspection Date	24-Oct-2014		Pre	evious I	nspection Date	20-Apr-2011				
Inspection Cycle (Default) (months)	21					,				
Comment										