

Bridge Culvert Inspection			
Bridge File Number	82091 -1 Bridge Culvert	Form Type	CUL1
Year Built	2002	Lot No.	4
Bridge or Town Name	TWO HILLS	Inspector Name	Jason Saly
Located Over	TRIBUTARY TO VERMILION RIVER, 6.5.28, WATERCRS-ST	Inspector Class	BR CLS A
Located On	36:20 C1 23.205	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	09-Jan-2013
Legal Land Location	SW SEC 6 TWP 54 RGE 12 W4M	Data Entry By	Marcia Chavez
Longitude, Latitude	-111:46:16, 53:38:03	Data Entry Date	12-Feb-2013
Road Authority	Alberta Transportation (AIT)	Reviewer Name	John O'Brien
Contract Main. Area	CMA14	Review Date	19-Jan-2013
Clear Roadway/Skew	12 / 2 deg. (RHF)	Dept. Reviewer Name	Darron Ahlstedt
AADT/Year	1,290 / 2011 (A)	Dept. Review Date	13-Feb-2013
Road Classification	RAU-211.8-110	Follow-Up By	
Detour Length (km)	3		

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	3050	SP	72.54	152X51	3.0	ROUND
Special Features								
Special Features Comment								

Utilities (Located at)

Utility Attachments				
Telephone	West r/w.	Gas		
Power	1 wire 30m East of r/w.	Municipal		
Others		Problem (Y/N)	No	
Remarks				

Approach Road / Embankment

		Last	Now	Explanation of Condition
Horizontal Alignment		8	8	On grade, long crest curve to the South.
Vertical Alignment		7	7	
Roadway Width (m)	12.000			
Embankment		7	N	Snow covered, but no signs of problems.
Sideslope (:1)	4.0			Steepen to 3:1.
(Height of Cover(m) : 6.5)				West side measured.
Guardrail (Y/N)	No			
Approach Road / Embankment General Rating		7	7	

Upstream End

Culvert Component		Last	Now	Explanation of Condition
Direction		W		
End Treatment (Concrete, Steel, Others, None)	CONCRETE			
Headwall		9	8	
Collar		9	N	Snow covered.
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		N	N	Buried.

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		N	N	Under ice.
Heaving (mm)	300			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	600			
Scour Protection		N	N	Snow covered but no sign of problem.
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 350)				
Scour/Erosion		N	N	
Beavers (Y/N)	No			
Upstream End General Rating		7	N	GR was 7 from 11Aug2009.
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1 , Primary Span, Location Code: MAIN , Span (mm): , Rise (mm): 3050 , Type: SP)				
Barrel Last Accessible Date	09-Jan-2013			
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		N	6	Roof deformed on SW u/s end, but functional; estimated 30mm.
Measured Rise (mm)				
Measured At Ring No.				Estimated.
Sag (mm)				
Percent Sag	2			
Sidewall		N	7	Span at R2=3101=51mm Span at R9=3111=61mm=2% Span at R16=3056=6mm
Measured Span (mm)	3111			
Measured At Ring No.	9			
Deflection (mm)	61			
Percent Deflection	2			
Floor		N	N	Ice
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		N	8	
Separation (mm)	0			
Longitudinal Seams		N	8	
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	Yes			
Longitudinal Stagger (Y/N)	Yes			2N
Coating		N	7	
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	No			Typical standing water.

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 3050, Type: SP)				
Fish Passage Adequacy		7	7	
Baffle		X	X	
(Type :)				
Waterway Adequacy		9	8	(Ice 1.64m from roof near c/l. 02/12/10)
Icing (Y/N)	No			(10Dec2002).
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		N	6	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		E		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		N	N	Missing last bolt @ 10:00 along seam, minor. Iced over.
Heaving (mm)	150			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	600			
Scour Protection		N	N	Snow covered but no sign of problem.
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 400)				
Scour/Erosion		N	N	
Beavers (Y/N)	No			
Downstream End General Rating		7	N	GR was 7 from 11Aug2009.
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		7	7	Meandering stream.
Bank Stability		7	7	Low marshy area.
HWM (m below Top of Culvert)				HWM not visible.
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading	NONE			(10Dec2002).
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		7	7	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	55.6/66.7	Sufficiency Rating (Last/Now) (%)	72.1/70.3	Est. Repl. Yr	2054	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date		Estimated Total	0	
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Dave Lam		Previous Assistant's Name				
Next Inspection Date	09-Oct-2014		Previous Inspection Date	08-Dec-2010			
Inspection Cycle (Default) (months)	21						
Comment							