						Brid	lge Ir	nspectio	n							
Bridge File Num	File Number 82400 W-2 Bridge							Form Type			SG					
Year Built/Year 2006/2006									Lot No.			3				
Supstr						Inspector Name			Garry Roberts							
Bridge or Town						Inspect	Inspector Class			BR CLS A						
Located Over	NOSE CREEK, 2.13.32.1, RCRS-ST					Assistant Name										
Located On		201:08 L						Assistant Class								
Water Body Cl./	Year							Inspection Date			20-Aug-2011					
Navigabil. Cl./Ye									ntry By		Erin Roberts					
Legal Land Loca		SW SEC	29 TWP	25 RGE			Data Er	Data Entry Date			07-Sep-2011					
Longitude, Latitu		-114:06:4					Reviewer Name			Tom Carey						
Road Authority		Alberta T			T)			Review Date			24-Aug-201	1				
Contract Main. A	Area	DEERFO			,			Dept. Reviewer Name			Tim Davies					
Clear Roadway/	Skew	13.3 /						Dept. R	eview Da	ate	08-Sep-201	1				
AADT/Year		29,320 /	2010 (A)					Follow-	Uр Ву							
Road Classificat	ion	RFD-412														
Detour Length (I	km)	1														
Allowable Load		ngle			Semi				Train				> On Criti	n Critical Spans		
											>Critica		>Critical N			
Design Loading:													> Primary	Span		
Required Load F	Postino	ı (t)		Single		Post	ing II	nformation Semi			Truck Train					
Posted Loading		( )		Single									k Train			
Posted:	Lane	WB			tion (Y/N)	No			Semi In Advance (Y				ridge (Y/N)	No		
Posted:	Lane	EB			tion (Y/N)		,	In Advance (Y/N)		INO	At Bridge (Y/N)		INO			
Remarks Not reg'd					11011 (1714)			111 7	dvarice	(1/14)		AL D	nage (1/14)			
Hazard Marker			No													
Remarks	At Dila	ge (1/1 <b>1</b> )	140													
Other Sign Type																
Other eight type						Utiliti	ies (L	Located	at)							
Utility Attachmer	nts								,							
Telephone								Gas								
Power	In are	:a						Municipal								
Others	Light	Standards							Problem (Y/N) No							
Remarks								•								
						Ар	proa	ch Road								
					Las	st N	low	Explan	Explanation of Condition							
Horizontal Aligni	ment				7	7	7									
Vertical Alignme	nt				7	7	7									
Roadway Width	(m)		15.000					Bump and potholes at		both approaches. East is worst.						
Approach Bump					8	8 3										
Guardrail (Y/N)		Yes					Thriebe	am- 10m	at ex	iting end 50m	at ap	proach.				
Guardrail				8	8 8											
Length (m)			10.000													
Current Stand	ard (Y/	N)	Yes													
Termination Ty	уре		Attenati	on												
Drainage					7	7	7									
Approach Road	l Gene	eral Ratin	1		-	7	7									
Approach Noac		. a. Rauni					•									

					Supers	structure
Bridge Com	ponent					Explanation of Condition
_	an : <b>WG, 1 Sp</b> a	ans. I engths	(m): 43. A-lde			
Special Feat		and, Longino	(),			
Special Feat					X	
(Type:)	<u></u>					
Special Feat	ure				X	
(Type:)	uie					
	face/Deck Top	Dotail Pating	10			
vvearing Sun	N (%)	1 (%)				
Last	0	0	0	3 (%)	0	
Now	0.0	0.0	0.0	_	0.0	
		0.0	0.0			Transverse supplies at Fast and from impact leading of approach
Wearing Sur		NE 4 AOD)		8	6	Transverse cracking at East end from impact loading of approach bump.
	ype : MIX TYP	PE 1 ACP)				
(Thickness	(mm) : <b>90</b> )			1	1	
Deck Top				N	N	Paved over.
Deck Rideab	ility			8	4	Due to approach bump causing impact loading.
Deck Joints				X	Х	
Temperatu	re (deg. C)					
(Expansion	Type:)					
(Fixed Type						
Gap Size (	mm)	Gap	Location			
·	•	·				
Deck Draina	ne	<u> </u>		7	7	
Drains Clo		No				
Curbs/Media				8	8	
	: Standard)					
	ercent Area)	0				
Bridge Rail	Jisoni / licaj	U		9	8	
	EEL BRIDGE	TURE)		9	O	
Bridge Rail F		· ODL)		9	8	
	LVANIZED P	OST STEEL .	DOST STEEL			
	Posts Coating	OUT UTEEL,I	JOI JIEEL	8	8	
	USIS CUAIIIIY			0	U	
(Type : ) Sidewalk				X	V	
Sidewalk				^	X	
Girder/Beam	1					
Cover Plate					X	
Flange				8	8	
Web					8	
Stiffeners				8	8	
Splice				X	X	
Weld				8	8	
Diaphragms/	Cross Frame			8	8	

			tructure	
Bridge Component		Last		Explanation of Condition
(Primary Span : WG, 1 Spans, L	engths(m): 43, A-Iden	t Num	ber: A1	(696-01)
Paint Condition		X	X	Weathering steel
(Colour Description : )				
(Colour Code : )				
Touchup Required (Y/N)	No			
Bearings		8	8	
Temperature (deg. C)	21			
(Expansion Type : REINFORC	ED PAD BEARING)			
(Fixed Type : )				
Coating Adequate (Y/N)	Coating Adequate (Y/N) Yes			
Functioning (Y/N)	Yes			
Deck Underside		8	8	
Stains (Percent Area)	0			
Span Alignment Problems				
Vertical (Y/N)	No			
Horizontal (Y/N)	No			
Superstructure General Rating		8	8	
			Subst	ructure
Bridge Component		Last	Now	Explanation of Condition
Abutments		Luci	11011	
Bearing Seats/Caps		8	8	
(Type : CONCRETE)				
Backwalls/Breastwalls			8	
Wingwalls			8	
Piles		8	8	4 drilled piles each abut.
Paint/Coating		8	8	Graffiti at both ends.
Abutment Stability		9	8	
Scour/Erosion		7	7	
Piers/Bents				
(Type:)				
Bearing Seats/Caps		Х	Х	
(Type:)				
(Total Number of Bearing Piles :	)			
Pier Shaft/Piles		Х	Х	
Bracing/Struts/Sheathing		Х	Х	
Nose Plate			Х	
Paint/Coating			X	
(Colour Description : )		X		
(Colour Code : )				
Pier Stability			Х	
Scour		Х	Х	
Debris (Y/N)	No			
Substructure General Rating		8	8	

Structure Usage										
		Last	Now	Explanation of Condition						
Channel										
(U/S Direction : N)			Pathways at both abuts.							
(D/S Direction : S)			Curve U/S							
Alignment		6	6	Carro 5/5						
Bank Stability			7							
HWM (m below Top of Curb)				No visible HWM						
Drift (Y/N)	No									
Slope Protection		7	7							
(Type: NATURAL; NATURAL	)									
Guidebank/Spurs		X	X							
Adequacy of Opening			7							
(Fish Compensation Measure 1 :	NONE)									
(Fish Compensation Measure 2 :	NONE)									
Channel General Rating		6	6							

Bridge Inspection & Maintenance System (Web 2005)

				Mai	intenance Re	ecommend	lations						
Inspector Recommendations		Year	Inspector	r Comments			Department Co	mmer	Target Year	Est. Cost	Cat #		
REPAIR/REPLACE BRIDGE RAIL													
GALVANIZE/PAINT BRIDGE RAIL													
RETROFIT BRIDGE RAIL													
SEAL CURBS													
PATCH DECK													
SEAL DECK		2011	Seal tran	nsverse crack E	East end- fror	n bump							
OVERLAY DECK													
REPAIR/REPLACE DECK JOINTS													
RESET/ PAINT BEARINGS													
REPAINT SUPERSTRUCTURE													
STRAIGHTEN/REPLACE MEMBERS													
WASHING													
SHOTCRETE REPAIRS													
REPAIR ABUTMENT SCOUR/EROSI	ON												
PLACE ADDITIONAL RIP RAP													
REMOVE DRIFT ACCUMULATION													
OTHER ACTION		2011 Exacavate and transition paving at b causing impact loading on bridge.				oth ends-							
OTHER ACTION													
OTHER ACTION													
OTHER ACTION													
Structural Condition Rating (Last/N (%)	ow)	88.9/88		Sufficiency F (%)	Rating (Last/	Now)	67.6/64.4	Es	t. Repl. Yr	2078	Maint. Red	qd. (Y/N)	Yes
Special Comments for Next Inspection							Department Comments						
Maintenance Reviewed By							Date			F	Estimated Total	I 0	
Proposed Long-Term Strategy													
On 3-Year Program (Y/N)													
Proposed Action													
Previous Inspector's Name	Garry R	Garry Roberts					Previous Assistant's Name						
Next Inspection Date	20-May	0-May-2013 Previous Inspection Date 23-Nov-2009											
Inspection Cycle (Default) (months)													
Comment	21												