

Bridge Culvert Inspection			
Bridge File Number	08242 -1 Bridge Culvert	Form Type	CUL1
Year Built	1990	Lot No.	1
Bridge or Town Name	GADSBY	Inspector Name	Dave Lam
Located Over	PAINTEARTH CREEK, 5.23, WATERCRS-ST	Inspector Class	BR CLS A
Located On	601:04 C1 21.438	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	12-Jul-2011
Legal Land Location	SW SEC 16 TWP 40 RGE 16 W4M	Data Entry By	Marcia Chavez
Longitude, Latitude	-112:15:24, 52:26:02	Data Entry Date	16-Aug-2011
Road Authority	Alberta Transportation (AIT)	Reviewer Name	John O'Brien
Contract Main. Area	UNDEFINED CMA	Review Date	27-Jul-2011
Clear Roadway/Skew	12 / 45 deg. (RHF)	Dept. Reviewer Name	Chris Black
AADT/Year	100 / 2010 (A)	Dept. Review Date	30-Aug-2011
Road Classification	RCU-209G-90	Follow-Up By	
Detour Length (km)	6		

**Bridge Culvert Information**

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	3670	SP	61	152X51	3.0	ROUND
Special Features								
Special Features Comment								

**Utilities (Located at)**

Utility Attachments			
Telephone	In r/w to North.	Gas	
Power	3 wires 15m North of c/l.	Municipal	
Others		Problem (Y/N)	No
Remarks			

**Approach Road / Embankment**

	Last	Now	Explanation of Condition
Horizontal Alignment	7	7	Pipe through int R.R. 16-4.
Vertical Alignment	9	9	
Roadway Width (m)	12.000		
Embankment	7	3	1.0m deep crevices at various spots on roadway shoulder around both bevel ends (photo).
Sideslope ( __:1)	3.0		
(Height of Cover(m) : 1)			
Guardrail (Y/N)	No		
<b>Approach Road / Embankment General Rating</b>	<b>7</b>	<b>3</b>	

**Upstream End**

Culvert Component	Last	Now	Explanation of Condition
Direction	N		Northwest.
End Treatment (Concrete, Steel, Others, None)	CONCRETE		
Headwall	8	8	
Collar	8	8	
Wingwalls	X	X	
(Shape : )			
Cutoff Wall	N	N	Submerged.

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		8	8	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			(08Oct2009). Under water.
Above/Below (mm)	600			
Scour Protection		4	3	Riprap sloughed up to 300mm around collar.
(Type : <b>RIP RAP</b> )				
(Avg. Rock Size(mm) : <b>300</b> )				
Scour/Erosion		4	3	Erosion from road drainage creating deep crevices, but not as a result of insufficient riprap.
Beavers (Y/N)	No			
<b>Upstream End General Rating</b>		<b>8</b>	<b>3</b>	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 3670, Type: SP)				
Barrel Last Accessible Date	22-Mar-2006			Water 0.9m deep, viewed from ends. No problems visible.
<b>Special Features</b>				
Special Feature				
(Type : )				
Special Feature				
(Type : )				
Roof		8	8	
Measured Rise (mm)				
Measured At Ring No.				(Est. sag 60mm. 22Mar2006).
Sag (mm)	60			
Percent Sag	2			
Sidewall		8	N	(22Mar2006)
Measured Span (mm)	3730			
Measured At Ring No.	9			
Deflection (mm)	60			1.6%
Percent Deflection	2			
Floor		N	N	
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		N	N	
Separation (mm)	0			
Longitudinal Seams		N	N	
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	Yes			
Longitudinal Stagger (Y/N)	Yes			
Coating		7	7	
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	ZERO			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 3670, Type: SP)				
Ponding (Y/N)	No			
Fish Passage Adequacy		8	8	
Baffle		X	X	
(Type : )				
Waterway Adequacy		8	8	(22Mar2006). Under water.
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
<b>Barrel General Rating</b>		<b>N</b>	<b>N</b>	G.R. was "8" from 22/Mar/2006.
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		S		Southeast.
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	
Bevel End		7	7	(08Oct2009). Under water.
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	1000			
Scour Protection		5	3	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		5	3	Surface erosion off road causing deep voids & undermining (photo).
Beavers (Y/N)	No			
<b>Downstream End General Rating</b>		<b>5</b>	<b>3</b>	
Structure Usage				
		Last	Now	Explanation of Condition
<b>Channel (U/S and D/S)</b>				
Alignment		8	8	
Bank Stability		5	5	Vertical banks U/S & D/S.
HWM (m below Top of Culvert)	1.7			(22Mar2006). Grass in fence.
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading	AGGRADING			(22Mar2006). Under water.
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
<b>Channel General Rating</b>		<b>8</b>	<b>8</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP	2011	Add all aroun both bevels.					
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION	2011	Repair crevices/voids in embankment at both ends.					
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>55.6/55.6</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>70.7/52.9</b>	Est. Repl. Yr	2052	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection	Observe inlet slope protection for possible undermining.		Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Owen Salava		Previous Assistant's Name				
Next Inspection Date	12-Oct-2014		Previous Inspection Date	08-Oct-2009			
Inspection Cycle (Default) (months)	39						
Comment							