

Bridge Inspection										
Bridge File Number	83058 -1 Bridge				Form Type	TT				
Year Built/Year Supstr	1986/1986				Lot No.	4				
Bridge or Town Name	N COOKING LA				Inspector Name	Jason Saly				
Located Over	WATERCOURSE, WATERCRS-NI				Inspector Class	BR CLS A				
Located On	TRAIL-PED, ON 50000 FB				Assistant Name					
Water Body Cl./Year					Assistant Class					
Navigabil. Cl./Year					Inspection Date	28-Nov-2011				
Legal Land Location	SE SEC 19 TWP 52 RGE 20 W4M				Data Entry By	Marcia Chavez				
Longitude, Latitude	-112:55:43, 53:30:11				Data Entry Date	03-Jan-2012				
Road Authority	Alberta Transportation (AIT)				Reviewer Name	John O'Brien				
Contract Main. Area	UNDEFINED CMA				Review Date	15-Dec-2011				
Clear Roadway/Skew	3 /				Dept. Reviewer Name	Andrew Smikles				
AADT/Year					Dept. Review Date	09-Jan-2012				
Road Classification	RLU-207G-60				Follow-Up By					
Detour Length (km)										
Allowable Load (t):	Single		Semi		Train		----> On Critical Spans ---->Critical Member			
Design Loading:							----> Primary Span			

Posting Information									
Required Load Posting (t)	Single				Semi		Truck Train		
Posted Loading (t)	Single				Semi		Truck Train		
Posted:	Lane	EB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No	
Posted:	Lane	WB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No	
Remarks									
Hazard Marker At Bridge (Y/N)	No								
Remarks									
Other Sign Types									

Utilities (Located at)										
Utility Attachments										
Telephone					Gas					
Power					Municipal					
Others					Problem (Y/N)	No				
Remarks										

Approach Road									
		Last	Now	Explanation of Condition					
Horizontal Alignment		5	6	TRAIL; OK for designed use.					
Vertical Alignment		5	6						
Roadway Width (m)	3.700								
Approach Bump		5	6						
Guardrail (Y/N)		No							
Guardrail		X	X						
Length (m)									
Current Standard (Y/N)		No							
Termination Type		None							
Drainage		5	N	Snow covered.					
<b>Approach Road General Rating</b>		<b>5</b>	<b>6</b>						

Superstructure					
Bridge Component		Last	Now	Explanation of Condition	
(Primary Span : <b>TT, 1 Spans, Lengths(m): 4.9, A-Ident Number: )</b>					
<b>Special Features</b>					
Special Feature			X		
(Type : )					
Special Feature			X		
(Type : )					
Wearing Surface/Deck Top Detail Ratings					
	N (%)	1 (%)	2 (%)	3 (%)	Snow covered.
<b>Last</b>					
<b>Now</b>	100.0	0.0	0.0	0.0	
Wearing Surface/Deck Top				5	N
(Material Type : <b>TREATED TIMBER</b> )					
(Plank Thickness(mm) : <b>80</b> )					
(Plank Width(mm) : <b>310</b> )					
Deck Rideability				5	6
Wheel Guards				5	7
(Curb Type : <b>Standard</b> )					
(Type : <b>TREATED TIMBER</b> )					
(Thickness(mm) : <b>150</b> )					
(Width(mm) : <b>150</b> )					
Bridge Rail					6
(Type : <b>TREATED TIMBER BRIDGE SOLID BEAM (EX. TIMBER RAILS)</b> )					
Bridge Rail Posts				X	6
(Type : <b>TREATED TIMBER;TREATED TIMBER</b> )					
Bridge Rail/Posts Coating				X	X
(Type : )					
(No. of Stringers : <b>7</b> )					
Stringer Detail Ratings					
	N (count)	1 (count)	2 (count)	3 (count)	
<b>Last</b>					
<b>Now</b>	0	0	0	0	
Stringers				5	7
(Type : <b>TREATED TIMBER</b> )					
(Width(mm) : <b>200</b> )					
(Depth(mm) : <b>300</b> )					
(Spacing(mm) : <b>530</b> )					
Sub Deck/Deck Underside				X	6
(Material Type : <b>TREATED TIMBER</b> )					
(Plank Thickness(mm) : <b>75</b> )					
(Plank Width(mm) : <b>300</b> )					
Defects (Percent Area)					
<b>Span Alignment Problems</b>					
Vertical (Y/N)		No			
Horizontal (Y/N)		No			
<b>Superstructure General Rating</b>				<b>5</b>	<b>7</b>

Substructure									
Bridge Component		Last	Now	Explanation of Condition					
<b>Abutments</b>									
(Extended Backwall Piles (Y/N) : <b>N</b> )									
(Extended Backwall Piles Spacing(mm) : )									
(Total Number of Caps/Corbels : <b>1:1</b> )				TT cap on mud sill.					
Bearing Seats/Caps/Corbels Detail Ratings									
	N (count)	1 (count)	2 (count)				3 (count)		
<b>Last</b>									
<b>Now</b>	0	0	0				0		
Bearing Seats/Caps/Corbels							X	5	
(Type : <b>TREATED TIMBER</b> )									
(Depth(mm) : <b>140</b> )									
(Width(mm) : <b>500</b> )									
Backwalls/Breastwalls							X	X	
Greatest Height (m)									
Wingwalls				X	X				
(Total Number of Bearing Piles : <b>0:0</b> )									
Piles Detail Ratings									
	N (count)	1 (count)	2 (count)	3 (count)					
<b>Last</b>									
<b>Now</b>	0	0	0	0					
Piles				X	X				
Paint/Coating				X	X				
Abutment Stability				5	6				
Scour/Erosion				5	6				
<b>Piers/Bents</b>									
(Type : )									
(Total Number of Caps/Corbels : )									
Bearing Seats/Caps/Corbels Detail Ratings									
	N (count)	1 (count)	2 (count)	3 (count)					
<b>Last</b>									
<b>Now</b>									
Bearing Seats/Caps/Corbels				X	X				
(Type : )									
(Depth(mm) : )									
(Width(mm) : )									
(Total Number of Bearing Piles : )									
Piles Detail Ratings									
	N (count)	1 (count)	2 (count)	3 (count)					
<b>Last</b>									
<b>Now</b>									
Pier Shaft/Piles				X	X				
Greatest Height (m)									
Bracing/Struts/Sheathing				X	X				
Nose Plate				X	X				
Paint/Coating				X	X				
(Colour Description : )									
(Colour Code : )									
Pier Stability				X	X				

Substructure				
Bridge Component		Last	Now	Explanation of Condition
Scour		X	X	
Debris (Y/N)	Yes			
<b>Substructure General Rating</b>		<b>5</b>	<b>5</b>	
Structure Usage				
		Last	Now	Explanation of Condition
<b>Channel</b>				
(U/S Direction : <b>N</b> )				
(D/S Direction : <b>S</b> )				
Alignment		5	6	
Bank Stability		5	N	Snow covered.
HWM (m below Top of Curb)				HWM not visible.
Drift (Y/N)	Yes			Beaver dam u/s ~10m.
Slope Protection		5	6	
(Type : <b>NATURAL; NATURAL</b> )				
Guidebank/Spurs		X	X	
Adequacy of Opening		5	6	
(Fish Compensation Measure 1 : <b>NONE</b> )				
(Fish Compensation Measure 2 : <b>NONE</b> )				
<b>Channel General Rating</b>		<b>5</b>	<b>6</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
REPAIR/REPLACE BRIDGE RAIL							
PATCH DECK							
REPLACE STRIP DECK							
REPLACE SUB DECK							
STRAIGHTEN/REPLACE MEMBERS							
WASHING							
CORE TIMBER CAPS/CORBELS							
REPAIR/REPLACE TIMBER CAPS							
REPAIR ABUTMENT SCOUR/EROSION							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL STRUTS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>55.0/66.7</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>51.2/82.8</b>	Est. Repl. Yr	2017	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Aime Theroux		Previous Assistant's Name				
Next Inspection Date	28-Aug-2016		Previous Inspection Date	12-Nov-2002			
Inspection Cycle (Default) (months)	57						
Comment							