						Bridge I	nspection						
Bridge File Num	e File Number 83063 -1 Bridge						Form Type		ТТ				
Year Built/Year		2002/2002					Lot No.	2					
Supstr							Inspector Nar	ne	Jason Saly				
Bridge or Town	Name	N COOK					Inspector Cla	BR CLS A					
Located Over			COURSE				Assistant Nar	ne					
Located On		TRAIL-P	ED, ON 5	0000 F	В		Assistant Cla						
Water Body Cl./							Inspection Da	29-Nov-201	1				
Navigabil. Cl./Y							Data Entry By	Marcia Chavez					
Legal Land Loc			26 TWP		20 W4M		Data Entry Da	03-Jan-2012	2				
Longitude, Latit	ude		59, 53:30				Reviewer Na	John O'Brie	n				
Road Authority			ransporta		-)		Review Date						
Contract Main.		UNDEFI	NED CM/	4			Dept. Review	er Name	Andrew Smi	kles			
Clear Roadway	/Skew						Dept. Review		09-Jan-2012	2			
AADT/Year							Follow-Up By						
Road Classifica		RLU-207	′G-60										
Detour Length (
Allowable Load	(t): Sir	gle			Semi		Tr	ain			> On Criti >Critical M	cal Spans ⁄Iember	
Design Loading:					II			I			> Primary		
5 5						Posting I	nformation				,, ,		
Required Load Posting (t)				Single			Semi			Truck Train			
Posted Loading (t)				Single			Semi			Truck Train			
Posted:	Lane	EB		At Junction (Y/N)		No	In Advan	In Advance (Y/N)		At Bridge (Y/N)		No	
Posted:	Lane	WB		At Junction (Y/N)		No		In Advance (Y/N)		At Bridge (Y/N)		No	
Remarks							I						
Hazard Marker	At Brid	ae (Y/N)	No										
Remarks													
Other Sign Type	es												
					ι	Jtilities (I	_ocated at)						
Utility Attachme	nts												
Telephone							Gas						
Power							Municipal						
Others							Problem (Y/N) No					
Remarks													
						Approa	ch Road						
					Las	t Now	Explanation	of Condi	tion				
Horizontal Align	ment				Las		1	of Condi	tion				
Horizontal Align Vertical Alignme						5	Explanation	of Condi	tion				
	ent		4.000		5	5	Explanation	of Condi	tion				
Vertical Alignme	ent (m)		4.000		5	5	Explanation	of Condi	tion				
Vertical Alignme Roadway Width	ent (m)		4.000 No		5	5	Explanation	of Condi	tion				
Vertical Alignme Roadway Width Approach Bump	ent (m)				5	5 5 5	Explanation	of Condi	tion	_			
Vertical Alignme Roadway Width Approach Bump Guardrail (Y/N)	ent (m)				5 5 5	5 5 5	Explanation	of Condi	tion				
Vertical Alignme Roadway Width Approach Bump Guardrail (Y/N) Guardrail	ent (m)	N)			5 5 5	5 5 5	Explanation	of Condi	tion				
Vertical Alignme Roadway Width Approach Bump Guardrail (Y/N) Guardrail Length (m)	ent (m) o	N)	No		5 5 5	5 5 5	Explanation	of Condi	tion				
Vertical Alignme Roadway Width Approach Bump Guardrail (Y/N) Guardrail Length (m) Current Stand	ent (m) o	N)	No		5 5 5	5 5 5 X	Explanation	of Condi	tion				

						structure
Bridge Comp					Now	Explanation of Condition
	n : TT, 1 Span	is, Lengths(n	n): 6.7, A-Ide	nt Numl	ber:)	
Special Feat						
Special Featu	ire				X	
(Type :)						_
Special Featu	ire				X	
(Type :)						
Wearing Surfa	ace/Deck Top					
	N (%)	1 (%)	2 (%)	3 (%)		_
Last						Snow covered.
Now	100.0	0.0	0.0	C	0.0	
	ace/Deck Top			5	N	-
	/pe : UNTREA		R)			_
(Plank Thic	kness(mm) : 7	5)				_
(Plank Widt	h(mm) : 300)					
Deck Rideabi	lity			5	5	
Wheel Guard	S			5	6	
(Curb Type	: Standard)					_
(Type :)						_
(Thickness	(mm) :)				_	
(Width(mm)	:)					
Bridge Rail					5	DECK TO STREAMBED APPROX. 700m
(Type : BRI	DGE SOLID E	BEAM (EX. TI	MBER RAILS	5))		
Bridge Rail P	osts			X	5	
(Type :)						
Bridge Rail/Posts Coating X X						
(Type :)						
(No. of String	ers : 7)					
Stringer Deta	il Ratings					
	N (count)	1 (count)	2 (count)	3 (cou	unt)	
Last						
Now	0	0	0		0	
Stringers				5	7	
(Type : TRE	EATED TIMBE	ER)				_
(Width(mm)	: 200)					
(Depth(mm) : 300)					
(Spacing(m	m):)					
Sub Deck/De	ck Underside			X	7	Deck underside; single layer TT.
(Material Ty	/pe : TREATE	D TIMBER)				
(Plank Thic	kness(mm) : 7	5)				_
	h(mm) : 300)					
Defects (Pe						
	ent Problems	5				
Vertical (Y/		No				
Horizontal (•	No				
	ure General R	ating		5	7	
					Subst	ructure
Bridge Comp	onent			Last	Now	Explanation of Condition
Abutments						
(Extended I	Backwall Piles	(Y/N):)				
(Extended I	Backwall Piles	Spacing(mm)):)			

					Subst	ructure
Bridge Comp	oonent			Last	Now	Explanation of Condition
(Total Number of Caps/Corbels : :)					Timber caps on mud sill.	
Bearing Seats	s/Caps/Corbe	Is Detail Ratir	ngs			_
	N (count)	1 (count)	2 (count)	3 (co	unt)	_
Last						-
Now	0	0	0		0	-
Bearing Seat	s/Caps/Corbe	ls		5	5	
(Type : TRE	EATED TIMB	ER)				_
(Depth(mm) : 200)					_
(Width(mm)) : 500)					
Backwalls/Bro	eastwalls			Х	X	
Greatest He	eight (m)					
Wingwalls				X	X	
(Tatal Nivesha	w of Dooring (
	er of Bearing F	Plies : U:U)				-
Piles Detail R		1 (001001)	2 (001101)	2 (00	unt)	
Last	N (count)	1 (count)	2 (count)	3 (co	unt)	-
Now	0	0	0		0	-
Piles	0	0	0	X	x	-
Paint/Coating				X	X	
Faint/Coating)					
Abutment Stability					4	Settlement at SE corner; Parks Maintenance has repaired twice over the years.
Scour/Erosion					5	
Piers/Bents						
(Type :)						_
(Total Numbe	er of Caps/Co	rbels :)				_
Bearing Seats	s/Caps/Corbe	Is Detail Ratir	ngs			
	N (count)	1 (count)	2 (count)	3 (co	unt)	_
Last						-
Now						-
	s/Caps/Corbe	ls		X	X	-
(Type :)						-
(Depth(mm						-
(Width(mm)	· · ·					
	er of Bearing F	Piles :)				-
Piles Detail R						-
	N (count)	1 (count)	2 (count)	3 (co	unt)	-
Last						
Now				X		-
Pier Shaft/Piles					X	
Greatest He						
Bracing/Struts/Sheathing				X	X	
Nose Plate				X	X	
Paint/Coating				X	X	
(Colour Des	scription :)					
(Colour Co	de:)					
Pier Stability				X	X	
Scour				X	Х	

			Subst	ructure
Bridge Component		Last	Now	Explanation of Condition
Debris (Y/N)	Yes			
Substructure General Rating		5	4	
		S	Structu	re Usage
		Last	Now	Explanation of Condition
Channel				
(U/S Direction :)				Unknown
(D/S Direction :)				
Alignment			7	
Bank Stability		7	7	
HWM (m below Top of Curb)				HWM not visible.
Drift (Y/N)	Yes			
Slope Protection			5	
(Type : NATURAL; NATURA	L)			
Guidebank/Spurs			X	
Adequacy of Opening			5	
(Fish Compensation Measure 1	: NONE)			
(Fish Compensation Measure 2	: NONE)			
Channel General Rating		4	5	

Maintenance Recommendations													
Inspector Recommendations	`	Year	Inspecto	or Comments			Department Co	mmen	ts		Target Year	Est. Cost	Cat #
REPAIR/REPLACE BRIDGE RAIL													
PATCH DECK													
REPLACE STRIP DECK													
REPLACE SUB DECK													
STRAIGHTEN/REPLACE MEMBERS													
WASHING													
CORE TIMBER CAPS/CORBELS													
REPAIR/REPLACE TIMBER CAPS													
REPAIR ABUTMENT SCOUR/EROSI	NC												
PLACE ADDITIONAL RIP RAP													
REMOVE DRIFT ACCUMULATION													
INSTALL STRUTS													
OTHER ACTION	2	2012 Repair mud sill at S abut.											
OTHER ACTION													
OTHER ACTION													
OTHER ACTION													
OTHER ACTION													
Structural Condition Rating (Last/No (%)	ow) t	55.0/61.	1	Sufficiency R (%)	ating (Last/	Now) (61.0/79.6	Est	. Repl. Yr	2020	Maint. Red	qd. (Y/N)	Yes
Special Comments for Next Inspection							Department Comments				·		
Maintenance Reviewed By							Date				Estimated Total	0	
Proposed Long-Term Strategy													
On 3-Year Program (Y/N)													
Proposed Action													
		revious Inspector's Name Aime Theroux Previo						s Assistant's Name					
Previous Inspector's Name	Aime Th	neroux				Previous /	Assistant's Name	e					
Previous Inspector's Name Next Inspection Date	Aime Th 29-Aug-						Assistant's Name	e	13-Nov-2002				
								9	13-Nov-2002				