Bridge Inspection															
Bridge File Num	ber	84035 -1 Bridge							Form T	уре		PCS			
Year Built/Year		1958/	/1958	8					Lot No.			4			
Supstr		041.6		. ,					Inspect	or Nam	е	Garry Rober	rts		
Bridge or Town Name CALGARY					DO (	<b></b>	Inspector Class			BR CLS A					
Located Over FISH CREEK, 2.13.31, WATERC					RS-S	51	Assistant Name								
Located On TRAIL-PED, ON 50000 FB							Assistant Class								
Water Body Cl./Year						Inspection Date 01-Oct-2010									
Navigabil. Cl./Year					•		Data Entry By Alyssa Boynton								
Legal Land Location NW SEC 25 TWP 22 RGE 1 W5					VI		Data Entry Date 22-Oct-2010								
Longitude, Latitude -114:00:48, 50:53:58				<b>-</b> \			Review	Reviewer Name Tom Carey							
Road Authority Alberta Transportation (AIT)				1)			Review Date 06-Oct-2010								
Contract Main. A			EFIN	IED CMA	١				Dept. Reviewer Name			Lorenz Bohnert			
Clear Roadway/	Skew	3.8 /							Dept. F	Review D	Date	27-Oct-2010	)		
AADT/Year									Follow-	Up By					
Road Classificat															
Detour Length (R	ĺ	ala				Semi				T				> On Critic	ol Chana
Allowable Load	(1).	igie				Seiiii				Train				> On Critical Spans> Critical Member	
Design Loading:														> Primary	Span
							Po	osting l	nformati	on					
Required Load F		(t)			Single				Se	mi			Truck Train		
Posted Loading	(t)				Single				Se	mi		Tr		k Train	
Posted:	Lane	NE			At Junction (Y/N)			No	In Advance (Y/N)		No		ridge (Y/N)	No	
Posted:	Lane	SE	В		At Junc	tion (Y/	(Y/N) No		In Advance (Y/N)		No	At Bridge (Y/N) No		No	
Remarks		quired													
Hazard Marker A	At Brid	ge (Y/ľ	N)	No											
Remarks				Not requ	<sub>l</sub> uired										
Other Sign Type	S.														
Liette Are I							Ut	ilities (l	Located	at)					
Utility Attachmer	nts														
Telephone	14/ /	DOM.		10: 1 1:					Gas						
Power	vvest	t ROW - multiple lines							Municip		NI-				
Others									Probler	n (Y/N)	No				
Remarks								Annros	oh Boo	J					
							Last		Explanation of Condition						
Horizontal Aligni	ment						5	5		audii U	. Jonal				
Vertical Alignme							5	5	1						
		3.800													
Approach Bump				4	5										
Guardrail (Y/N)							Extend	ed rail a	and T.T.	Planks					
Guardrail (1774)				5	6				-						
Length (m)															
Current Stand	ard (Y/	N)		Yes											
Termination Ty				NONE											
Drainage							7	7							
									-						
Approach Road	Approach Road General Rating					5	5								

					Supers	structure			
Bridge Com	ponent			Last		Explanation of Condition			
(Primary Spa	nn : <b>PE, 2 Spar</b>	ns, Length	s(m): 12.8-12.8	, A-Iden	t Numl	ber: )			
Special Feat	ures								
Special Feat	ure				X				
(Type:)									
Special Feat	ure				Х				
(Type:)									
Wearing Surf	face/Deck Top	Detail Rat	ings						
	N (%)	1 (%)	2 (%)	3 (%)					
Last									
Now	0.0	0.0	0.0	(	0.0				
Wearing Sur	face			4	7	ACP is on top of 50mm concrete overlay			
(Material T	ype : <b>ACP</b> )								
(Thickness	(mm) : <b>50</b> )								
	ection Problem	n No							
(Y/N)									
Deck Top				4	N	Paved over			
Deck Rideab	ility			5	7				
Deck Nideab	шц			3					
Deck Joints				Х	X				
Bump (Y/N	)	No							
Deck Draina	ge			5	6				
Drains Clo		No							
Curbs/Media				5	5	Curb height 100mm to ACP			
(Curb Type	: Standard)					50mm of curb Height @ACP @ SW			
	ercent Area)	0				· ·			
						minor spalls @ curb exteriors			
Bridge Rail				7	7	Many post anchor bolts are welded.			
		BEAM (EX	TIMBER RAILS	i	T	T.T. rails			
Bridge Rail F				5	5	Painted post. Green treated rail			
	ST STEEL)				1	- amea posit e tosti il saltos tan			
	osts Coating			5	5				
(Type : PA	INT)				_				
Sidewalk				X	X				
Girder Detail	Ratings								
Jiidor Botali	N (count)	1 (count)	2 (count)	3 (co.	unt)				
Last	(County	· (ocarr)	_ (553111)	3 (00)	)				
Now	0	0	0		0				
Girders				4	4	Wide cracks and spalls in AZ of curbs.			
	te Inspection D	Date 01-0	Oct-2010			#4 girder @ south span has wide crack in one leg in AZ.			
Cracking (Y/N) Yes						Diagonal wide cracks @ pier end diaphrams at Sp.1 and Sp.2 - G4			
Spalling (Percent Area) 10									
Lift or Connector Pocket Yes Grouted (Y/N)									
(Number Of									
	nent Problems	3							
	Vertical (Y/N) No								
	Horizontal (Y/N) No								
	ure General R			4	4				
						I .			

					ructure					
Bridge Com	ponent			Last	Now	Explanation of Condition				
Abutments										
(Extended	Backwall Pile	es (Y/N) : <b>N</b> )								
(Extended	Backwall Pile	es Spacing(mn	n) : )							
(Total Numb	er of Caps/Co	orbels : : )								
		els Detail Rati	าตร			1				
Boaring Coa	N (count)	1 (count)	2 (count)	3 (cou	ınt)					
Last	(000)	. (666)		(000	<u>,</u>					
Now	0	0	0		0					
Bearing Sea	Bearing Seats/Caps/Corbels				6					
(Type : CC				6						
(Depth(mm										
(Width(mm										
Backwalls/Bi				5 N		Concrete backwall not visible				
Greatest H		1.50		- 14		- State Stat				
Wingwalls	ioigiit (iii)	1.00		5	6					
(Total Numb	er of Bearing	Piles : <b>0:0</b> )			1					
Piles Detail F						1				
	N (count)	1 (count)	2 (count)	3 (cou	unt)	Buried				
Last										
Now	10	0	0		0					
Piles				N	N					
Paint/Coating	g			X	Х					
Abutment St	ability			7	7					
Scour/Erosic	on			7	7					
Piers/Bents										
	ER-SOLID)	arbola · \				+				
	er of Caps/Corb		200			+				
bearing Sea	N (count)	els Detail Ratio		2 (00)	ınt)	1				
Last	iv (count)	1 (count)	2 (count)	3 (cou	arit)	Spall @ top @ u/s - Minor				
Now	10	0	0		0					
	ts/Caps/Corb		J J	5	5	-				
(Type : CC		UI3		- 5	J					
(Depth(mm										
(Width(mm										
	er of Bearing	Piles · n)								
Piles Detail F		1 1100 . <b>U</b> )				1				
i iles Detail f	N (count)	1 (count)	2 (count)	3 (cou	ınt)	Massive Pier				
Last	iv (count)	i (count)	Z (COUTIL)	3 (600	A110)	I Maddive 1 let				
Now	1	0	0		0					
Pier Shaft/Piles				5	6	1				
Greatest Height (m) 3.30					<u> </u>	1				
	Bracing/Struts/Sheathing									
Nose Plate					7					
Paint/Coating	a			5	5					
	(Colour Description : )									
(Colour Co										
(Coloui Co	u <del>c</del> . )				D	a 3 of 5				

				, ,			
			Subst	ructure			
Bridge Component		Last	Now	Explanation of Condition			
Pier Stability		7	7				
Scour		7	6				
Debris (Y/N) No							
Substructure General Rating			5				
		5	Structu	re Usage			
		Last	Now	Explanation of Condition			
Channel							
(U/S Direction : W)				Sharp bend immediately u/s of bridge			
(D/S Direction : E)							
Alignment		4	5				
Bank Stability		4	5	eroded area at NW corner.			
HWM (m below Top of Curb)	2.5			No visible HWM.			
Drift (Y/N)	No						
Slope Protection		5	5	Cl. 1 and 2 and concrete rubble			
(Type : <b>RIP RAP</b> ; <b>RIP RAP</b> )							
Guidebank/Spurs		X	X				
Adequacy of Opening			6				
(Fish Compensation Measure 1	: NONE)						
(Fish Compensation Measure 2	: NONE)						
Channel General Rating		5	5				

		Maintenance Re	commend	ations					
Inspector Recommendations	Year	Inspector Comments		Department Comm	nents		Target Year	Est. Cost	Cat #
REPAIR/REPLACE BRIDGE RAIL									
SEAL CURBS									
PATCH DECK									
OVERLAY DECK									
STRAIGHTEN/REPLACE MEMBERS									
WASHING									
SHOTCRETE REPAIRS									
CORE TIMBER CAPS/CORBELS									
REPAIR/REPLACE TIMBER CAPS									
REPAIR ABUTMENT SCOUR/EROSI	ON								
PLACE ADDITIONAL RIP RAP									
REMOVE DRIFT ACCUMULATION									
INSTALL STRUTS									
OTHER ACTION									
OTHER ACTION									
OTHER ACTION									
OTHER ACTION									
Structural Condition Rating (Last/N (%)	ow) 50.0/50	.0 Sufficiency Rating (Last/N	low) 5	58.7/74.0	Est. Repl. Yr	2025	Maint. Red	qd. (Y/N)	No
Special Comments for Next Inspection	·			Department Comments					
Maintenance Reviewed By				Date		ı	Estimated Total	0	
Proposed Long-Term Strategy									
On 3-Year Program (Y/N)									
Proposed Action									
Previous Inspector's Name	Tom Carey		Previous /	Assistant's Name					
Next Inspection Date	01-Jul-2015		Previous I	Inspection Date	22-Jun-2005				
Inspection Cycle (Default) (months)	57								
Comment									