						:	Bridge li	nspec	tion						
Bridge File Numbe	File Number 84038 -1 Bridge											SG			
Year Built/Year								Lot N	lo.		3				
Supstr								Inspector Name Garry Roberts							
Bridge or Town Na								Inspector Class		BR	BR CLS A				
Located Over	B	OULTO /ATERC	N CREE CRS-ST	Κ, 2.13.5	6.23,			Assistant Name							
Located On		RAIL-PE						Assistant Class							
Water Body Cl./Yea	ar							Inspection Date			06	06-Dec-2011			
Navigabil. Cl./Year								Data Entry By Erir				Erin Roberts			
Legal Land Locatio						1		Data	Data Entry Date 29-Jan-2012						
Longitude, Latitude								Reviewer Name Tom Carey							
Road Authority			ransporta		Γ)			Review Date			21	21-Dec-2011			
Contract Main. Are			NED CMA			Dept. Revie			. Review	er Nam	e Tir	Tim Davies			
Clear Roadway/Sk	ew 3	/				Dept. Review [Date	06	-Feb-2012	2			
AADT/Year								Follo	w-Up By	'					
Road Classification	1														
Detour Length (km)															
Allowable Load (t):	Single	е			Semi				Tr	ain				> On Criti	cal Spans
														>Critical	
Design Loading:								_						> Primary	Span
Demoised Lead Dee	· · · · · · · · · · · · · · · · · · ·			0: 1		Po	osting li	nformation							
Required Load Pos	sting (t))		Single				Semi				Truck Train		+	
Posted Loading (t)		LUD.		Single	04	'A 1\			Semi In Advance (Y/N)				Truck Train		
	ane	NB		At June			No							ridge (Y/N)	No
	ane	SB		At Junc	tion (Y/	IN)	No	1	n Advan	ce (Y/IN) No)	At B	ridge (Y/N)	No
	ot requ		NI-												
Hazard Marker At Bridge (Y/N) No															
Remarks Not required.															
Other Sign Types						114	ilities (l	Locate	nd at)						
Utility Attachments						O.	illues (i	Locate	au at)						
Telephone								Gas							
Power								Municipal							
Others									lem (Y/N	l) No					
Remarks								1 100	10111 (1711	1) 140					
romano							Approa	ach Ro	ad						
					L	ast									
Horizontal Alignme	ent					5	5		Bridge						
Vertical Alignment						5	5								
Roadway Width (m	1)		2.000						_	_					
Approach Bump						5	5								
Guardrail (Y/N)			No					1.8m	length c	of timber	rail	@ NE			
Guardrail				3	3	Bottom plank broken									
Length (m)			1.800						م.سا						
Current Standard	(Y/N)		Yes												
Termination Type	Э		None												
Drainage						7	7								
Approach Road G	enera	I Rating	9			5	5								

						Suners	structure
Bridge Comp	onent					Now	Explanation of Condition
(Primary Spar		ns. Lend	aths(n	n): 14.9. A-ld			
Special Featu		,	,	.,		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
	Special Feature						
(Type:)						X	
Special Featu	re					Х	
(Type:)	10						
Wearing Surfa	oco/Dock Top	Dotail B	atings				
	N (%)	1 (%)	auriys	2 (%)	3 (%)		
Last	IN (/0)	1 (70)		2 (70)	3 (70)		_
Now	100.0	0.0	<u> </u>	0.0		0.0	
		0.0	<u>, </u>	0.0			180mm x 45mm CCA timber.
Wearing Surfa		TED TU	4050	<u> </u>	7	N	180mm x 45mm CCA timber. 14.9m clear span 16.1m out to out longitudinal @ stripdeck.
	pe : UNTREA	IED III	NIBEK)			
(Thickness(ı	mm) : 75)						Snow covered.
Deck Top					X	X	
Deck Rideabil	ity				7	7	
Deck Joints					X	X	
Temperature	e (deg. C)						
(Expansion	Type:)						
(Fixed Type							
Gap Size (m			Gap L	ocation			
	,		1				
							-
							-
							-
							-
Deck Drainage	Δ				7	7	
Drains Clog					,		
					7	7	140mm v 65mm lower roll of heidenroll acts as such
Curb Type					7	7	140mm x 65mm lower rail of bridgerail acts as curb.
(Curb Type		_					-
Scaling (Per	cent Area)	0			_		NATION OF THE PROPERTY OF THE
Bridge Rail					7	6	Mix of treated and untreated material.
(Type:)							-
Bridge Rail Po	osts				7	6	
(Type:)							
Bridge Rail/Po	osts Coating				7	5	
(Type:)							
Sidewalk					X	Х	
Girder/Beam							
Cover Plate					Х	X	2 - 310mm x 205mm I-Beam stringers.
Flange					9	7	40mm sag in stringers.
Web					9	7	
Stiffeners					Х	Х	
Splice					X	Х]
Weld					X	7	Diaphragms are welded.
Diaphragms/C	Cross Frame				8	7	

Superstructure									
Bridge Component		Last	Now	Explanation of Condition					
(Primary Span : RB, 1 Spans, Lo	engths(m): 14.9, A-Ide	nt Nur	nber:)						
Paint Condition		8	6						
(Colour Description : GREEN)									
(Colour Code : 14090)									
Touchup Required (Y/N)	No								
Bearings		8	7	Surface corrosion.					
Temperature (deg. C)	-10								
(Expansion Type : SLIDING PI	LATE)								
(Fixed Type :)									
Coating Adequate (Y/N)	Yes								
Functioning (Y/N)	Yes								
Deck Underside		7	7	185mm x 65mm CCA timber subdeck.					
Stains (Percent Area)	10								
Span Alignment Problems									
Vertical (Y/N)	No								
Horizontal (Y/N)	No								
Superstructure General Rating	j	7	7						
			Cubet						
Bridge Component		Last	Now	Explanation of Condition					
Abutments		Lasi	INOW	Explanation of Condition					
Bearing Seats/Caps		9	8						
(Type : CONCRETE)									
Backwalls/Breastwalls			8						
		9							
Wingwalls		9	8						
Piles			Х						
Paint/Coating		Х	Х						
Abutment Stability		9	8						
Scour/Erosion		7	7						
Piers/Bents									
(Type:)									
Bearing Seats/Caps		Х	Х						
(Type:)									
(Total Number of Bearing Piles :)								
Pier Shaft/Piles		Х	Х						
Bracing/Struts/Sheathing		Х	Х						
Nose Plate			Х						
Paint/Coating		Х	X						
(Colour Description :)									
(Colour Code :)									
Pier Stability		Х	X						
Scour		N	X						
Debris (Y/N)	No								
Substructure General Rating		9	8						

Structure Usage										
				Explanation of Condition						
Channel										
(U/S Direction : E)			On curve.							
(D/S Direction : W)										
Alignment		6	6							
Bank Stability		8	8							
HWM (m below Top of Curb)	VM (m below Top of Curb)			No visible HWM						
Drift (Y/N)	No									
Slope Protection			7							
(Type: RIP RAP; RIP RAP)										
Guidebank/Spurs		X	X							
Adequacy of Opening		9	7							
(Fish Compensation Measure 1 :	NONE)									
(Fish Compensation Measure 2 :	NONE)									
Channel General Rating		7								

84038 -1 Bridge

Maintenance Recommendations												
Inspector Recommendations		Year Inspector Comments				Department Comm	nents		Target Year	Est. Cost	Cat #	
REPAIR/REPLACE BRIDGE RAIL						·						
GALVANIZE/PAINT BRIDGE RAIL												
RETROFIT BRIDGE RAIL												
SEAL CURBS												
PATCH DECK												
SEAL DECK												
OVERLAY DECK												
REPAIR/REPLACE DECK JOINTS												
RESET/ PAINT BEARINGS												
REPAINT SUPERSTRUCTURE												
STRAIGHTEN/REPLACE MEMBERS												
WASHING												
SHOTCRETE REPAIRS												
REPAIR ABUTMENT SCOUR/EROSIG	ON											
PLACE ADDITIONAL RIP RAP												
REMOVE DRIFT ACCUMULATION												
OTHER ACTION	2	2012 Replace one timber rail @ NE - 140 x 65 x 1800mm CCA Timber										
OTHER ACTION												
OTHER ACTION												
OTHER ACTION												
Structural Condition Rating (Last/No. (%)	ow)	88.9/83.3		Sufficiency Rating (Last/Now) (%)		91.5/88.4	Est. Repl. Yr	2030	Maint. Red	qd. (Y/N)	Yes	
Special Comments for Next Inspection						Department Comments						
Maintenance Reviewed By						Date		E	Estimated Total	0		
Proposed Long-Term Strategy												
On 3-Year Program (Y/N)												
Proposed Action												
Previous Inspector's Name Tom (arey			Previous	s Assistant's Name						
Next Inspection Date	06-Sep-	-2016			Previous	s Inspection Date 29-Oct-2008						
Inspection Cycle (Default) (months)	57					•	1					
Comment												