Bridge Inspection																
Bridge File Number 84063 -1 Bridge			<b>J</b>				Form Type			SG						
Year Built/Year Supstr	1988						No.	_		4						
Bridge or Town Name CANMORE									Inspector Name			Garry Roberts				
Located Over LOCAL ROAD									Inspector Class			BR CLS A				
Located On TRAIL-PED, ON 50000 PS					-			Assistant Name								
Water Body Cl./Year									Assistant Class							
•									Inspection Date			20-Jul-2012				
Navigabil. Cl./Year					1 \//5\/	1		Data Entry By			Kelsey Roberts					
Legal Land Location SE SEC 1 TWP 25 RGE 11 W5N					1 44314	1		Data Entry Date			31-Aug-2012					
Longitude, Latitude -115:24:05, 51:06:15					Τ\			Reviewer Name			Tom Carey					
Road Authority Alberta Transportation (Al Contract Main. Area UNDEFINED CMA					AII)			Rev	Review Date			27-Jul-2012				
			INED CIVIA	1				Dep	ot. Revi	ewer I	Name	Tim Davies				
Clear Roadway/	Skew	4.6 /							ot. Revi	ew Da	ite	06-Sep-2012				
AADT/Year	:							Foll	low-Up	Ву						
Road Classificat																
Detour Length (		1 -			0	.							0 01-1	0.0%.10		
Allowable Load (	t): Sin	gie		Semi					Train			> (		> On Critic	> On Critical Spans >Critical Member	
Design Loading:												> Primary Spa				
0 0						Ро	sting l	nforr	nation					,		
Required Vert. C	learan	ce Postir	ıg (m)				Ţ									
Posted Vertical (				No												
	NB					In Advance (			Lane SB O		n Bridge (m)		In Advance (Y/N)			
Remarks	Not re		<u> </u>			,	, ,					3 ( 7)			7	
Required Load F				Single					Semi			Truck Train				
Posted Loading		( )		Single					Semi			Truck Train				
Posted:							No			dvance (Y/N)		No			No	
Posted:	Lane						No	In Advance (Y/N)			` ,	No			No	
Remarks Not req.					11011 (17	,,,,	-10		mina	41100	(1714)	110	, D.	lago (1/11)	110	
			No													
Hazard Marker At Bridge (Y/N) No  Remarks Not req.																
Other Sign Types																
Outlot Olgit Typo						Uti	ilities (l	oca	ted at)							
Utility Attachmer	nts															
Telephone								Gas								
Power											r pipes NW & SE					
Others	Liaht s	standards	NW & S	E					blem (Y					<u>-</u>		
Remarks	J (								(1							
							Approa	ch R	oad							
						Last	Now	Explanation of Condition								
Horizontal Aligni	ment					5	5	1	NC20							
Vertical Alignme						5	5									
Roadway Width (m) 4.600																
Approach Bump						7	5	1								
Guardrail (Y/N) Yes								CC	CCA Timber rail							
Guardrail					Χ	7	30/ Timborian									
Length (m) 5.000																
Current Standard (Y/N) Yes																
Termination Type End Post																
Drainage						7	7									
Approach Road	l Gene	ral Ratin	g			5	5									

						Superstructure							
			Last	Now	Explanation of Condition								
(Primary Spa	n : <b>RB, 3 Spa</b>	ns, Lengtl	hs(n	n): 4.9-14.9-5	A-Ide	nt Num	ber: )						
Special Feat	ures												
Special Feat	ure					X							
(Type:)													
Special Feature						X							
(Type:)													
Wearing Surface/Deck Top Detail Ratings													
				3 (%)									
Last	0	0		0		0							
Now	0.0	0.0		0.0	(	0.0							
Wearing Surface (Material Type : COPPER CHROMATE ARSENATE T TIMBER; UNTREATED TIMBER)					6 TREAT	7 <b>TED</b>	75x250 CCA						
(Thickness	(mm) : <b>/5</b> )					Τ.							
Deck Top					6	7							
Deck Rideab	ility				Х	7							
Deck Joints					Х	Х							
Temperatu	re (deg. C)												
(Expansion	Type:)												
(Fixed Type	e:)												
Gap Size (r	mm)	Ga	ap L	ocation									
Deck Drainag	ge				7	Х							
Drains Clog													
Curbs/Media	n				Х	X							
	: Standard)												
Scaling (Pe													
Bridge Rail					7	7							
	EATED TIMBI	ER BRIDG	E S	OLID BEAM (									
Bridge Rail P	osts				7	7							
	EATED TIMBI	ER:TREAT	ΓED	TIMBER)			5% failed						
Bridge Rail/P		,			5	5							
					0								
(Type : <b>PAINT</b> ) Sidewalk					Х	X							
Girder/Beam													
Cover Plate					X	X							
	<del>-</del>				9	8							
Flange						8	-						
Web Stiffeners					9 X		-						
						X	-						
Splice					X	X	-						
Weld	Onese F:				X	8							
Diaphragms/Cross Frame					9	8							

			Supers	tructure
Bridge Component		Last	Now	Explanation of Condition
(Primary Span: RB, 3 Spans, Le	engths(m): 4.9-14.9-5,	A-Ider	nt Num	ber: )
Paint Condition		8	7	
(Colour Description : BROWN)				
(Colour Code : <b>30252</b> ;)				
Touchup Required (Y/N)	No			
Bearings		N	N	too high to see
Temperature (deg. C)				
(Expansion Type : REINFORC TEFLON AND STAINLESS ST	ED NEOPRENE BEAR ΓΕΕL)	ING W	/ITH	
(Fixed Type : REINFORCED N TEFLON AND STAINLESS ST		WITH		
Coating Adequate (Y/N)				
Functioning (Y/N)				
Deck Underside		8	8	150x150 CCA Timber
Stains (Percent Area)	2			
Span Alignment Problems				
Vertical (Y/N)	No			
Horizontal (Y/N)	No			
Superstructure General Rating		8	8	
			Subst	ructure
Bridge Component		Last	Now	Explanation of Condition
Abutments				
Bearing Seats/Caps		N	N	
(Type : TREATED TIMBER)				
Backwalls/Breastwalls		8	8	150x150 CCA Timber Crib
Wingwalls		8	8	150x150 CCA Timber Crib
Piles		N	N	
Paint/Coating		Х	Х	
Abutment Stability		8	8	
Scour/Erosion		8	8	
Piers/Bents				
(Type : PIER-COLUMN)				
Bearing Seats/Caps		Х	X	
(Type : TREATED TIMBER)				
(Total Number of Bearing Piles :	0:0)			
Pier Shaft/Piles	,	Х	X	
Bracing/Struts/Sheathing		Х	Х	
Nose Plate		Х	Х	
Paint/Coating		X	X	
(Colour Description : )			,,	
(Colour Code : )				
Pier Stability		Х	X	
Scour		Х	X	
Debris (Y/N)	No			

Substructure										
Last	Now	Explanation of Condition								
8	8									
	a Hoose									
	Explanation of Condition									
Last	Explanation of Condition									
8	7									
X	X									
	Ι Λ									
8	7									
8	7									
8	7									
8	7									
	8 Last 8 X 8 8 8	Last   Now								

84063 -1 Bridge

Maintenance Recommendations												
Inspector Recommendations		Year	Inspector Comments		Department Commo	Target Year	Est. Cost	Cat #				
REPAIR/REPLACE BRIDGE RAIL												
GALVANIZE/PAINT BRIDGE RAIL												
RETROFIT BRIDGE RAIL												
SEAL CURBS												
PATCH DECK												
SEAL DECK												
OVERLAY DECK												
REPAIR/REPLACE DECK JOINTS												
RESET/ PAINT BEARINGS												
REPAINT SUPERSTRUCTURE												
STRAIGHTEN/REPLACE MEMBERS												
WASHING												
SHOTCRETE REPAIRS												
REPAIR ABUTMENT SCOUR/EROSI	NC											
PLACE ADDITIONAL RIP RAP												
REMOVE DRIFT ACCUMULATION												
OTHER ACTION												
OTHER ACTION												
OTHER ACTION												
OTHER ACTION												
Structural Condition Rating (Last/No. (%)	ow)	88.9/88.9	Sufficiency Rating (Last/N	Now)	88.0	Est. Repl. Yr	2045	Maint. Red	qd. (Y/N)	No		
Special Comments for Next Inspection					Department Comments							
Maintenance Reviewed By					Date		E	Estimated Total	0			
Proposed Long-Term Strategy												
On 3-Year Program (Y/N)												
Proposed Action												
Previous Inspector's Name Tom C		arey		Previous A	Assistant's Name							
Next Inspection Date 20-Ap		·2017		Previous	Inspection Date 18-Jul-2007							
Inspection Cycle (Default) (months) 57												
Comment												