Bridge Inspection																	
Bridge File Numl	mber 84064 -1 Bridge								Form Type		SG						
Year Built/Year		1988/1988							\rightarrow	Lot No.			4				
Supstr										Inspector Name			Garry Roberts				
Bridge or Town Name CANMORE									Inspector Class			BR CLS A					
Located Over LOCAL ROAD									Assistant Name								
Located On TRAIL-PED, ON 50000 PS								As	Assistant Class								
Water Body Cl./Year									Inspection Date			20-Jul-2012					
Navigabil. Cl./Year									Data Entry By			Kelsey Roberts					
Legal Land Location SE SEC 1 TWP 25 RGE 11 W5M					М			Data Entry Date			31-Aug-2012						
Longitude, Latitude -115:23:58, 51:06:12								Reviewer Name			Tom Carey						
Road Authority		Alb	erta Tra	ansporta	ation (Al	T)				Review Date			27-Jul-2012				
Contract Main. A	rea	UNI	DEFINE	ED CMA	4				De	ept. Revi	ewer	Name	Tim Davies				
Clear Roadway/S	Skew	4.6	/							ept. Revi			06-Sep-2012)			
AADT/Year										ollow-Up			CC CC	-			
Road Classificat	ion								╝``	л.он ор	_,						
Detour Length (k	m)																
Allowable Load (t): Sir	ngle				Sem	i			Train				> On Critical Spans			ns
5															>Critical I		
Design Loading:															> Primary	Span	
De avrine d Vent. C	M	г) ti	()			Po	sting	into	rmation							
Required Vert. C				(m)													
Posted Vertical C			` ′		No			() (() I)	١		0.0		D :: ()			0.74	I
Posted: Lane NB On Bridge (m) In Adva							ance	(Y/N)	No	Lane	SB	0	n Bridge (m)		In Advance	e (Y/N)	No
	Not R																
Required Load F		j (t)			Single					Semi			Truck Train				
Posted Loading (t)				Single					Semi			Truck Train					
Posted:	Lane	NB At Junction (-			In Advance (Y/N)		No	At Bridge (Y/N)		No					
	Lane		SB		At June	ction (\	(/N)	No		In Adv	ance	(Y/N)	No	At Br	idge (Y/N)	No	
Remarks Not Req.																	
Hazard Marker At Bridge (Y/N) No																	
Remarks Not Req.																	
Other Sign Types																	
							Ut	ilities	Loc	ated at)							
Utility Attachmen	nts											l					
Telephone									G								
Power										Municipal Water pipes @ N\			pipes @ NW	& NE			
Others	Light	stan	dards @	2 North					Pr	Problem (Y/N) No							
Remarks																	
								Approach Road									
Llavia a stat All							Last	Now	\neg	Explanation of Condition							
Horizontal Alignr							5	5	\dashv N	NC21							
Vertical Alignment					5	5	+										
Roadway Width (m) 4.000					_	T _	G	Gravel path									
Approach Bump					7	5	+-										
Guardrail (Y/N) Yes					C	CCA Timber rail											
Guardrail			Х	7	+												
Length (m) 4.500																	
Current Standard (Y/N) Yes																	
Termination Ty	/ре			End Po	st												
Drainage							7	7									
Approach Road	l Gene	eral F	Rating				5	5									

							tructure
Bridge Comp					Last		Explanation of Condition
	n : RB, 3 Spa ı	ns, Len	gths(n	n): 4.4-14.8-4	.4, A-Id	ent Nu	mber:)
Special Feat	ures						
Special Featu	ıre					X	
(Type:)							
Special Featu	ıre					X	
(Type :)							
Wearing Surfa	ace/Deck Top	Detail F	Ratings	3			
	N (%)	1 (%)		2 (%)	3 (%)		
Last	0	()	0		0	
Now	w 0.0 0.0 0.0					0.0	
Wearing Surface (Material Type : COPPER CHROMATE ARSENATE TIMBER)					6 TREAT	6 FED	
(Thickness)	mm) : 50)						
Deck Top					6	6	
Deck Rideabi	lity				7	7	
Deck Joints					Х	Х	
Temperatur	e (deg. C)						
(Expansion	Type:)						
(Fixed Type	e:)						
Gap Size (r	nm)		Gap L	ocation			
Deck Drainag	je				Х	Х	
Drains Clog	ged (Y/N)						
Curbs/Mediar	า				Х	X	
(Curb Type	: Standard)				·		
Scaling (Pe	rcent Area)						
Bridge Rail					7	7	
(Type : TRE	EATED TIMBE	ER BRID BEAM (OGE S	OLID BEAM (MBER RAILS	EX. TII	MBER	
Bridge Rail P	osts				7	7	
(Type : TRE	EATED TIMBE	ER)			·		5% failed
Bridge Rail/P					5	5	- 070 Tanou
(Type : PAI							
Sidewalk	•				Х	Х	
Girder/Beam							
Cover Plate					Х	Х	
Flange					9	8	
Web					9	8	
Stiffeners					Х	Х	
Splice					Х	Х	
Weld					Х	8	
Diaphragms/0	Cross Frame				9	8	
J							

Superstructure									
Bridge Component		1		Explanation of Condition					
(Primary Span : RB, 3 Spans, L	engths(m): 4.4-14.8-4.								
Paint Condition	<u> </u>	8	7						
(Colour Description : BROWN)								
(Colour Code : 30252)									
Touchup Required (Y/N)	No								
Bearings		N	N	too high to see					
Temperature (deg. C)									
(Expansion Type :)									
(Fixed Type :)									
Coating Adequate (Y/N)									
Functioning (Y/N)									
Deck Underside		8	8	150x150 CCA Timber					
Stains (Percent Area)	5								
Span Alignment Problems									
Vertical (Y/N)	No								
Horizontal (Y/N)	No								
Superstructure General Rating	9	8	8						
Bridge Component		Last	Now	Explanation of Condition					
Abutments		Lasi	INOW	Explanation of Condition					
Bearing Seats/Caps		N	N						
(Type : TREATED TIMBER)		- 11	- 14						
Backwalls/Breastwalls		8	8	150x150 CCA Timber cribbing					
Daditialio, Broadtivalio				TOOK TOO CON THIRDS CHESTING					
Wingwalls		8	8	150x150 CCA Timber cribbing					
Piles		N	N						
T iled			I IN						
Paint/Coating		Х	Х						
Abutment Stability		8	8						
Scour/Erosion		8	8						
Piers/Bents									
(Type : PIER-COLUMN)									
Bearing Seats/Caps		Х	X						
(Type:)									
(Total Number of Bearing Piles :	0:0)		Ι						
Pier Shaft/Piles		X	X						
Bracing/Struts/Sheathing		X	X						
Nose Plate		Х	X						
Paint/Coating		X	X						
(Colour Description :)									
(Colour Code :)		Х							
Pier Stability			X						
Scour		Х	X						
Debris (Y/N)	No								
Substructure General Rating		8	8						

Structure Usage									
	Last	Now	Explanation of Condition						
Grade Separation		_							
Road Alignment	8	7							
Traffic Safety Features	X	X							
Туре		_							
Slope Protection		7							
(Type: NATURAL)									
Bank Stability	6	7							
Drainage	7	7							
Grade Separation General Rating	8	7							

84064 -1 Bridge

Bridge Inspection & Maintenance System (Web 2005)

			Maintenance F	Recommend	lations					
Inspector Recommendations	Y	Year Inspector Comments			Department Comme		Target Year	Est. Cost	Cat #	
REPAIR/REPLACE BRIDGE RAIL					·					
GALVANIZE/PAINT BRIDGE RAIL										
RETROFIT BRIDGE RAIL										
SEAL CURBS										
PATCH DECK										
SEAL DECK										
OVERLAY DECK										
REPAIR/REPLACE DECK JOINTS										
RESET/ PAINT BEARINGS										
REPAINT SUPERSTRUCTURE										
STRAIGHTEN/REPLACE MEMBERS										
WASHING										
SHOTCRETE REPAIRS										
REPAIR ABUTMENT SCOUR/EROSIG	NC									
PLACE ADDITIONAL RIP RAP										
REMOVE DRIFT ACCUMULATION										
OTHER ACTION										
OTHER ACTION										
OTHER ACTION										
OTHER ACTION										
Structural Condition Rating (Last/No (%)	ow) 8	8.9/88.9	Sufficiency Rating (Las	t/Now)	/88.0 E	st. Repl. Yr	2045	Maint. Red	qd. (Y/N)	No
Special Comments for Next Inspection					Department Comments					
Maintenance Reviewed By					Date		E	Estimated Total	0	
Proposed Long-Term Strategy										
On 3-Year Program (Y/N)										
Proposed Action										
Previous Inspector's Name Tom C		rey		Previous	s Assistant's Name					
Next Inspection Date 20-Apr				Previous	s Inspection Date 18-Jul-2007					
	57									
Comment										