Bridge Inspection																
Bridge File Number 85020 E-1 Bridge								Form Type			CON					
Year Built/Year 2006/2006							Lot No.				3					
Supstr					· -			Insp	Inspector Name			Wade Nanninga				
Bridge or Town Name ANTHONY HENDAY DRIVE						/ATEDODO			Inspector Class			BR CLS A				
Located Over BLACKMUD CREEK, 6.95.2, ST					o.2, WA	VATERCES-			Assistant Name							
Located On		216:06	L1 1.523						Assistant Class							
Water Body Cl./	Year							Inspection Date			27-Feb-2013					
Navigabil. Cl./Year								, ,				Theresa Lacusta				
Legal Land Location NW SEC 29 TWP 5					24 W4	Data Entry Date			19-Mar-2013							
Longitude, Latitude -113:30:46, 53:26:05								Reviewer Name			Eric Carcoux					
Road Authority		Alberta	Transport	ation (Al	T)			Rev	iew Dat	е		14-Mar-2013	3			
Contract Main. A	rea	ANTHO	NY HEND	AY DRI	٧E							Brent Herric				
Clear Roadway/	Skew	18.7 /							t. Revie		е	20-Mar-2013	3			
AADT/Year		51,020	/ 2011 (A)					Follo	Follow-Up By							
Road Classificat	ion	RFD-41	2.4-110													
Detour Length (F	(m)	1														
Allowable Load ((t): Sin	ngle CS	1 28		Semi	C	S2 49			Train		CS3 62		> On Critical Spans> Critical Member		
Design Loading:																
Design Loading.						D	osting I	nforn	nation					> Primary	Span	
Required Load Posting (t) Single							Janing I		Semi			Truck Train				
Posted Loading		()		Single	•				Semi					ruck Train		
Posted:	Lane	WB			tion (Y/	V/NI)				Advance (Y/N)				At Bridge (Y/N)		
Posted:	Lane	EB			tion (Y/					Ivance (Y/N)		No		ridge (Y/N)	No	
Remarks		equired.		7 tt Garre	7.1011 (171	• • •	1110		minare	.,, 00, (,	,,,,	110	,	lago (1/11)	110	
Hazard Marker At Bridge (Y/N) Yes																
Remarks	w Dila;	90 (1711)	1.00													
Other Sign Type																
3 71						Ut	tilities (Locat	ted at)							
Utility Attachmer	nts															
Telephone							Gas									
Power	Street	t lighting							Municipal							
Others									Problem (Y/N) No							
Remarks	Munic	cipal utilit	ies througl	nout area	a.											
							Approa	pach Road								
					L	.ast			Explanation of Condition							
Horizontal Aligni						8	8	Slig	Slight curves (H & V) West.							
Vertical Alignme						8	8		-							
Roadway Width (m) 18.700						Wid	Wide cracks in ACP at approachs.									
Approach Bump				6	6											
Guardrail (Y/N) Yes																
Guardrail				9	8											
Length (m) 84.000																
Current Standard (Y/N) Yes																
Termination Ty	pe		Turned	Down				N 4 - '	ority - f		!!	v ot NIT en - 1	,,,;4l-	onorcia		
Drainage						5	5	iviaj	ority of e	erosior	ı gull	y at NE filled	with C	oncrete.		
Approach Road General Rating						8	8									

Superstructure											
Bridge Com	ponent			Last		Explanation of Condition					
(Primary Spa	(Primary Span : CA, 3 Spans, Lengths(m): 16.5-41.6-16.5, A-Ident Number:)										
Special Feat	tures										
Special Feat	ure				X						
(Type:)											
Special Feat	ure				Х						
(Type:)											
	face/Deck Top	Detail Ratings	<u> </u>								
9	N (%)	1 (%)	2 (%)	3 (%)							
Last											
Now											
Wearing Surf	Wearing Surface					Transverse and longitudinal cracks in ACP.					
(Material T											
(Thickness											
Deck Top	,,			N	N						
Dook 10p				.,	.,						
Deck Rideab	ility			9	9						
Deck Joints				X	X	Integral abutments and piers.					
Temperatu	re (deg. C)	-5				integral abutificities and piers.					
(Expansion											
(Fixed Type											
Gap Size (Gan I	ocation								
Gap Size (i	111111)	Gap L	ocation								
Deck Drainage				9	9	No drains.					
Drains Clogged (Y/N) No						ino dianis.					
Curbs/Median				9	9						
				9	9						
	(Curb Type : Standard) Scaling (Percent Area) 0										
	ercent Area)	0		0							
Bridge Rail	LVANIZED CT	TEL BRIDGE	TUDE	9	9						
` • •	LVANIZED ST	EEL BRIDGE	IUBE)								
Bridge Rail P		OT OTES! 0	41.\/4.\UZED	9	9						
STEEL)	LVANIZED PO	OSI SIEEL;G	ALVANIZED	POST							
Bridge Rail/P	Posts Coating			9	8						
	LVANIZED)										
Sidewalk	,			Х	Х						
Girders				9	9	Box section.					
Diaphragms/	Cross Frame			X	X						
Diaprilagins/	CIOOS I IAIIIC										
Bearings				N	N	20mm thick.					
Temperatu	re (deg. C)	-5									
(Expansion	Type : REINF	ORCED PAD	BEARING)								
(Fixed Type :)											
Coating Adequate (Y/N) Yes											
Functioning (Y/N) Yes											
Deck Underside				9	9						
Stains (Per	Stains (Percent Area) 0										
1	nent Problems	3									
Vertical (Y/N) No											
Horizontal	· ·	No									

				tructure
Bridge Component				Explanation of Condition
(Primary Span : CA, 3 Spans, L	engths(m): 16.5-41.6-1	16.5, A	-Ident I	Number:)
Superstructure General Rating	g	9	9	
			Subst	ructure
Bridge Component		Last	Now	Explanation of Condition
Abutments			1	
Bearing Seats		9	9	
Backwalls/Breastwalls		9	9	
Wingwalls		9	7	Stained @ all corners.
Piles		N	8	Diagonal conc. supports - random narrow diagonal cracks
Paint/Coating		X	8	
Abutment Stability		9	9	
·				
Scour/Erosion		9	7	steep headslopes.
Piers/Bents				
(Type : PIER-COLUMN)				
Bearing Seats/Caps		7	9	
(Type : CONCRETE)				
Pier Shaft/Piles		9	7	Arch with concrete walls supporting box girders. Hairline map cracking on a few of the vertical members.
Nose Plate		Х	Х	
Paint/Coating		Х	X	
(Colour Description :)				
(Colour Code :)		1	1	
Pier Stability		9	9	
Scour		9	N	
Debris (Y/N)	No			
Substructure General Rating		7	7	
		5	Structu	re Usage
			Now	Explanation of Condition
Channel	<u>'</u>			
(U/S Direction : S)				
(D/S Direction : N)				
Alignment		8	8	
Bank Stability			8	
HWM (m below Top of Curb)				HWM not visible.
Drift (Y/N)	No			
Slope Protection		9	7	Riprap at creek level, granular at mid level, upper bank mulch.
(Type : RIP RAP; RIP RAP)				
Guidebank/Spurs		X	X	
Adequacy of Opening		9	9	
(Fish Compensation Measure 1	: NONE)			
(Fish Compensation Measure 2	· NONE)			

Structure Usage									
	Last	Now	Explanation of Condition						
Channel General Rating	8	7							

85020 E-1 Bridge

					Maint	tenance Reco	mmend	ations						
Inspector Recommendations			Year Inspector Comments					Department Co	mmen		Target Year	Est. Cost	Cat #	
REPAIR/REPLACE BRIDGE RAIL														
GALVANIZE/PAINT BRIDGE RAIL														
RETROFIT BRID	GE RAIL													
SEAL CURBS														
PATCH DECK			2013 Seal cracks in ACP over deck and a approaches.											
SEAL DECK														
OVERLAY DECK														
REPAIR/REPLAC	E DECK JOINTS													
RESET/ PAINT BEARINGS														
WASHING														
SHOTCRETE RE	PAIRS													
REPAIR ABUTME	NT SCOUR/EROSI	ON												
PLACE ADDITION	NAL RIP RAP													
REMOVE DRIFT ACCUMULATION														
OTHER ACTION														
OTHER ACTION														
OTHER ACTION														
OTHER ACTION														
Structural Condition Rating (Last/Now) (%)			88.9/88.	9	Sufficiency Rat	ting (Last/Nov	w) 7	78.8/77.1	Esf	t. Repl. Yr	2080	Maint. Red	qd. (Y/N)	Yes
Special Monitor erosion at NE. Comments for Next Inspection								Department Comments						
Maintenance Rev	iewed By							Date				Estimated Total	0	
Proposed Long-Term Strategy														
On 3-Year Program (Y/N)														
Proposed Action														
Previous Inspector's Name Kris		Kris Bo	sters			Pr	revious /	vious Assistant's Name						
Next Inspection D	ate	27-Nov	-2014			Pi	revious I	nspection Date		29-Apr-2011				
		21												
Comment														