

| Bridge Culvert Inspection | | | | |
|---------------------------|--|--|---------------------|-----------------|
| Bridge File Number | 85120 -1 Bridge Culvert | | Form Type | CUL1 |
| Year Built | 2007 | | Lot No. | 4 |
| Bridge or Town Name | MILL CREEK CULVERT LOCATED UNDER CNR NEAR EDMONTON | | Inspector Name | Wade Nanninga |
| Located Over | OLDMAN CREEK, 6.74, WATERCRS-ST | | Inspector Class | BR CLS A |
| Located On | CNR AND MILL CREEK | | Assistant Name | |
| Water Body Cl./Year | | | Assistant Class | |
| Navigabil. Cl./Year | | | Inspection Date | 28-Feb-2013 |
| Legal Land Location | NW SEC 33 TWP 51 RGE 23 W4M | | Data Entry By | Theresa Lacusta |
| Longitude, Latitude | -113:20:18, 53:27:04 | | Data Entry Date | 13-Mar-2013 |
| Road Authority | AREL | | Reviewer Name | Eric Carcoux |
| Contract Main. Area | ANTHONY HENDAY DRIVE | | Review Date | 13-Mar-2013 |
| Clear Roadway/Skew | | | Dept. Reviewer Name | Eric Carcoux |
| AADT/Year | | | Dept. Review Date | 22-Mar-2013 |
| Road Classification | | | Follow-Up By | |
| Detour Length (km) | | | | |

| Bridge Culvert Information | | | | | | | | |
|----------------------------|--------|------|----------------|------|--------|---------------|--------------------|-------|
| Number of Culverts | | 1 | | | | | | |
| Pipe # | Barrel | Span | Rise (or Dia.) | Type | Length | Corr. Profile | Pl./Slab Thickness | Shape |
| 1 | MAIN | - | 2400 | CP | 34.3 | | 225.0 | ROUND |
| Special Features | | | | | | | | |
| Special Features Comment | | | | | | | | |

| Utilities (Located at) | | | |
|------------------------|--------------------------|---------------|----|
| Utility Attachments | | | |
| Telephone | | Gas | |
| Power | | Municipal | |
| Others | CN communications cable. | Problem (Y/N) | No |
| Remarks | | | |

| Approach Road / Embankment | | | | |
|--|-----|----------|----------|--------------------------|
| | | Last | Now | Explanation of Condition |
| Horizontal Alignment | | 9 | 9 | Railway track. |
| Vertical Alignment | | 9 | 9 | |
| Roadway Width (m) | | | | |
| Embankment | | 8 | 8 | |
| Sideslope (__:1) | 3.0 | | | |
| (Height of Cover(m) : 3.3) | | | | |
| Guardrail (Y/N) | No | | | |
| Approach Road / Embankment General Rating | | 8 | 9 | |

| Upstream End | | | | |
|---|----------|------|-----|--------------------------|
| Culvert Component | | Last | Now | Explanation of Condition |
| Direction | | E | | |
| End Treatment (Concrete, Steel, Others, None) | CONCRETE | | | |
| Headwall | | X | X | |
| Collar | | X | X | |
| Wingwalls | | X | X | |
| (Shape :) | | | | |
| Cutoff Wall | | X | X | |

| Upstream End | | | | |
|---|-------------|----------|----------|--|
| Culvert Component | | Last | Now | Explanation of Condition |
| Bevel End | | 8 | 8 | |
| Heaving (mm) | 0 | | | |
| Invert Above/Below Stream Bed | BELOW | | | |
| Above/Below (mm) | 600 | | | |
| Scour Protection | | 8 | 8 | |
| (Type : RIP RAP) | | | | |
| (Avg. Rock Size(mm) : 500) | | | | |
| Scour/Erosion | | 8 | 8 | |
| Beavers (Y/N) | No | | | |
| Upstream End General Rating | | 8 | 8 | |
| Bridge Culvert Barrel | | | | |
| Culvert Component | | Last | Now | Explanation of Condition |
| (Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2400, Type: CP) | | | | |
| Barrel Last Accessible Date | 28-Feb-2013 | | | Ice/Water 1.2m deep. Shape and condition look very good. |
| Special Features | | | | |
| Special Feature | | | | |
| (Type :) | | | | |
| Special Feature | | | | |
| (Type :) | | | | |
| Roof | | 9 | 8 | |
| Measured Rise (mm) | | | | |
| Measured At Ring No. | | | | |
| Sag (mm) | | | | |
| Percent Sag | | | | |
| Sidewall | | 9 | 8 | |
| Measured Span (mm) | 2435 | | | |
| Measured At Ring No. | 5 | | | |
| Deflection (mm) | 35 | | | |
| Percent Deflection | 2 | | | |
| Floor | | N | N | |
| Bulge (mm) | | | | |
| Measured At Ring No. | | | | |
| Abrasion (Y/N) | | | | |
| Circumferential Seams | | N | 6 | Grout in joints is loose and broken.-no problem |
| Separation (mm) | 20 | | | |
| Longitudinal Seams | | X | X | |
| Total No. of Cracked Rings | | | | |
| Total No. of Rings with Two Cracked Seams | | | | |
| Min. Remaining Steel Between Cracks (mm) | | | | |
| Proper Lap (Y/N) | | | | |
| Longitudinal Stagger (Y/N) | | | | |
| Coating | | X | X | |
| Corrosion By Soil (Y/N) | | | | |
| Corrosion By Water (Y/N) | | | | |
| Camber POS/ZERO/NEG | ZERO | | | |
| Ponding (Y/N) | No | | | |

| Bridge Culvert Barrel | | | | |
|---|----------|----------|----------|------------------------------------|
| Culvert Component | | Last | Now | Explanation of Condition |
| (Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2400, Type: CP) | | | | |
| Fish Passage Adequacy | | 5 | 7 | |
| Baffle | | X | X | |
| (Type :) | | | | |
| Waterway Adequacy | | 8 | 8 | |
| Icing (Y/N) | No | | | |
| Silting (Y/N) | No | | | |
| Drift (Y/N) | No | | | |
| Barrel General Rating | | N | 8 | |
| Downstream End | | | | |
| Culvert Component | | Last | Now | Explanation of Condition |
| Direction | | W | | |
| End Treatment (Concrete, Steel, Others, None) | CONCRETE | | | |
| Headwall | | X | X | |
| Collar | | X | X | |
| Wingwalls | | X | X | |
| (Shape :) | | | | |
| Cutoff Wall | | X | X | |
| Bevel End | | 8 | 8 | |
| Heaving (mm) | 0 | | | |
| Invert Above/Below Stream Bed | BELOW | | | |
| Above/Below (mm) | 600 | | | |
| Scour Protection | | 8 | 8 | |
| (Type : RIP RAP) | | | | |
| (Avg. Rock Size(mm) : 500) | | | | |
| Scour/Erosion | | 8 | 8 | |
| Beavers (Y/N) | No | | | |
| Downstream End General Rating | | 8 | 8 | |
| Structure Usage | | | | |
| | | Last | Now | Explanation of Condition |
| Channel (U/S and D/S) | | | | |
| Alignment | | 7 | 6 | 90 degrees east end. Gentle curve. |
| Bank Stability | | 8 | 8 | |
| HWM (m below Top of Culvert) | | | | HWM not visible. |
| Drift (Y/N) | No | | | |
| Channel Bottom Degrading/Aggrading | | | | |
| Beavers (Y/N) | No | | | |
| (Fish Compensation Measure 1 : NONE) | | | | |
| (Fish Compensation Measure 2 : NONE) | | | | |
| Channel General Rating | | 7 | 6 | |

| Maintenance Recommendations | | | | | | | |
|---|------------------|--|---------------------------|---------------|-----------------|-------------------|----|
| Inspector Recommendations | Year | Inspector Comments | Department Comments | Target Year | Est. Cost | Cat # | |
| SHOTCRETE REPAIRS | | | | | | | |
| PLACE ADDITIONAL RIP RAP | | | | | | | |
| REMOVE DRIFT ACCUMULATION | | | | | | | |
| INSTALL CONCRETE/STEEL LINING | | | | | | | |
| INSTALL STRUTS | | | | | | | |
| INSTALL CONCRETE COLLAR/CUTOFF | | | | | | | |
| REPAIR SEAMS | | | | | | | |
| OTHER ACTION | | | | | | | |
| OTHER ACTION | | | | | | | |
| OTHER ACTION | | | | | | | |
| OTHER ACTION | | | | | | | |
| Structural Condition Rating (Last/Now) (%) | 55.6/88.9 | Sufficiency Rating (Last/Now) (%) | 72.3/86.7 | Est. Repl. Yr | 2080 | Maint. Req. (Y/N) | No |
| Special Comments for Next Inspection | | | Department Comments | | | | |
| Maintenance Reviewed By | | | Date | | Estimated Total | 0 | |
| Proposed Long-Term Strategy | | | | | | | |
| On 3-Year Program (Y/N) | | | | | | | |
| Proposed Action | | | | | | | |
| Previous Inspector's Name | Eric Caroux | | Previous Assistant's Name | | | | |
| Next Inspection Date | 28-Nov-2017 | | Previous Inspection Date | 25-Apr-2011 | | | |
| Inspection Cycle (Default) (months) | 57 | | | | | | |
| Comment | | | | | | | |