								Bridge li	nspe	ction						
Bridge File Num	ber	0859	7 -1 E	Bridge				J		т Туре			PCS			
Year Built/Year		1977	/1977	7					Lot	No.	2					
Supstr	N. a.a.a.a	MOD	ואום						Insp	Inspector Name Owen S			Owen Salav	en Salava		
Bridge or Town Name MORRIN  Located Over MICHICHI CREEK. 3.35. WATE				A/A TEI	200	C CT	Insp	Inspector Class			BR CLS A					
Located Over MICHICHI CREEK, 3.35, WATER Located On 9:08 C1 10.665				KUK	3-31	Assistant Name										
Water Body CI./Year						Ass	Assistant Class									
										Inspection Date 02-Nov-2011						
Navigabil. Cl./Year  Legal Land Location SE SEC 13				13 TM/D 31 DCE 10 M//M						Data Entry By Marcia Chavez						
				·03 51·39·56						Data Entry Date 24-Nov-2011						
				Transportation (AIT)						Reviewer Name John O'Brien						
Contract Main. Area CMA21									Review Date			13-Nov-2011				
Clear Roadway/		11.3							Dept. Reviewer Name							
AADT/Year	<u> </u>	-		11 (A)						t. Revie		)	24-Nov-201	1		
Road Classifica	tion			4-120					Follow-Up By							
Detour Length (		12														
Allowable Load	ĺ	igle	CS1	28		Semi	C	S2 49			Train	cs	33 62		> On Critical Spans >Critical Member	
Design Loading:	:		HS25	5											> Primary	Span
							ŀ	osting l	nforn	nation						
Required Load F	Posting	(t)		Single					Semi				Truck Train			
Posted Loading	(t)				Single					Semi			Truck Train			
Posted:	Lane	E	В		At Junction (Y/N)		No	In Advance (Y/N)		No	At Bridge (Y/N) No		No			
Posted:	Lane	M	/B		At Junc	tion (Y	/N)	No		In Advance (Y/N) No		No	At B	ridge (Y/N)	No	
Remarks	Not re		ĺ													
Hazard Marker	At Brid	ge (Y/		No												
Remarks				Not requ	uired.											
Other Sign Type	es															
Litility Attachma	nto						U	Itilities (l	Loca	ted at)						
Utility Attachme	T	rhai							Gas							
Power	Telephone South r/w.							nicipal								
Others										blem (Y	/NI) N	No				
Remarks									1 10		/1 <b>1)</b>   11					
Romano								Approa	ch R	oad						
							Las		Explanation of Condition							
Horizontal Align	ment						8	8								
Vertical Alignme	ent						8	8								
Roadway Width (m)			11.800													
Approach Bump				7	7											
Guardrail (Y/N)				Yes					1 be	1 bent section at SW, minor.						
Guardrail						4	7									
Length (m)			61.800					Insufficient poets. Not their barre								
Current Standard (Y/N) No			No					Insufficient posts. Not thrie beam.								
Termination T	уре			Turn Do	wn											
Drainage							5	7								
Approach Road	d Gene	Approach Road General Rating					8	8				_				

					Supers	tructure			
Bridge Compo	onent			Last	Now	Explanation of Condition			
(Primary Span		ns, Lengths(n	n): 10.7, A-Ide						
Special Featu		<u> </u>	·						
Special Featur					X				
(Type:)									
Special Feature					X				
(Type : )									
Wearing Surface	ce/Deck Top	Detail Ratings							
	N (%)	1 (%)	2 (%)	3 (%)					
Last	(**)	(12)	(12)	- ()					
Now	0.0	0.0	0.0	C	0.0				
Wearing Surfa	ice		•	5	6	One long crack @ 3.2m out from North curb.			
(Material Typ									
(Thickness(n									
Lateral Connec	· · ·	n No							
(Y/N)		1							
Deck Top				N	N				
Deck Rideabili	ity			7	7				
Deck Joints				N	N	Paved.			
		No		IN	IN	Paveu.			
Bump (Y/N)		INO							
Deck Drainage				4	5				
Drains Clogg				_					
Curbs/Median				6	7				
(Curb Type :									
Scaling (Per	cent Area)	3							
Bridge Rail				7	7				
` • •		EEL BRIDGE	TUBE)			One nut @ SE up 25mm.			
Bridge Rail Po				4	4				
STÉEL)		OST STEEL;G	ALVANIZED	POST					
Bridge Rail/Po				7	6				
(Type : GAL)	VANIZED)								
Sidewalk				X	X				
Cinder D. 1 11 D	) atia s:-								
Girder Detail R		1 (00:001)	2 (25:-21)	2 (5-	un4\				
	N (count)	1 (count)	2 (count)	3 (cou					
Last	0	0	0		0				
Now	0	0	0		0				
Girders		00.11	0044	5 5					
Last Complete Inspection Date 02-Nov-2011						Small cracks, no staining, W end G5-6,8.			
Cracking (Y/N) Yes									
Spalling (Percent Area) 0									
Lift or Connector Pocket Grouted (Y/N)  Yes									
(Number Of Gi	irders : <b>10</b> )								
Span Alignme	ent Problems	3							
Vertical (Y/N) No									
Horizontal (Y	//N)	No							
Superstructur	uperstructure General Rating								

					Subst	ructure
Bridge Com	ponent			Last	Now	Explanation of Condition
Abutments						
(Extended	Backwall Piles	s (Y/N) : <b>Y</b> )				
(Extended	Backwall Piles	s Spacing(mm	): 1200)			
(Total Numb	er of Caps/Co	rbels : <b>2:2</b> )				No subcap but extra pile at centerline plus steel plates make
Bearing Sea	ts/Caps/Corbe	ls Detail Ratir	gs			connection acceptable.
	N (count)	1 (count)	2 (count)	3 (cou	unt)	
Last	0	0	0		0	
Now	0	0	0		0	
Bearing Sea	ts/Caps/Corbe	ls		5	5	
(Type : <b>TR</b>	EATED TIMB	ER)				
(Depth(mn	n) : <b>350</b> )					
(Width(mm	n): <b>300</b> )					
Backwalls/B	reastwalls			4	7	
Greatest H	leight (m)	3.00				
Wingwalls				4	7	
	er of Bearing F	Piles : <b>12:12</b> )				
Piles Detail I			1-,	1		
	N (count)	1 (count)	2 (count)	3 (cou		
Last	0	0	0		0	
Now	0	0	0	4	0 6	_
	Piles					
Paint/Coatin	g			X	X	
Abutment St	ability			7	7	
Scour/Erosio	on			5	5	
Piers/Bents						
(Type:)	<u>'</u>					
	er of Caps/Co	rhels · )				
	ts/Caps/Corbe		ns			
Boarning Coa	N (count)	1 (count)	2 (count)	3 (cou	ınt)	
Last	0	0	0		0	
Now					-	
	ts/Caps/Corbe	els		X	X	-
(Type:)	, Саро, Обі ве			Α		
(Depth(mn	u) · )					
(Width(mm						
	er of Bearing F	Piles · \				
Piles Detail I						
. IIOO DEIAII I	N (count)	1 (count)	2 (count)	3 (cou	ınt)	
Last	it (Journ)	i (oouiii)	Z (Sourit)	3 (000		
Now						
Pier Shaft/Piles				X	X	-
	Greatest Height (m)					
	Bracing/Struts/Sheathing					
Nose Plate						
	α.			X	X	
Paint/Coatin	•			X	X	-
	escription:)					
(Colour Co	oae:)					

			Subst	ructure			
Bridge Component		Last	Now	Explanation of Condition			
Pier Stability		X	X				
Scour		Х	X				
Debris (Y/N) Yes				Old piles & driven sheeting. OK as they are low.			
Substructure General Rating			5				
			Structu	re Usage			
		Last	Now	Explanation of Condition			
Channel							
(U/S Direction : N)				Poor approach to bridge from NE @ 30 degree angle.			
(D/S Direction : S)							
Alignment		5	5				
Bank Stability		8	8				
HWM (m below Top of Curb)				HWM not visible.			
Drift (Y/N)	No						
Slope Protection		5	5	Asphalt mixed in. Rock primarily at corners. Fieldstone.			
(Type : RIP RAP; RIP RAP)		·					
Guidebank/Spurs			X				
Adequacy of Opening			8				
(Fish Compensation Measure 1	: NONE)						
(Fish Compensation Measure 2	: NONE)						
Channel General Rating		4	5				

	Maintenance	Recommendations				
Year	Inspector Comments	Department Co	nments	Target Year	Est. Cost	Cat #
2012	Tighten 1 anchor bolt nut at SE.					
NC						
ow) 50.0/55	Sufficiency Rating (Las	st/Now) 45.2/48.9	Est. Repl. Yr 2024	4 Maint. Re	eqd. (Y/N)	Yes
		Department Comments				
		Date		Estimated Tota	1 0	
Wayne Cappe	llani	Previous Assistant's Name	Chris Black			
02-Aug-2013		Previous Inspection Date	27-Sep-2011			
21						
	2012  DN  50.0/55  Wayne Cappel 02-Aug-2013	Year Inspector Comments  2012 Tighten 1 anchor bolt nut at SE.  DN  DN  50.0/55.6 Sufficiency Rating (Las (%))  Wayne Cappellani  02-Aug-2013	2012 Tighten 1 anchor bolt nut at SE.  DN  Sw) 50.0/55.6 Sufficiency Rating (Last/Now) 45.2/48.9  Department Comments  Date  Wayne Cappellani  02-Aug-2013 Previous Assistant's Name Previous Inspection Date	Year	Year	Vear   Inspector Comments