a				
a				
a				
a				
a				
a				
a				
a				
> On Critical	Spans			
	Jan			
uck Train				
	No			
	No			
Access foot bridge to seawall.				
u	>Critical Mer > Primary Sp Ick Train Ick Train Bridge (Y/N)			

						structure
Bridge Comp						Explanation of Condition
		ins, Lengths(m): 4.9-4.9-4	.9-4.9-4	.9-4.9-4	4.9-4.9-4.9-4.9-4.9, A-Ident Number:)
Special Feat	ures					
Special Featu	ire				X	
(Type :)					-	_
Special Featu	ire				X	
(Type :)						
Wearing Surfa	ace/Deck Top	Detail Ratings				
	N (%)	1 (%)	2 (%)	3 (%)		
Last						_
Now	100.0					
Wearing Surf	ace/Deck Top			X	N	Snow covered
(Material Ty	/pe:)					
(Plank Thic	kness(mm) :)					
(Plank Widt	h(mm) :)					
Deck Rideabi	lity			7	7	
Wheel Guard	S			7	N	Snow covered
(Curb Type	: None)					_
(Type : TRE	EATED TIMBE	ER)				_
(Thickness)	(mm) : 40)					_
(Width(mm)	: 140)					
Bridge Rail				7	7	steel panel
(Type :)						
Bridge Rail P	osts			7	7	
(Type : GAI STEEL)	LVANIZED PC	OST STEEL;G	ALVANIZED	POST		
Bridge Rail/P	osts Coating			7	7	
(Type : GA	LVANIZED)					
(No. of String	ers : 4;4;4;4;4	;4;4;4;4;4;4;4	.)			340mm ice to bottom stringer.
Stringer Deta	il Ratings					Ice to deep.
	N (count)	1 (count)	2 (count)	3 (cou	unt)	
Last						
Now	48					
Stringers				N	N	
(Type : TRE	EATED TIMBE	ER)				
(Width(mm)	: 200)					
(Depth(mm) : 250)					
(Spacing(m	m) : 450)					
Sub Deck/De	ck Underside			6	N	
(Material Ty	/pe : TREATE	D TIMBER)				
(Plank Thic	kness(mm) : 4	0)				
(Plank Widt	h(mm) : 200)					
Defects (Pe	ercent Area)	1				
Span Alignm	ent Problems	6				
Vertical (Y/		No				
Horizontal (Y/N)	No				
Superstructu	ure General R	ating		6	6	GR carried fwd.
		_				

Alberta Transportation

					Subst	ructure
Bridge Com	ponent			Last	Now	Explanation of Condition
Abutments						
(Extended	Backwall Piles	s (Y/N) :)				Fill to bottom of stringers, both Abuts26-Oct-2007
(Extended	Backwall Piles	s Spacing(mm):)			
(Total Numbe	er of Caps/Co	rbels : 1:1)				
Bearing Seat	s/Caps/Corbe	ls Detail Ratin	igs			
	N (count)	1 (count)	2 (count)	3 (cou	unt)	-
Last	100	0	0		0	-
Now	2					
Bearing Seat	s/Caps/Corbe	ls		N	N	
(Type : TRI		ER)				
(Depth(mm):)					
(Width(mm)):)					
Backwalls/Br	eastwalls			N	N	
Greatest H	eight (m)					
Wingwalls				Х	Х	
	er of Bearing F	Piles : 0:0)				-
Piles Detail R						-
	N (count)	1 (count)	2 (count)	3 (cou		-
Last	100	0	0		0	-
Now	100					-
Piles				N	N	
Paint/Coating	9			X	X	
Abutment Sta	ability			8	8	
Scour/Erosio	n			8	N	
Piers/Bents						
	R-COLUMN)					
		rbels · 1· ·1·1·	1: :1:1:1:1:1)			(Steel bracket connection between
· ·	s/Caps/Corbe		· · · ·			- piles & caps.21-July-2002)
	N (count)	1 (count)	2 (count)	3 (cou	unt)	1
Last	100	0	0		0	
Now	100				5	
	s/Caps/Corbe	ls		7	N	-
	EATED TIMB				IN	Not visable due to wate/icer depth.
(Depth(mm						
(Width(mm)	· · · · · · · · · · · · · · · · · · ·					-
	· · · · · · · · · · · · · · · · · · ·		:0:0:0:0:0:0:0)		
Piles Detail R		1103 . 0.0.0.	.0.0.0.0.0.0.0	/		-
r iles Detail R	N (count)	1 (count)	2 (count)	3 (cou	unt)	
Last	100				0	-
Now	100	0	0		0	-
Pier Shaft/Pil	1			N	N	-
		1.50		IN	IN	
Greatest H		1.50		N	NI	
Bracing/Strut	soneathing			N	N	
Nose Plate				X	X	
Paint/Coating	-			X	Х	
(Colour De	· · · · · · · · · · · · · · · · · · ·					-
(Colour Co	de :)					

Alberta Transportation

		_	Subst	ructure
Bridge Component		Last	Now	Explanation of Condition
Pier Stability		7	7	
		-		
Scour		7	N	
Debris (Y/N)	No		-	
Substructure General Rating		7	7	General rating carried forward.
		S	Structu	re Usage
				Explanation of Condition
Channel				
(U/S Direction :)				
(D/S Direction :)				
Alignment		7	7	
Bank Stability		7	7	
HWM (m below Top of Curb)	0.7			
Drift (Y/N)	No			
Slope Protection		7	N	Snow covered
(Туре :)				
Guidebank/Spurs		X	X	
Adequacy of Opening			7	
(Fish Compensation Measure 1	NONE)			
(Fish Compensation Measure 2	NONE)			
Channel General Rating		7	7	

		Mainten	ance Recommend	ations					
Inspector Recommendations	Year	Inspector Comments		Department Cor	mments		Target Year	Est. Cost	Cat #
REPAIR/REPLACE BRIDGE RAIL									
PATCH DECK									
REPLACE STRIP DECK									
REPLACE SUB DECK									
STRAIGHTEN/REPLACE MEMBERS									
WASHING									
CORE TIMBER CAPS/CORBELS									
REPAIR/REPLACE TIMBER CAPS									
REPAIR ABUTMENT SCOUR/EROSIO	NC								
PLACE ADDITIONAL RIP RAP									
REMOVE DRIFT ACCUMULATION									
INSTALL STRUTS									
OTHER ACTION									
OTHER ACTION									
OTHER ACTION									
OTHER ACTION									
Structural Condition Rating (Last/No (%)	ow) 72.2/72	.2 Sufficiency Rating (%)	g (Last/Now) /	85.3	Est. Repl. Yr	2022	Maint. Red	qd. (Y/N)	No
Structural Condition Rating (Last/No (%) Special Comments for Next Inspection	ow) 72.2/72		g (Last/Now) /	85.3 Department Comments	Est. Repl. Yr	2022	Maint. Red	qd. (Y/N)	No
(%) Special Comments for	ow) 72.2/72		g (Last/Now) /	Department	Est. Repl. Yr		Maint. Red		No
(%) Special Comments for Next Inspection	ow) 72.2/72		g (Last/Now) /	Department Comments	Est. Repl. Yr				No
(%) Special Comments for Next Inspection Maintenance Reviewed By	ow) 72.2/72		g (Last/Now) /	Department Comments	Est. Repl. Yr				No
(%) Special Comments for Next Inspection Maintenance Reviewed By Proposed Long-Term Strategy	ow) 72.2/72		g (Last/Now) /	Department Comments	Est. Repl. Yr				No
(%) Special Comments for Next Inspection Maintenance Reviewed By Proposed Long-Term Strategy On 3-Year Program (Y/N)	ow) 72.2/72			Department Comments					No
(%) Special Comments for Next Inspection Maintenance Reviewed By Proposed Long-Term Strategy On 3-Year Program (Y/N) Proposed Action			Previous	Department Comments Date					No
(%) Special Comments for Next Inspection Maintenance Reviewed By Proposed Long-Term Strategy On 3-Year Program (Y/N) Proposed Action Previous Inspector's Name Next Inspection Date	Jim Amirault		Previous	Department Comments Date					No