

| Bridge Culvert Inspection | | | | |
|---------------------------|---|--|---------------------|-----------------|
| Bridge File Number | 08814 -2 Bridge Culvert | | Form Type | CUL1 |
| Year Built | 2011 | | Lot No. | 4 |
| Bridge or Town Name | EDSON | | Inspector Name | Shane Hall |
| Located Over | SUNDANCE CREEK, 8.11.107.30, WATERCRS-ST | | Inspector Class | BR CLS A |
| Located On | 47:06 C1 56.719 | | Assistant Name | |
| Water Body Cl./Year | | | Assistant Class | |
| Navigabil. Cl./Year | | | Inspection Date | 15-Oct-2012 |
| Legal Land Location | NE SEC 4 TWP 53 RGE 18 W5M | | Data Entry By | Theresa Lacusta |
| Longitude, Latitude | -116:35:21, 53:33:17 | | Data Entry Date | 14-Nov-2012 |
| Road Authority | Alberta Transportation (AIT) | | Reviewer Name | Eric Carcoux |
| Contract Main. Area | CMA13 | | Review Date | 12-Nov-2012 |
| Clear Roadway/Skew | 9.1 / -5 deg. (LHF) | | Dept. Reviewer Name | Brent Herrick |
| AADT/Year | 1,020 / 2011 (A) | | Dept. Review Date | 20-Nov-2012 |
| Road Classification | RAU-209-110 | | Follow-Up By | |
| Detour Length (km) | 6 | | | |

Bridge Culvert Information

| Number of Culverts | | 1 | | | | | | |
|--------------------------|--------|------|----------------|------|--------|---------------|--------------------|-------|
| Pipe # | Barrel | Span | Rise (or Dia.) | Type | Length | Corr. Profile | Pl./Slab Thickness | Shape |
| 1 | MAIN | - | 7425 | SP | 93.6 | 400X150 | 6.0 | ROUND |
| Special Features | | | | | | | | |
| Special Features Comment | | | | | | | | |

Utilities (Located at)

| | | | | |
|---------------------|------------------------------|--|---------------|----------------------|
| Utility Attachments | | | | |
| Telephone | 4 lines buried in West ditch | | Gas | 60m North, 100m East |
| Power | 100m West, 60m North | | Municipal | |
| Others | | | Problem (Y/N) | No |
| Remarks | | | | |

Approach Road / Embankment

| | | Last | Now | Explanation of Condition |
|--|-------|----------|----------|--|
| Horizontal Alignment | | 7 | 7 | Culvert located at bottom of sag curve, good sight distances. No passing NB. |
| Vertical Alignment | | 7 | 7 | |
| Roadway Width (m) | 9.100 | | | |
| Embankment | | 9 | 9 | Measured on West side 7.2m |
| Sideslope (__:1) | 4.0 | | | |
| (Height of Cover(m) : 7.2) | | | | |
| Guardrail (Y/N) | Yes | | | |
| Approach Road / Embankment General Rating | | 7 | 7 | |

Upstream End

| Culvert Component | | Last | Now | Explanation of Condition |
|---|----------|------|-----|--------------------------|
| Direction | | W | | |
| End Treatment (Concrete, Steel, Others, None) | CONCRETE | | | |
| Headwall | | X | 9 | |
| Collar | | 9 | 9 | |
| Wingwalls | | X | X | |
| (Shape :) | | | | |
| Cutoff Wall | | X | N | |

| Upstream End | | | | |
|---|-------------|----------|----------|--|
| Culvert Component | | Last | Now | Explanation of Condition |
| Bevel End | | 9 | 9 | |
| Heaving (mm) | 0 | | | |
| Invert Above/Below Stream Bed | BELOW | | | |
| Above/Below (mm) | 2150 | | | |
| Scour Protection | | 9 | 9 | |
| (Type : RIP RAP) | | | | |
| (Avg. Rock Size(mm) : 800) | | | | |
| Scour/Erosion | | 9 | 9 | |
| Beavers (Y/N) | No | | | |
| Upstream End General Rating | | 9 | 9 | |
| Bridge Culvert Barrel | | | | |
| Culvert Component | | Last | Now | Explanation of Condition |
| (Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 7425, Type: SP) | | | | |
| Barrel Last Accessible Date | 15-Oct-2012 | | | |
| Special Features | | | | |
| Special Feature | | | | |
| (Type :) | | | | |
| Special Feature | | | | |
| (Type :) | | | | |
| Roof | | 8 | 8 | Downward distortion. 12m from u/s end. Surveyed on Oct-01-2011 |
| Measured Rise (mm) | 7244 | | | |
| Measured At Ring No. | 4 | | | Rise measurement not possible due to silt/gravel on floor. |
| Sag (mm) | 181 | | | |
| Percent Sag | 2 | | | |
| Sidewall | | 8 | 8 | Inward deflection 9m from d/s Surveyed on Oct-01-2011 |
| Measured Span (mm) | 7356 | | | |
| Measured At Ring No. | 64 | | | |
| Deflection (mm) | 69 | | | |
| Percent Deflection | 1 | | | |
| Floor | | 9 | N | Floor not visible - Covered by silt/cobble. |
| Bulge (mm) | | | | |
| Measured At Ring No. | | | | |
| Abrasion (Y/N) | No | | | |
| Circumferential Seams | | 9 | 9 | |
| Separation (mm) | | | | |
| Longitudinal Seams | | 9 | 9 | |
| Total No. of Cracked Rings | | | | |
| Total No. of Rings with Two Cracked Seams | | | | 1N |
| Min. Remaining Steel Between Cracks (mm) | | | | |
| Proper Lap (Y/N) | Yes | | | |
| Longitudinal Stagger (Y/N) | Yes | | | |
| Coating | | 9 | 9 | |
| Corrosion By Soil (Y/N) | No | | | |
| Corrosion By Water (Y/N) | Yes | | | |
| Camber POS/ZERO/NEG | ZERO | | | |
| Ponding (Y/N) | No | | | |

| Bridge Culvert Barrel | | | | |
|---|----------|----------|----------|---|
| Culvert Component | | Last | Now | Explanation of Condition |
| (Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 7425, Type: SP) | | | | |
| Fish Passage Adequacy | | 9 | 9 | |
| Baffle | | X | X | |
| (Type :) | | | | |
| Waterway Adequacy | | 9 | 9 | |
| Icing (Y/N) | No | | | |
| Silting (Y/N) | No | | | |
| Drift (Y/N) | No | | | |
| Barrel General Rating | | 8 | 8 | |
| Downstream End | | | | |
| Culvert Component | | Last | Now | Explanation of Condition |
| Direction | | E | | |
| End Treatment (Concrete, Steel, Others, None) | CONCRETE | | | |
| Headwall | | X | 9 | |
| Collar | | 9 | 9 | |
| Wingwalls | | X | X | |
| (Shape :) | | | | |
| Cutoff Wall | | 9 | N | |
| Bevel End | | 9 | 9 | |
| Heaving (mm) | | | | |
| Invert Above/Below Stream Bed | BELOW | | | |
| Above/Below (mm) | 1650 | | | |
| Scour Protection | | 9 | 9 | |
| (Type : RIP RAP) | | | | |
| (Avg. Rock Size(mm) : 800) | | | | |
| Scour/Erosion | | 9 | 9 | |
| Beavers (Y/N) | No | | | |
| Downstream End General Rating | | 9 | 9 | |
| Structure Usage | | | | |
| | | Last | Now | Explanation of Condition |
| Channel (U/S and D/S) | | | | |
| Alignment | | 7 | 7 | Smooth 90 deg transition from channel to culvert. |
| Bank Stability | | 9 | 9 | |
| HWM (m below Top of Culvert) | | | | HWM not visible |
| Drift (Y/N) | No | | | |
| Channel Bottom Degrading/Aggrading | | | | |
| Beavers (Y/N) | No | | | |
| (Fish Compensation Measure 1 : NONE) | | | | Willow planting d/s only. Rock filled culvert (Class 1m, clean 6-80 & few Class 1) |
| (Fish Compensation Measure 2 : NONE) | | | | |
| Channel General Rating | | 7 | 7 | |

| Maintenance Recommendations | | | | | | | |
|---|--------------------------|--|---------------------------|---------------|-----------|-------------------|----|
| Inspector Recommendations | Year | Inspector Comments | Department Comments | Target Year | Est. Cost | Cat # | |
| SHOTCRETE REPAIRS | | | | | | | |
| PLACE ADDITIONAL RIP RAP | | | | | | | |
| REMOVE DRIFT ACCUMULATION | | | | | | | |
| INSTALL CONCRETE/STEEL LINING | | | | | | | |
| INSTALL STRUTS | | | | | | | |
| INSTALL CONCRETE COLLAR/CUTOFF | | | | | | | |
| REPAIR SEAMS | | | | | | | |
| OTHER ACTION | | | | | | | |
| OTHER ACTION | | | | | | | |
| OTHER ACTION | | | | | | | |
| OTHER ACTION | | | | | | | |
| Structural Condition Rating (Last/Now) (%) | 88.9/88.9 | Sufficiency Rating (Last/Now) (%) | 92.5/92.5 | Est. Repl. Yr | 2061 | Maint. Req. (Y/N) | No |
| Special Comments for Next Inspection | | | Department Comments | | | | |
| Maintenance Reviewed By | | | Date | | | Estimated Total | 0 |
| Proposed Long-Term Strategy | | | | | | | |
| On 3-Year Program (Y/N) | | | | | | | |
| Proposed Action | | | | | | | |
| Previous Inspector's Name | Anne-Frederique Lavallee | | Previous Assistant's Name | | | | |
| Next Inspection Date | 15-Jul-2014 | | Previous Inspection Date | 17-Oct-2011 | | | |
| Inspection Cycle (Default) (months) | 21 | | | | | | |
| Comment | | | | | | | |