

Bridge Culvert Inspection				
Bridge File Number	08952 -1 Bridge Culvert		Form Type	CUL1
Year Built	1989		Lot No.	4
Bridge or Town Name	ETZIKOM		Inspector Name	Tom Carey
Located Over	FORTY MILE COULEE, 2.7.1.12.2, WATERCRS-ST		Inspector Class	BR CLS A
Located On	885:04 C1 9.534		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	13-Mar-2012
Legal Land Location	NE SEC 14 TWP 7 RGE 9 W4M		Data Entry By	Anne Roberts
Longitude, Latitude	-111:06:44, 49:33:52		Data Entry Date	10-Apr-2012
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Garry Roberts
Contract Main. Area	CMA24		Review Date	25-Mar-2012
Clear Roadway/Skew	10.8 /		Dept. Reviewer Name	Tim Davies
AADT/Year	230 / 2011 (A)		Dept. Review Date	17-Apr-2012
Road Classification	RCU-210-110		Follow-Up By	
Detour Length (km)	26			

**Bridge Culvert Information**

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	1800	MP	48	125X26	2.8	ROUND
Special Features								
Special Features Comment								

**Utilities (Located at)**

Utility Attachments				
Telephone	Along West fence.		Gas	
Power			Municipal	
Others			Problem (Y/N)	No
Remarks				

**Approach Road / Embankment**

		Last	Now	Explanation of Condition
Horizontal Alignment		6	6	In curve, super elevated.
Vertical Alignment		6	6	In bottom of sag
Roadway Width (m)	10.800			
Embankment		8	8	
Sideslope ( :1)	3.0			
(Height of Cover(m) : 4.3)				
Guardrail (Y/N)	No			
<b>Approach Road / Embankment General Rating</b>		<b>6</b>	<b>6</b>	

**Upstream End**

Culvert Component		Last	Now	Explanation of Condition
Direction		W		West
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		5	N	(Start of pitted rust on floor.) Submerged
Heaving (mm)	100			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	200			
Scour Protection		N	N	
(Type : <b>RIP RAP</b> )				
(Avg. Rock Size(mm) : <b>250</b> )				
Scour/Erosion		N	N	
Beavers (Y/N)	No			
<b>Upstream End General Rating</b>		<b>5</b>	<b>N</b>	PR 5
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : <b>1</b> , Primary Span, Location Code: <b>MAIN</b> , Span (mm): , Rise (mm): <b>1800</b> , Type: <b>MP</b> )				
Barrel Last Accessible Date	09-Feb-2009			
<b>Special Features</b>				
Special Feature				Average 1000 mm deep water - viewed from ends - shape good.
(Type : )				
Special Feature				
(Type : )				
Roof		8	N	(Est)
Measured Rise (mm)	1790			
Measured At Ring No.	4			
Sag (mm)	10			
Percent Sag				
Sidewall		8	N	(Inward)
Measured Span (mm)	1793			
Measured At Ring No.	4			
Deflection (mm)	7			
Percent Deflection				
Floor		N	N	(Ice covered)
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		7	N	
Separation (mm)	35			
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		4	4	(Some superficial rust @ barrel floor. Pitted corrosion @ bevel floors.) Pitted corrosion at top of roof at ends.
Corrosion By Soil (Y/N)	Yes			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	Yes			(200mm of water in the pipe.) 2005/10/17

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1800, Type: MP)				
Fish Passage Adequacy		X	X	
Baffle		X	X	
(Type : )				
Waterway Adequacy		8	8	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
<b>Barrel General Rating</b>		<b>8</b>	<b>N</b>	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		E		East
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	
Bevel End		8	N	Submerged
Heaving (mm)	125			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	250			
Scour Protection		N	5	Doesn't have too much rock at sides
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 200)				
Scour/Erosion		8	5	
Beavers (Y/N)	No			
<b>Downstream End General Rating</b>		<b>8</b>	<b>N</b>	PR 8
Structure Usage				
		Last	Now	Explanation of Condition
<b>Channel (U/S and D/S)</b>				
Alignment		8	8	Pipe is an equalizer between 2 large ponds
Bank Stability		8	8	
HWM (m below Top of Culvert)				(HWM .6m) 02/05/31 HWM not visible.
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading				
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
<b>Channel General Rating</b>		<b>8</b>	<b>8</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>88.9/55.6</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>84.4/66.6</b>	Est. Repl. Yr	2032	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date		Estimated Total	0	
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Tim Davies		Previous Assistant's Name				
Next Inspection Date	13-Jun-2015		Previous Inspection Date	09-Feb-2009			
Inspection Cycle (Default) (months)	39						
Comment							