

Bridge Inspection									
Bridge File Number	09301 -1 Bridge				Form Type	PCS			
Year Built/Year Supstr	1967/1994				Lot No.	2			
Bridge or Town Name	GROUARD				Inspector Name	Brian Pientsch			
Located Over	TRIBUTARY TO UTIKUMA RIVER, 8.10.18.22.4.6, WATERCRS-ST				Inspector Class	BR CLS A			
Located On	750:04 C1 27.084				Assistant Name	Clem Guenette			
Water Body Cl./Year					Assistant Class				
Navigabil. Cl./Year					Inspection Date	14-Nov-2012			
Legal Land Location	SW SEC 7 TWP 79 RGE 12 W5M				Data Entry By	Theresa Lacusta			
Longitude, Latitude	-115:52:39, 55:49:43				Data Entry Date	09-Jan-2013			
Road Authority	Alberta Transportation (AIT)				Reviewer Name	Eric Carcoux			
Contract Main. Area	CMA02				Review Date	08-Jan-2013			
Clear Roadway/Skew	12 /				Dept. Reviewer Name	David Morrison			
AADT/Year	480 / 2011 (A)				Dept. Review Date	20-Feb-2013			
Road Classification	RCU-210-110				Follow-Up By				
Detour Length (km)	999								
Allowable Load (t):	Single	CS1 28	Semi	CS2 49	Train	CS3 62	----> On Critical Spans ---->Critical Member		
Design Loading:	CS750						----> Primary Span		

Posting Information									
Required Load Posting (t)			Single		Semi		Truck Train		
Posted Loading (t)			Single		Semi		Truck Train		
Posted:	Lane	NB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No	
Posted:	Lane	SB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No	
Remarks									

Hazard Marker At Bridge (Y/N)	Yes								
Remarks									
Other Sign Types									

Utilities (Located at)									
Utility Attachments									
Telephone	N r/w boundary				Gas				
Power	1 wire O.H. S r/w				Municipal				
Others					Problem (Y/N)	No			
Remarks									

Approach Road											
			Last	Now	Explanation of Condition						
Horizontal Alignment			7	7	Limited sight distance to the south.West approx. 150m.						
Vertical Alignment			5	6							
Roadway Width (m)	10.000		4 missing posts will bw installed @ corner as per contract 10419 prior ro 15-Jun-2013.								
Approach Bump		5								7	
Guardrail (Y/N)	Yes										
Guardrail		4								8	
Length (m)	54.466										
Current Standard (Y/N)	Yes										
Termination Type	TURN DOWN										
Drainage		2	7								
Approach Road General Rating			2	6							

Superstructure					
Bridge Component		Last	Now	Explanation of Condition	
(Primary Span : SC, 1 Spans, Lengths(m): 8.5, A-Ident Number:)					
Special Features					
Special Feature			X		
(Type :)					
Special Feature			X		
(Type :)					
Wearing Surface/Deck Top Detail Ratings					
	N (%)	1 (%)	2 (%)	3 (%)	
Last	0	0	0	10	
Now					
Wearing Surface			3	8	
(Material Type : ACP)					
(Thickness(mm) : 140)					
Lateral Connection Problem (Y/N)		No			
Deck Top			N	7	View prior to installing waterproofing membrane.
Deck Rideability			5	7	
Deck Joints			N	X	
Bump (Y/N)		No			
Deck Drainage			6	7	No deck drains.
Drains Clogged (Y/N)		No			
Curbs/Median			4	4	Curbs to be patched and sealed as per contract 10419 prior to 15-Jun-2013
(Curb Type : Standard)					
Scaling (Percent Area)		0			
Bridge Rail			7	9	Double layer
(Type : THRIE BEAM)					
Bridge Rail Posts			7	9	
(Type : GALVANIZED POST STEEL;GALVANIZED POST STEEL)					
Bridge Rail/Posts Coating			7	9	
(Type :)					
Sidewalk			X	X	
Girder Detail Ratings					
	N (count)	1 (count)	2 (count)	3 (count)	
Last					
Now					
Girders			5	5	Narrow longitudinal crack, full length on girder 11. Spall @ drift pin & side on G6. Crack @ drift pin location on G5. Hairline longitudinal crack on side of G2,G3 & G4.
Last Complete Inspection Date		14-Nov-2012			
Cracking (Y/N)		Yes			
Spalling (Percent Area)		0			
Lift or Connector Pocket Grouted (Y/N)		Yes			
(Number Of Girders : 11)					
Span Alignment Problems					
Vertical (Y/N)		No			
Horizontal (Y/N)		No			
Superstructure General Rating			5	5	

Substructure							
Bridge Component				Last	Now	Explanation of Condition	
Abutments							
(Extended Backwall Piles (Y/N) : N)							
(Extended Backwall Piles Spacing(mm) :)							
(Total Number of Caps/Corbels : 1:1)							
Bearing Seats/Caps/Corbels Detail Ratings							
	N (count)	1 (count)	2 (count)	3 (count)		HP 310x94 cap	
Last							
Now							
Bearing Seats/Caps/Corbels				7	9		
(Type : STEEL)							
(Depth(mm) : 310)							
(Width(mm) : 310)							
Backwalls/Breastwalls				4	9		Vertical sheet piles
Greatest Height (m)		2.72					
Wingwalls				3	9		
(Total Number of Bearing Piles : 9:9)							
Piles Detail Ratings							
	N (count)	1 (count)	2 (count)	3 (count)		Galvanized caps & piles.	
Last	0	0	0	8			
Now							
Piles				3	9		
Paint/Coating				X	9		
Abutment Stability				4	8		
Scour/Erosion				3	8		
Piers/Bents							
(Type :)							
(Total Number of Caps/Corbels :)							
Bearing Seats/Caps/Corbels Detail Ratings							
	N (count)	1 (count)	2 (count)	3 (count)			
Last							
Now							
Bearing Seats/Caps/Corbels				X	X		
(Type :)							
(Depth(mm) :)							
(Width(mm) :)							
(Total Number of Bearing Piles :)							
Piles Detail Ratings							
	N (count)	1 (count)	2 (count)	3 (count)			
Last							
Now							
Pier Shaft/Piles				X	X		
Greatest Height (m)							
Bracing/Struts/Sheathing				7	X		
Nose Plate				X	X		
Paint/Coating				X	X		
(Colour Description :)							
(Colour Code :)							
Pier Stability				X	X		

Substructure				
Bridge Component		Last	Now	Explanation of Condition
Scour		X	X	
Debris (Y/N)	No			
Substructure General Rating		3	8	
Structure Usage				
		Last	Now	Explanation of Condition
Channel				
(U/S Direction : E)				
(D/S Direction : W)				
Alignment		7	7	
Bank Stability		7	7	
HWM (m below Top of Curb)				HWM not visible.
Drift (Y/N)	No			
Slope Protection		3	7	
(Type :)				
Guidebank/Spurs		X	X	
Adequacy of Opening		7	7	
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		3	7	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
REPAIR/REPLACE BRIDGE RAIL							
SEAL CURBS	2013	Seal curbs and patch as per contract.					
PATCH DECK							
OVERLAY DECK							
STRAIGHTEN/REPLACE MEMBERS							
WASHING							
SHOTCRETE REPAIRS							
CORE TIMBER CAPS/CORBELS							
REPAIR/REPLACE TIMBER CAPS							
REPAIR ABUTMENT SCOUR/EROSION							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL STRUTS							
OTHER ACTION	2013	Add missing guardrail posts as per contract.					
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	44.4/72.2	Sufficiency Rating (Last/Now) (%)	36.8/70.0	Est. Repl. Yr	2015	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Shane Hall		Previous Assistant's Name	Jordan Evans			
Next Inspection Date	14-Feb-2016		Previous Inspection Date	24-Feb-2009			
Inspection Cycle (Default) (months)	39						
Comment							