

| Bridge Culvert Inspection | | | |
|---------------------------|--|---------------------|-----------------|
| Bridge File Number | 09586 -1 Bridge Culvert | Form Type | CUL1 |
| Year Built | 1966 | Lot No. | 2 |
| Bridge or Town Name | FROG LAKE | Inspector Name | Todd Warshawski |
| Located Over | TRIBUTARY TO FROG CK, 6.7.5, WATERCRS-ST | Inspector Class | BR CLS B |
| Located On | 897:10 C1 4.538 | Assistant Name | |
| Water Body Cl./Year | | Assistant Class | |
| Navigabil. Cl./Year | | Inspection Date | 14-Dec-2011 |
| Legal Land Location | SE SEC 17 TWP 58 RGE 3 W4M | Data Entry By | Theresa Lacusta |
| Longitude, Latitude | -110:24:43, 54:00:47 | Data Entry Date | 14-Jan-2012 |
| Road Authority | Alberta Transportation (AIT) | Reviewer Name | Eric Carcoux |
| Contract Main. Area | CMA08 | Review Date | 04-Jan-2012 |
| Clear Roadway/Skew | 9.4 / 15 deg. (RHF) | Dept. Reviewer Name | Brent Herrick |
| AADT/Year | 860 / 2010 (A) | Dept. Review Date | 18-Jan-2012 |
| Road Classification | RCU-210-110 | Follow-Up By | |
| Detour Length (km) | 100 | | |

Bridge Culvert Information

| | | | | | | | | |
|--------------------------|--------|------|----------------|------|--------|---------------|--------------------|-----------|
| Number of Culverts | 1 | | | | | | | |
| Pipe # | Barrel | Span | Rise (or Dia.) | Type | Length | Corr. Profile | Pl./Slab Thickness | Shape |
| 1 | MAIN | 2489 | 1753 | RPP | 30.5 | 152X51 | 3.0,3.0,2.8 | PIPE ARCH |
| Special Features | | | | | | | | |
| Special Features Comment | | | | | | | | |

Utilities (Located at)

| | | | |
|---------------------|---|---------------|----|
| Utility Attachments | | | |
| Telephone | East r/w. | Gas | |
| Power | | Municipal | |
| Others | | Problem (Y/N) | No |
| Remarks | BF tag installed @ East end, exterior of South bevel. | | |

Approach Road / Embankment

| | Last | Now | Explanation of Condition |
|--|----------|----------|---|
| Horizontal Alignment | 7 | 7 | Entrances North & South. Grade to the South, limited sight distance. No passing to North & South |
| Vertical Alignment | 6 | 6 | |
| Roadway Width (m) | 9.400 | | E |
| Embankment | 8 | 8 | |
| Sideslope (___:1) | 3.0 | | |
| (Height of Cover(m) : 1.7) | | | |
| Guardrail (Y/N) | Yes | | East side only. Minor strike damage to 8 sections, still functional. |
| Approach Road / Embankment General Rating | 6 | 6 | |

Upstream End

| Culvert Component | Last | Now | Explanation of Condition |
|---|-------|-----|--------------------------|
| Direction | E | | |
| End Treatment (Concrete, Steel, Others, None) | STEEL | | |
| Headwall | X | X | |

| Upstream End | | | | |
|--|-------------|----------|----------|--|
| Culvert Component | | Last | Now | Explanation of Condition |
| Collar | | X | X | |
| Wingwalls | | X | X | |
| (Shape :) | | | | |
| Cutoff Wall | | X | X | |
| Bevel End | | 7 | 7 | |
| Heaving (mm) | 0 | | | |
| Invert Above/Below Stream Bed | BELOW | | | |
| Above/Below (mm) | 50 | | | |
| Scour Protection | | 6 | 6 | |
| (Type : RIP RAP) | | | | |
| (Avg. Rock Size(mm) : 300) | | | | |
| Scour/Erosion | | 6 | 6 | |
| Beavers (Y/N) | Yes | | | Beaver dam just U/S. |
| Upstream End General Rating | | 6 | 6 | |
| Bridge Culvert Barrel | | | | |
| Culvert Component | | Last | Now | Explanation of Condition |
| (Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 2489, Rise (mm): 1753, Type: RPP) | | | | |
| Barrel Last Accessible Date | 10-Aug-2008 | | | Viewed from ends, shape and condition appear ok. |
| Special Features | | | | |
| Special Feature | | | | |
| (Type :) | | | | |
| Special Feature | | | | |
| (Type :) | | | | |
| Roof | | 5 | N | Water/ice 1.1m |
| Measured Rise (mm) | 1635 | | | (20/Mar/2002) Not measured. |
| Measured At Ring No. | | | | |
| Sag (mm) | 118 | | | |
| Percent Sag | | | | |
| Sidewall | | 5 | N | |
| Measured Span (mm) | 2585 | | | |
| Measured At Ring No. | | | | |
| Deflection (mm) | 96 | | | |
| Percent Deflection | 4 | | | |
| Floor | | N | N | Covered in water/ice. |
| Bulge (mm) | 0 | | | |
| Measured At Ring No. | | | | |
| Abrasion (Y/N) | No | | | |
| Circumferential Seams | | 7 | N | |
| Separation (mm) | 0 | | | |
| Longitudinal Seams | | 7 | N | |
| Total No. of Cracked Rings | 0 | | | |
| Total No. of Rings with Two Cracked Seams | | | | |
| Min. Remaining Steel Between Cracks (mm) | | | | |
| Proper Lap (Y/N) | No | | | |
| Longitudinal Stagger (Y/N) | Yes | | | |

| Bridge Culvert Barrel | | | | |
|--|-------|----------|----------|---|
| Culvert Component | | Last | Now | Explanation of Condition |
| (Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 2489, Rise (mm): 1753, Type: RPP) | | | | |
| Coating | | 6 | N | |
| Corrosion By Soil (Y/N) | | | | |
| Corrosion By Water (Y/N) | Yes | | | |
| Camber POS/ZERO/NEG | NEG | | | |
| Ponding (Y/N) | Yes | | | |
| Fish Passage Adequacy | | 5 | 5 | |
| Baffle | | X | X | |
| (Type :) | | | | |
| Waterway Adequacy | | 5 | 5 | At U/S opening. |
| Icing (Y/N) | No | | | |
| Silting (Y/N) | Yes | | | |
| Drift (Y/N) | Yes | | | |
| Barrel General Rating | | 5 | 5 | General rating carried fwd from AUg, 2008. |
| Downstream End | | | | |
| Culvert Component | | Last | Now | Explanation of Condition |
| Direction | | W | | |
| End Treatment (Concrete, Steel, Others, None) | STEEL | | | |
| Headwall | | X | X | |
| Collar | | X | X | |
| Wingwalls | | X | X | |
| (Shape :) | | | | |
| Cutoff Wall | | X | X | |
| Bevel End | | 7 | 7 | |
| Heaving (mm) | 100 | | | |
| Invert Above/Below Stream Bed | BELOW | | | |
| Above/Below (mm) | 110 | | | |
| Scour Protection | | 7 | 7 | |
| (Type : RIP RAP) | | | | |
| (Avg. Rock Size(mm) : 250) | | | | |
| Scour/Erosion | | 7 | 7 | |
| Beavers (Y/N) | No | | | |
| Downstream End General Rating | | 7 | 7 | |
| Structure Usage | | | | |
| | | Last | Now | Explanation of Condition |
| Channel (U/S and D/S) | | | | |
| Alignment | | 8 | 8 | U/S is large slough. |
| Bank Stability | | 8 | 8 | |
| HWM (m below Top of Culvert) | | | | HWM not visible (High water reaches crown or higher. 94/09/20) |
| Drift (Y/N) | Yes | | | |

| Structure Usage | | | | |
|--|-----|----------|----------|--------------------------|
| | | Last | Now | Explanation of Condition |
| Channel Bottom Degrading/Aggrading | | | | |
| Beavers (Y/N) | Yes | | | |
| (Fish Compensation Measure 1 : NONE) | | | | |
| (Fish Compensation Measure 2 : NONE) | | | | |
| Channel General Rating | | 8 | 8 | |

| Maintenance Recommendations | | | | | | | |
|---|------------------|--|---------------------------|---------------|-----------|-------------------|-----|
| Inspector Recommendations | Year | Inspector Comments | Department Comments | Target Year | Est. Cost | Cat # | |
| SHOTCRETE REPAIRS | | | | | | | |
| PLACE ADDITIONAL RIP RAP | | | | | | | |
| REMOVE DRIFT ACCUMULATION | 2012 | Beaver dam/debris on East side. | | | | | |
| INSTALL CONCRETE/STEEL LINING | | | | | | | |
| INSTALL STRUTS | | | | | | | |
| INSTALL CONCRETE COLLAR/CUTOFF | | | | | | | |
| REPAIR SEAMS | | | | | | | |
| OTHER ACTION | | | | | | | |
| OTHER ACTION | | | | | | | |
| OTHER ACTION | | | | | | | |
| OTHER ACTION | | | | | | | |
| Structural Condition Rating (Last/Now) (%) | 55.6/55.6 | Sufficiency Rating (Last/Now) (%) | 56.7/56.5 | Est. Repl. Yr | 2025 | Maint. Req. (Y/N) | Yes |
| Special Comments for Next Inspection | | | Department Comments | | | | |
| Maintenance Reviewed By | | | Date | | | Estimated Total | 0 |
| Proposed Long-Term Strategy | | | | | | | |
| On 3-Year Program (Y/N) | | | | | | | |
| Proposed Action | | | | | | | |
| Previous Inspector's Name | Dave Lam | | Previous Assistant's Name | | | | |
| Next Inspection Date | 14-Mar-2015 | | Previous Inspection Date | 10-Aug-2008 | | | |
| Inspection Cycle (Default) (months) | 39 | | | | | | |
| Comment | | | | | | | |