

Bridge Inspection							
Bridge File Number	00992 -1 Bridge			Form Type	SG		
Year Built/Year Supstr	1955/1955			Lot No.	1		
Bridge or Town Name	FORT MACLEOD			Inspector Name	Randy Bredo		
Located Over	WILLOW CREEK, 2.12.25, WATERCRS-ST			Inspector Class	BR CLS A		
Located On	811:02 C1 4.003			Assistant Name	Bryce Clayton		
Water Body Cl./Year				Assistant Class			
Navigabil. Cl./Year				Inspection Date	20-Jan-2010		
Legal Land Location	NW SEC 24 TWP 9 RGE 26 W4M			Data Entry By	Jill Potts		
Longitude, Latitude	-113:24:26, 49:45:14			Data Entry Date	12-May-2011		
Road Authority	Alberta Transportation (AIT)			Reviewer Name	Garry Roberts		
Contract Main. Area	CMA26			Review Date	25-Mar-2010		
Clear Roadway/Skew	7.3 /			Dept. Reviewer Name	Tim Davies		
AADT/Year	1,240 / 2010 (A)			Dept. Review Date	20-May-2011		
Road Classification	RLU-207G-60			Follow-Up By			
Detour Length (km)	10						
Allowable Load (t):	Single	CS1 39 GIRDER	Semi	CS2 51 GIRDER	Train	CS3 63 GIRDER	----> On Critical Spans ---->Critical Member
Design Loading:	HS20				----> Primary Span		

Posting Information								
Required Load Posting (t)			Single		Semi		Truck Train	
Posted Loading (t)			Single		Semi		Truck Train	
Posted:	Lane	NB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No
Posted:	Lane	SB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No
Remarks	Not required.							
Hazard Marker At Bridge (Y/N)	Yes							
Remarks	{400mm too low. May 10, 2009 CP inspection}							
Other Sign Types	Curve signs, 85 km/hr.							

Utilities (Located at)				
Utility Attachments	TELEPHONE UTILITIES-PHONE LINE; TELEPHONE UTILITIES-Bell Canada Fibre Optic on outside fascia Aug 2005			
Telephone	West r/w and under West curb.		Gas	
Power	1 wire crosses 100m North of bridge.		Municipal	
Others	Water pump @ NW. Telus cable or cablevision, overhead 10m East.		Problem (Y/N)	No
Remarks				

Approach Road				
		Last	Now	Explanation of Condition
Horizontal Alignment		5	5	Curve at both ends of bridge limiting sight distance. Rise to South.
Vertical Alignment		5	5	
Roadway Width (m)	7.300			Not thrie beam.
Approach Bump		6	6	
Guardrail (Y/N)	Yes			
Guardrail		6	5	
Length (m)	99.000			
Current Standard (Y/N)	No			
Termination Type	Turn Down			
Drainage		3	6	Undermined at SW and SE corners.
<b>Approach Road General Rating</b>		<b>5</b>	<b>5</b>	

Superstructure							
Bridge Component		Last	Now	Explanation of Condition			
(Primary Span : <b>RB, 3 Spans, Lengths(m): 21.9-27.4-21.9, A-Ident Number: A0237-01</b> )							
<b>Special Features</b>							
Special Feature			X				
(Type : )							
Special Feature			X				
(Type : )							
Wearing Surface/Deck Top Detail Ratings							
	N (%)	1 (%)	2 (%)	3 (%)			
<b>Last</b>	0	0	0	0			
<b>Now</b>							
Wearing Surface			6	6	Chip coat on concrete & polymer overlay.		
(Material Type : <b>CONCRETE - CONVENTIONAL CHIP SEAL COAT</b> )							
(Thickness(mm) : <b>50</b> )							
Deck Top			N	N			
Deck Rideability			7	7			
Deck Joints			5	3	{Top of glands split, slight leakage on North abutment between G1 & G2. May 10, 2009 CP inspection} NW curb cover plate sits up 15mm		
Temperature (deg. C)		17					
(Expansion Type : <b>GLAND (WABO-MAUER, TRANSFLEX, ETC)</b> )							
(Fixed Type : )							
Gap Size (mm)		Gap Location					
65		North - A2					
70		South - A1					
Deck Drainage			8	6			
Drains Clogged (Y/N)		No					
Curbs/Median			5	5			
(Curb Type : <b>Standard</b> )							
Scaling (Percent Area)		5					
Bridge Rail			6	5	Posts re-habed.		
(Type : <b>STEEL BRIDGE TUBE</b> )							
Bridge Rail Posts			6	5	30% paint failure.		
(Type : <b>CONCRETE;CONCRETE</b> )							
Bridge Rail/Posts Coating			3	4			
(Type : <b>PAINT</b> )							
Sidewalk			X	X			
<b>Girder/Beam</b>							
Cover Plate			7	3	{1 small cracked weld at end of coverplate span 2 girder 3. May 10, 2009 CP inspection} Over pier bearings only.		
Flange			7	7			
Web			7	7	{1 small cracked weld. May 10, 2009 CP inspection}		
Stiffeners			7	7			
Splice			7	7			
Weld			7	3			
Diaphragms/Cross Frame			7	7	Concrete diaphragms at abuts		

Superstructure				
Bridge Component		Last	Now	Explanation of Condition
<b>(Primary Span : RB, 3 Spans, Lengths(m): 21.9-27.4-21.9, A-Ident Number: A0237-01)</b>				
Paint Condition		4	4	{Ends of girders re-painted @ abutment. 2% corrosion @ bottom flanges. May 10, 2009 CP inspection} Green
(Colour Description : <b>GREEN</b> )				
(Colour Code : <b>14090</b> )				
Touchup Required (Y/N)	No			
Bearings		6	3	{Bearings repainted @ abutments. Pier rocker bearings are attempting to walk off masonry plates with enough force to distort the anchor bolt. Backwall chipped out 30mm to allow expansion of girders. Abut brgs have been reset & pier 1 has 1 missing shoulder bolt & 2 backed off shoulder bolts. May 10, 2009 CP inspection} Sole plates modified to allow movement.
Temperature (deg. C)	17			
(Expansion Type : <b>SLIDING PLATE</b> )				
(Fixed Type : <b>ROCKER BEARING</b> )				
Coating Adequate (Y/N)	Yes			
Functioning (Y/N)	Yes			
Deck Underside		5	5	Narrow transverse cracks at approx 400mm o.c. in bending areas and approx 1500mm in neutral areas. All cracks have leaching stains.
Stains (Percent Area)	10			
<b>Span Alignment Problems</b>				
Vertical (Y/N)	No			
Horizontal (Y/N)	No			
<b>Superstructure General Rating</b>		<b>5</b>	<b>3</b>	{P1G1 rocker exp 55mm with only 30mm of room left. AB's badly bent P1. May 10, 2009 CP inspection}
Substructure				
Bridge Component		Last	Now	Explanation of Condition
<b>Abutments</b>				
Bearing Seats/Caps		6	6	
(Type : <b>CONCRETE</b> )				
Backwalls/Breastwalls		6	6	South backwall chipped to allow expansion
Wingwalls		6	X	Curtain walls
Piles		N	N	
Paint/Coating		X	X	
Abutment Stability		6	6	
Scour/Erosion		6	7	
<b>Piers/Bents</b>				
(Type : <b>PIER-SOLID</b> )				
Bearing Seats/Caps		7	7	
(Type : <b>CONCRETE</b> )				
(Total Number of Bearing Piles : <b>0:0</b> )				
Pier Shaft/Piles		7	7	
Bracing/Struts/Sheathing		X	X	
Nose Plate		7	7	
Paint/Coating		4	4	{60% corrosion on nose plates. May 10, 2009 CP inspection} 50% SURFACE CORROSION @ NOSEPLATE
(Colour Description : )				
(Colour Code : )				
Pier Stability		6	5	{South hill slowly sliding towards river, may cause problems later. May 10, 2009 CP inspection}
Scour		6	6	

Substructure				
Bridge Component		Last	Now	Explanation of Condition
Debris (Y/N)	Yes			{Large log caught on pier. Other large drift in channel. May 10, 2009 CP inspection}
<b>Substructure General Rating</b>		<b>6</b>	<b>5</b>	
Structure Usage				
		Last	Now	Explanation of Condition
<b>Channel</b>				
(U/S Direction : <b>W</b> )				Access trail under Span 1 {Steep cut @ South abutment but face of cut is 10m from abutment. May 10, 2009 CP inspection}
(D/S Direction : <b>E</b> )				
Alignment		6	7	
Bank Stability		6	5	{SW bank active eroding and moving towards channel, OK for now. May 10, 2009 CP inspection} Banks steep cut
HWM (m below Top of Curb)				No visible HWM
Drift (Y/N)	Yes			{Large drift in channel. May 10, 2009 CP inspection}
Slope Protection		6	6	Rip rap at South toe of slope (Type : <b>RIP RAP; RIP RAP</b> )
Guidebank/Spurs		X	X	
Adequacy of Opening		7	8	
(Fish Compensation Measure 1 : <b>NONE</b> )				
(Fish Compensation Measure 2 : <b>NONE</b> )				
<b>Channel General Rating</b>		<b>6</b>	<b>6</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
REPAIR/REPLACE BRIDGE RAIL							
GALVANIZE/PAINT BRIDGE RAIL							
RETROFIT BRIDGE RAIL							
SEAL CURBS							
PATCH DECK							
SEAL DECK							
OVERLAY DECK							
REPAIR/REPLACE DECK JOINTS	2011	{Repair leaking joint. May 10, 2009 CP inspection}					
RESET/ PAINT BEARINGS	2011	{Reset P1 bearings & install new anchor bolts & weld keepers so rocker does not walk off the masonry plate. Replace with neoprene pads another option. May 10, 2009 CP inspection}					
REPAINT SUPERSTRUCTURE							
STRAIGHTEN/REPLACE MEMBERS							
WASHING							
SHOTCRETE REPAIRS							
REPAIR ABUTMENT SCOUR/EROSION							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION	2011	{Remove drift from pier. May 10, 2009 CP inspection}					
OTHER ACTION	2011	Repair undermining at SW and SE approx 1m3 grout					
OTHER ACTION	2011	{Reset hazard markers to standard height. May 10, 2009 CP inspection}					
OTHER ACTION	2011	{Repair 1 cracked coverplate weld. May 10, 2009 CP inspection}					
OTHER ACTION	2011	{Reduce inspection cycle to coincide with closest hwy inspection cycle so this bridge can be inspected every 21 months until bearings are repaired. May 10, 2009 CP inspection}					
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>61.1/44.4</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>63.5/55.7</b>	Est. Repl. Yr	2028	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							

Proposed Action			
Previous Inspector's Name	Garry Roberts	Previous Assistant's Name	
Next Inspection Date	20-Apr-2013	Previous Inspection Date	19-Jan-2010
Inspection Cycle (Default) (months)	39		
Comment			