

Bridge Culvert Inspection				
Bridge File Number	72290 -1 Bridge Culvert		Form Type	CUL1
Year Built	1971		Lot No.	2
Bridge or Town Name	STANDARD		Inspector Name	Garry Roberts
Located Over	SEVERN CREEK, 3.33.8, WATERCRS-ST		Inspector Class	BR CLS A
Located On	840:02 C1 17.739		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	10-Jan-2012
Legal Land Location	NW SEC 2 TWP 26 RGE 22 W4M		Data Entry By	Anne Roberts
Longitude, Latitude	-112:58:54, 51:11:46		Data Entry Date	07-Feb-2012
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Joel Wozney
Contract Main. Area	CMA29		Review Date	18-Jan-2012
Clear Roadway/Skew	8.8 / 11 deg. (RHF)		Dept. Reviewer Name	Tim Davies
AADT/Year	620 / 2010 (A)		Dept. Review Date	09-Feb-2012
Road Classification	RCU-211-110		Follow-Up By	
Detour Length (km)	6			

Bridge Culvert Information								
Number of Culverts		1						
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	1981	2286	SPE	62.8	152X51	3.0	ELLIPSE
Special Features								
Special Features Comment								

Utilities (Located at)			
Utility Attachments			
Telephone	West ditch		Gas
Power			Municipal
Others			Problem (Y/N) No
Remarks			

Approach Road / Embankment				
		Last	Now	Explanation of Condition
Horizontal Alignment		8	7	
Vertical Alignment		8	7	
Roadway Width (m)	8.800			
Embankment		4	5	Ditch erosion @ NW not affecting culvert
Sideslope (:1)	2.0			
(Height of Cover(m) : 7.3)				
Guardrail (Y/N)	No			
Approach Road / Embankment General Rating		4	7	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		W		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		6	6	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	50			
Scour Protection		7	7	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 150)				
Scour/Erosion		7	7	
Beavers (Y/N)	No			
Upstream End General Rating		6	6	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 1981, Rise (mm): 2286, Type: SPE)				
Barrel Last Accessible Date	10-Jan-2012			
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		4	4	Could not confirm rise due to ice in R8
Measured Rise (mm)	2090			
Measured At Ring No.	8			
Sag (mm)	196			
Percent Sag	8			
Sidewall		3	4	Small construction tear in North sidewall R3. Isolated construction dents.
Measured Span (mm)	2165			
Measured At Ring No.	8			
Deflection (mm)	184			
Percent Deflection	9			
Floor		5	5	
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		7	7	
Separation (mm)	0			
Longitudinal Seams		5	4	1 seam at North sidewall not properly lapped with several loose bolts and gaps to 10 mm
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	No			
Longitudinal Stagger (Y/N)	No			
Coating		5	5	Superficial corrosion @ u/s bevel & floor and soil, corrosion stains through bolt holes
Corrosion By Soil (Y/N)	Yes			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	No			

Bridge Culvert Barrel					
Culvert Component		Last	Now	Explanation of Condition	
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 1981, Rise (mm): 2286, Type: SPE)					
Fish Passage Adequacy		X	7		
Baffle		X	X		
(Type :)					
Waterway Adequacy		6	4	Grass on roof and upper sidewall bolts indicate pipe has run full	
Icing (Y/N)	No				
Silting (Y/N)	No				
Drift (Y/N)	No				
Barrel General Rating		3	4		
Downstream End					
Culvert Component		Last	Now	Explanation of Condition	
Direction		E			
End Treatment (Concrete, Steel, Others, None)	STEEL				
Headwall		X	X		
Collar		X	X		
Wingwalls		X	X		
(Shape :)					
Cutoff Wall		X	X		
Bevel End		6	6		
Heaving (mm)	50				
Invert Above/Below Stream Bed	ABOVE				
Above/Below (mm)	100				
Scour Protection		4	4	Bevel undermined & 2m diameter deep rock lined scour hole	
(Type : RIP RAP)					
(Avg. Rock Size(mm) : 250)					
Scour/Erosion		4	4		
Beavers (Y/N)	No				
Downstream End General Rating		4	4		
Structure Usage					
		Last	Now	Explanation of Condition	
Channel (U/S and D/S)					
Alignment		7	6		
Bank Stability		6	7		
HWM (m below Top of Culvert)	0.0			Grass on roof bolts	
Drift (Y/N)	No				
Channel Bottom Degrading/Aggrading	DEGRADING				
Beavers (Y/N)	No				
(Fish Compensation Measure 1 : NONE)					
(Fish Compensation Measure 2 : NONE)					
Channel General Rating		6	6		

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP	2013	10 m 3 Cl. 1 at D/S					
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	33.3/44.4	Sufficiency Rating (Last/Now) (%)	39.6/47.7	Est. Repl. Yr	2025	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Jason Rusu		Previous Assistant's Name				
Next Inspection Date	10-Apr-2015		Previous Inspection Date	21-Oct-2008			
Inspection Cycle (Default) (months)	39						
Comment							