

Bridge Culvert Inspection			
Bridge File Number	72424 -1 Bridge Culvert	Form Type	CULM
Year Built	1959	Lot No.	4
Bridge or Town Name	NANTON	Inspector Name	Jon Davies
Located Over	NANTON CREEK, 2.12.12.12.5, WATERCRS-ST	Inspector Class	BR CLS B
Located On	2:10 R1 25.726;2:10 L1 25.654	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	18-Oct-2011
Legal Land Location	SE SEC 21 TWP 16 RGE 28 W4M	Data Entry By	Erin Roberts
Longitude, Latitude	-113:47:28, 50:21:39	Data Entry Date	21-Nov-2011
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Garry Roberts
Contract Main. Area	CMA27	Review Date	08-Nov-2011
Clear Roadway/Skew	21.4 / 30 deg. (RHF)	Dept. Reviewer Name	Tim Davies
AADT/Year		Dept. Review Date	25-Nov-2011
Road Classification	RAD-412.4-120	Follow-Up By	
Detour Length (km)	1		

**Bridge Culvert Information**

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	6100	3050	BP	53.3			RECTANGLE
Special Features	STORM WATER DRAIN							
Special Features Comment								

**Utilities (Located at)**

Utility Attachments							
Telephone	At East r/w.			Gas			
Power				Municipal			
Others	Fiber optics East ROW			Problem (Y/N)	No		
Remarks							

**Approach Road / Embankment**

		Last	Now	Explanation of Condition
Horizontal Alignment		5	5	Curve 50 m South.
Vertical Alignment		8	8	
Roadway Width (m)	21.400			
Embankment		7	7	
Sideslope (__:1)	3.0			
(Height of Cover(m) : 2)				
Guardrail (Y/N)	Yes			
<b>Approach Road / Embankment General Rating</b>		<b>5</b>	<b>5</b>	

**Upstream End**

Culvert Component		Last	Now	Explanation of Condition
Direction		W		West end.
End Treatment (Concrete, Steel, Others, None)	CONCRETE			
Headwall		6	6	Minor cracks and scaling
Collar		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Wingwalls (Shape : <b>FLARE</b> )		6	5	Minor cracks. Walls have moved away at barrel jct - away 25mm and in 50 mm at SW. Moved inward 100mm and away 50mm at NW
Cutoff Wall		N	N	Silt covered
Bevel End		X	X	
Heaving (mm)	0			
Invert Above/Below Stream Bed				At streambed.
Above/Below (mm)	0			
Scour Protection (Type : <b>RIP RAP</b> ) (Avg. Rock Size(mm) : <b>300</b> )		6	6	INGROWN
Scour/Erosion		6	6	
Beavers (Y/N)	No			
<b>Upstream End General Rating</b>		<b>6</b>	<b>6</b>	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 3050, Rise (mm): 3050, Type: BP, Cell Sequence: 1)				
Barrel Last Accessible Date	18-Oct-2011			South.
Special Features				
Special Feature (Type : <b>STORM WATER DRAIN</b> )		6	6	In Ring 2
Special Feature (Type : )				
Roof		6	6	Minor hairline long. cracks.
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)	0			
Percent Sag				
Sidewall		6	6	Some minor wide cracking near top of walls 1 to 1.5 mm.
Measured Span (mm)				
Measured At Ring No.				
Deflection (mm)	0			
Percent Deflection				
Floor		N	N	600 mm water and silt on floor. Steel fence panels washed into R1
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams		6	6	Efflorescence and minor leakage. 10mm vertical separation R2-R3
Separation (mm)	20			
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		X	X	
Corrosion By Soil (Y/N)				
Corrosion By Water (Y/N)				

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 3050, Rise (mm): 3050, Type: BP, Cell Sequence: 1)				
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			
Fish Passage Adequacy		5	5	
Baffle		X	X	
(Type : )				
Waterway Adequacy		7	7	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
<b>Barrel General Rating</b>		<b>6</b>	<b>6</b>	

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 3050, Rise (mm): 3050, Type: BP, Cell Sequence: 2)				
Barrel Last Accessible Date	18-Oct-2011			North. Receives most of flow.
<b>Special Features</b>				
Special Feature				
(Type : )				
Special Feature				
(Type : )				
Roof		6	6	Minor long. hairline cracks.
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)	0			
Percent Sag				
Sidewall		6	6	Isolated cracks at U/S and D/S end. Up to 1mm wide at NE. Vertical & longitudinal
Measured Span (mm)				
Measured At Ring No.				
Deflection (mm)	0			
Percent Deflection				
Floor		N	N	0 to 400mm deep silt and water on floor. Steel fence panels washed into R1
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams		6	6	Roof seam - box lower 15 mm from u/s end. Efflorescence and minor leakage.
Separation (mm)	20			
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		X	X	
Corrosion By Soil (Y/N)				
Corrosion By Water (Y/N)				

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 3050, Rise (mm): 3050, Type: BP, Cell Sequence: 2)				
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			
Fish Passage Adequacy		6	6	
Baffle		X	X	
(Type : )				
Waterway Adequacy		7	7	This cell takes the stream flow.
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
<b>Barrel General Rating</b>		<b>6</b>	<b>6</b>	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		E		East end. Vegetated silt 600 mm high across outlet of South cell
End Treatment (Concrete, Steel, Others, None)	CONCRETE			
Headwall		6	6	Minor cracks
Collar		X	X	
Wingwalls		5	4	Wing moved away 60 mm and in 200 mm with loss of fill @ NE. 0.5m long x 0.2m wide x 0.8m deep
(Shape : <b>FLARE</b> )				
Cutoff Wall		N	N	Silt covered
Bevel End		X	X	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	300			
Scour Protection		7	7	In grown ROCK @ SOUTH
(Type : <b>RIP RAP</b> )				
(Avg. Rock Size(mm) : <b>350</b> )				
Scour/Erosion		7	7	
Beavers (Y/N)	No			
<b>Downstream End General Rating</b>		<b>5</b>	<b>4</b>	
Structure Usage				
		Last	Now	Explanation of Condition
<b>Channel (U/S and D/S)</b>				
Alignment		5	5	Stream enters North cell RxR Bridge removed D/s abuts. still in place
Bank Stability		5	5	Steep cut @ NW
HWM (m below Top of Culvert)	2.0			Grass HWM @ u/s gates
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading	AGGRADING			
Beavers (Y/N)	No			

Structure Usage				
		Last	Now	Explanation of Condition
(Fish Compensation Measure 1 : <b>NONE</b> )				
(Fish Compensation Measure 2 : <b>NONE</b> )				
<b>Channel General Rating</b>		<b>5</b>	<b>5</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>66.7/66.7</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>65.8/67.0</b>	Est. Repl. Yr	2035	Maint. Reqd. (Y/N)	No
Special Comments for Next Inspection	Monitor D/S wing wall movement. Appears stable this inspection but may require horizontal struts if movement continues. J Davies 25-Oct-2011		Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Garry Roberts		Previous Assistant's Name				
Next Inspection Date	18-Jul-2013		Previous Inspection Date	26-Jan-2010			
Inspection Cycle (Default) (months)	21						
Comment							