

Bridge Culvert Inspection				
Bridge File Number	74569 -1 Bridge Culvert		Form Type	CUL1
Year Built	1989		Lot No.	3
Bridge or Town Name	STIRLING		Inspector Name	Jon Davies
Located Over	ETZIKOM COULEE, 11.9, WATERCRS-ST		Inspector Class	BR CLS B
Located On	61:02 C1 6.052		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	28-Mar-2013
Legal Land Location	SW SEC 6 TWP 7 RGE 18 W4M		Data Entry By	Lauren Korte
Longitude, Latitude	-112:26:20, 49:31:32		Data Entry Date	08-Apr-2013
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Garry Roberts
Contract Main. Area	CMA24		Review Date	07-Apr-2013
Clear Roadway/Skew	10 /		Dept. Reviewer Name	Tim Davies
AADT/Year	540 / 2012 (A)		Dept. Review Date	22-Apr-2013
Road Classification	RAU-209-110		Follow-Up By	
Detour Length (km)	6			

Bridge Culvert Information								
Number of Culverts		1						
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	PI./Slab Thickness	Shape
1	MAIN	6898	4224	RPA	21.3	152X51	4.0,5.0	ARCH
Special Features								
Special Features Comment								

Utilities (Located at)			
Utility Attachments			
Telephone			Gas
Power			Municipal
Others	Fibre optic cable North ditch.		Problem (Y/N) No
Remarks			

Approach Road / Embankment				
		Last	Now	Explanation of Condition
Horizontal Alignment		7	7	Intersection West
Vertical Alignment		9	9	
Roadway Width (m)	10.000			
Embankment		8	7	Mower damage at SW wingend
Sideslope (_ :1)	4.0			
(Height of Cover(m) : 0.6)				
Guardrail (Y/N)	Yes			
Approach Road / Embankment General Rating		7	7	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction				North end.
End Treatment (Concrete, Steel, Others, None)	CONCRETE			
Headwall		8	8	
Collar		8	8	
Wingwalls		8	8	
(Shape : FLARE)				
Cutoff Wall		N	N	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		7	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	400			
Scour Protection		7	7	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 450)				
Scour/Erosion		7	7	
Beavers (Y/N)	No			
Upstream End General Rating		7	7	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 6898, Rise (mm): 4224, Type: RPA)				
Barrel Last Accessible Date	21-Jan-2009			High water level and thin ice
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		N	N	(est)21- Jan -2009 PR 8 Viewed from ends, shape is good
Measured Rise (mm)	4224			
Measured At Ring No.				
Sag (mm)	0			
Percent Sag				
Sidewall		N	N	(Isolated rock dent centerline East wall - minor.) 21- Jan -2009 PR 7
Measured Span (mm)	6898			
Measured At Ring No.	5			
Deflection (mm)	0			
Percent Deflection				
Floor		N	N	(Average 300mm deep silt with 700mm water.) 21- Jan -2009
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams		N	N	PR 8
Separation (mm)	0			
Longitudinal Seams		N	N	PR 8
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams	0			
Min. Remaining Steel Between Cracks (mm)	0			
Proper Lap (Y/N)	Yes			
Longitudinal Stagger (Y/N)	No			
Coating		N	N	(Minor superficial rust on isolated rock dent.)21- Jan -2009
Corrosion By Soil (Y/N)				
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 6898, Rise (mm): 4224, Type: RPA)				
Fish Passage Adequacy		8	8	
Baffle		X	X	
(Type :)				
Waterway Adequacy		9	9	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		N	N	PR 8
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction				South end.
End Treatment (Concrete, Steel, Others, None)	CONCRETE			
Headwall		8	8	
Collar		8	8	
Wingwalls		8	8	
(Shape :)				
Cutoff Wall		N	N	
Bevel End		7	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	400			
Scour Protection		7	7	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 450)				
Scour/Erosion		7	7	
Beavers (Y/N)	No			
Downstream End General Rating		7	7	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		6	6	Curves up & down stream
Bank Stability		5	5	Slumping U/S East bank 5m x 8m
HWM (m below Top of Culvert)				HWM not visible
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading	AGGRADING			Rock 0.7m high @ U/S end.
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		6	6	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION	2013	Replace wing end at SW					
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	55.6/55.6	Sufficiency Rating (Last/Now) (%)	72.3/72.2	Est. Repl. Yr	2045	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Jon Davies		Previous Assistant's Name				
Next Inspection Date	28-Dec-2014		Previous Inspection Date	15-Jun-2011			
Inspection Cycle (Default) (months)	21						
Comment							