

Bridge Inspection											
Bridge File Number	07475 -1 Bridge				Form Type	SG					
Year Built/Year Supstr	1957/1957				Lot No.	2					
Bridge or Town Name	BLUFFTON				Inspector Name	Owen Salava					
Located Over	BLINDMAN RIVER, 3.78, WATERCRS-ST				Inspector Class	BR CLS A					
Located On	20:06 C1 13.859				Assistant Name						
Water Body Cl./Year					Assistant Class						
Navigabil. Cl./Year					Inspection Date	09-Jul-2012					
Legal Land Location	SW SEC 12 TWP 44 RGE 3 W5M				Data Entry By	Marcia Chavez					
Longitude, Latitude	-114:18:57, 52:46:37				Data Entry Date	01-Aug-2012					
Road Authority	Alberta Transportation (AIT)				Reviewer Name	John O'Brien					
Contract Main. Area	CMA18				Review Date	30-Jul-2012					
Clear Roadway/Skew	11 /				Dept. Reviewer Name	Andrew Smikles					
AADT/Year	2,490 / 2011 (A)				Dept. Review Date	02-Aug-2012					
Road Classification	RLU-208G-90				Follow-Up By						
Detour Length (km)	3										
Allowable Load (t):	Single	CS1 75 GIRDER			Semi	CS2 108 GIRDER			Train	CS3 153 GIRDER	----> On Critical Spans ---->Critical Member
Design Loading:	HS20									----> Primary Span	

Posting Information									
Required Load Posting (t)			Single		Semi			Truck Train	
Posted Loading (t)			Single		Semi			Truck Train	
Posted:	Lane	NB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No	
Posted:	Lane	SB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No	
Remarks	Not required.								
Hazard Marker At Bridge (Y/N)	No								
Remarks	Not required.								
Other Sign Types	River ID.								

Utilities (Located at)										
Utility Attachments										
Telephone	In r/w to West.				Gas					
Power	On East r/w, 20 m from c/l, 1 wire.				Municipal					
Others					Problem (Y/N)		No			
Remarks										

Approach Road									
			Last	Now	Explanation of Condition				
Horizontal Alignment			7	7	Field approaches to the North.				
Vertical Alignment			7	7					
Roadway Width (m)	11.000		Small potholes developing at A1 in SBL (photo).						
Approach Bump			4	4					
Guardrail (Y/N)			Yes						
Guardrail			7	7	Not thrie beam.				
Length (m)			70.000						
Current Standard (Y/N)			No						
Termination Type			TURNED DOWN						
Drainage			4	4	Bridge is at bottom of sag with approaches partly draining onto bridge.				
Approach Road General Rating			7	7					

Superstructure					
Bridge Component		Last	Now	Explanation of Condition	
(Primary Span : RB, 2 Spans, Lengths(m): 15.2-15.2, A-Ident Number: A0244-01;A0244-02)					
Special Features					
Special Feature			X		
(Type :)					
Special Feature			X		
(Type :)					
Wearing Surface/Deck Top Detail Ratings					
	N (%)	1 (%)	2 (%)	3 (%)	
Last	10	0	0	0	
Now	0.0	0.0	0.0	0.0	
Wearing Surface			6	5	Hairline 0.1 mm wide map cracking at North span. Chipsealed with some delaminated at pier in NBL.
(Material Type : CONVENTIONAL CHIP SEAL COAT)					
(Thickness(mm) :)					
Deck Top			N	N	
Deck Rideability			7	6	
Deck Joints			3	3	(Leaking onto abut/pier at all 6 gutter locations.) - Unable to confirm in dry conditions; all joints tarred. Concrete blockout at deck underside is deteriorating exposing rusting rebar at N abut, pier & S abut block out. Pier joint is jammed.
Temperature (deg. C)		29			
(Expansion Type : BUFFER ANGLES)					
(Fixed Type : BUFFER ANGLES)					
Gap Size (mm)		Gap Location			
5		N. abut			
15		C. pier			
0		S. abut			
Deck Drainage			4	4	Deck joints allow water onto piers & abuts.
Drains Clogged (Y/N)		No			
Curbs/Median			N	5	Light scaling at face and transverse cracks.
(Curb Type : Standard)					
Scaling (Percent Area)		5			
Bridge Rail			7	7	20% of grout pads have voids under base plate. E rail multiple nuts not tight to washers - 26 in total.
(Type : GALVANIZED STEEL VERTICAL BAR)					
Bridge Rail Posts		N	4		
(Type : POST STEEL;POST STEEL)					
Bridge Rail/Posts Coating		7	7		
(Type : GALVANIZED)					
Sidewalk			X	X	
Girder/Beam					
Cover Plate			7	7	
Flange			7	7	
Web			7	7	
Stiffeners			X	X	
Splice			X	X	
Weld			7	7	
Diaphragms/Cross Frame			7	7	

Superstructure				
Bridge Component		Last	Now	Explanation of Condition
(Primary Span : RB, 2 Spans, Lengths(m): 15.2-15.2, A-Ident Number: A0244-01;A0244-02)				
Paint Condition		5	5	95% of girder paint is good. Some touch-up required below the joints.
(Colour Description : BLUE)				
(Colour Code : 502-105)				
Touchup Required (Y/N)	No			
Bearings		4	4	Bearings are resisting movements resulting in bent AB's and twisted plates. 2 anchor bolt nuts missing & other hardware loose. 50% superficial corrosion at abut bearings. S abutjammed against girders.
Temperature (deg. C)	29			
(Expansion Type : SLIDING PLATE)				
(Fixed Type : PINNED BEARING)				
Coating Adequate (Y/N)	No			
Functioning (Y/N)	No			
Deck Underside		6	6	Transverse cracks every est 1.5 m with leach stains under gutters. Joint block outs deteriorated at deck underside.
Stains (Percent Area)	2			
Span Alignment Problems				
Vertical (Y/N)	No			
Horizontal (Y/N)	No			
Superstructure General Rating		4	4	
Substructure				
Bridge Component		Last	Now	Explanation of Condition
Abutments				
Bearing Seats/Caps		5	5	Gravel and debris on abut seat due to leaky joints.
(Type : CONCRETE)				
Backwalls/Breastwalls		7	7	
Wingwalls		7	7	
Piles		N	N	
Paint/Coating		X	X	
Abutment Stability		5	5	
Scour/Erosion		7	6	Settlement or erosion under A2 seat.
Piers/Bents				
(Type : PIER-SOLID)				2 vertical medium width cracks and medium scaling. Gravel on pier seat due to leaky joint. Spall at NE corner.
Bearing Seats/Caps		4	4	
(Type : CONCRETE)				
(Total Number of Bearing Piles : 0)				
Pier Shaft/Piles		6	6	
Bracing/Struts/Sheathing		X	X	
Nose Plate		6	6	
Paint/Coating		X	4	Surface rusted.
(Colour Description :)				
(Colour Code :)				
Pier Stability		6	6	
Scour		N	N	
Debris (Y/N)	Yes			Drift on pier & abut seats.
Substructure General Rating		4	4	

Structure Usage				
		Last	Now	Explanation of Condition
Channel				
(U/S Direction : W)		Steep cut banks at D/S.		
(D/S Direction : E)				
Alignment		6	6	
Bank Stability		6	6	
HWM (m below Top of Curb)	-0.5	(Negative freeboard of approx 500. 07Feb2008). Drift on top of pier and abut seats at hslps.		
Drift (Y/N)	Yes			
Slope Protection		6	6	Some rock both abuts.
(Type : NATURAL; NATURAL)				
Guidebank/Spurs		X	X	
Adequacy of Opening		4	4	Basin scoured out under bridge but not affecting structure embankments. Minor erosion under A2 bearing seat (photo). Not passing full flow; drift on pier.
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		4	4	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
REPAIR/REPLACE BRIDGE RAIL	2012	Tighten 26 nuts flush to washers.					
GALVANIZE/PAINT BRIDGE RAIL							
RETROFIT BRIDGE RAIL							
SEAL CURBS							
PATCH DECK							
SEAL DECK							
OVERLAY DECK							
REPAIR/REPLACE DECK JOINTS	2012	Recast concrete blockouts @ underside of joints.					
RESET/ PAINT BEARINGS	2012	Replace bearings. Install 2 anchor bolt nuts and tighten all loose bolts.					
REPAINT SUPERSTRUCTURE	2012	Touchup paint under joints.					
STRAIGHTEN/REPLACE MEMBERS							
WASHING							
SHOTCRETE REPAIRS							
REPAIR ABUTMENT SCOUR/EROSION							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION	2012	Remove drift from superstructures and substructures.					
OTHER ACTION	2012	Clean gravel off abutment & pier seats.					
OTHER ACTION	2020	Raise bridge 600mm.					
OTHER ACTION	2012	Patch potholes at A1.					
OTHER ACTION	2012	Patch spall NE pier cap.					
Structural Condition Rating (Last/Now) (%)	44.4/44.4	Sufficiency Rating (Last/Now) (%)	63.9/63.6	Est. Repl. Yr	2035	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy	2006.05.09 Rehab in 2020 and spot replacement in 2050.						
On 3-Year Program (Y/N)	Y						
Proposed Action	2006.05.09 Joint repair in 2008.						
Previous Inspector's Name	Owen Salava		Previous Assistant's Name				
Next Inspection Date	09-Apr-2014		Previous Inspection Date	08-Dec-2010			
Inspection Cycle (Default) (months)	21						
Comment							