

Bridge Culvert Inspection				
Bridge File Number	07497 -1 Bridge Culvert		Form Type	CUL1
Year Built	1960		Lot No.	2
Bridge or Town Name	WARBURG		Inspector Name	Todd Warshawski
Located Over	LITTLE STRAWBERRY CREEK, 6.112.16, WATERCRS-ST		Inspector Class	BR CLS B
Located On	39:08 C1 3.971		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	10-Jan-2013
Legal Land Location	SW SEC 5 TWP 49 RGE 3 W5M		Data Entry By	Lisa Fairhurst
Longitude, Latitude	-114:24:22, 53:11:33		Data Entry Date	22-Jan-2013
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Eric Carcoux
Contract Main. Area	CMA11		Review Date	16-Jan-2013
Clear Roadway/Skew	11.1 / 0 deg.		Dept. Reviewer Name	Brent Herrick
AADT/Year	2,850 / 2011 (A)		Dept. Review Date	23-Jan-2013
Road Classification	RAU-211.8-110		Follow-Up By	
Detour Length (km)	6			

**Bridge Culvert Information**

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	5944	3277	AP	55.8			ARCH
Special Features								
Special Features Comment								

**Utilities (Located at)**

Utility Attachments				
Telephone	North & south r/w.		Gas	
Power	3 wires from c/l North r/w.		Municipal	
Others			Problem (Y/N)	No
Remarks				

**Approach Road / Embankment**

		Last	Now	Explanation of Condition
Horizontal Alignment		6	6	On a curve. Limited sight distance to west. Sag vertical curve.
Vertical Alignment		7	7	
Roadway Width (m)	11.100			
Embankment		N	N	(Sideslope changes from 2.5:1 to 4:1 after 3.7m from ACP. Gully @ SE 30m long, 2m wide, 700mm deep - photo.-27-May-2009)
Sideslope (__:1)	2.5			
(Height of Cover(m) : 3.1)				
Guardrail (Y/N)	Yes			
<b>Approach Road / Embankment General Rating</b>		<b>6</b>	<b>6</b>	

**Upstream End**

Culvert Component		Last	Now	Explanation of Condition
Direction		S		
End Treatment (Concrete, Steel, Others, None)	CONCRETE			
Headwall		7	6	
Collar		X	X	
Wingwalls		5	5	Wide vertical crack on SE wingwall.
(Shape : <b>FLARE</b> )				
Cutoff Wall		N	N	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		X	X	
Heaving (mm)	0			
Invert Above/Below Stream Bed				
Above/Below (mm)	0			
Scour Protection		N	N	
(Type : <b>NATURAL</b> )				
(Avg. Rock Size(mm) : )				
Scour/Erosion		N	N	
Beavers (Y/N)	Yes			Beaver dam in inlet-photo
<b>Upstream End General Rating</b>		<b>5</b>	<b>5</b>	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 5944, Rise (mm): 3277, Type: AP)				
Barrel Last Accessible Date	10-Jan-2013			Ice 2m to crown.
<b>Special Features</b>				
Special Feature				
(Type : )				
Special Feature				
(Type : )				
Roof		5	5	Roof appears to be in adequate condition.
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)	0			
Percent Sag				
Sidewall		5	5	Crack with efflorescence on S sidewall.
Measured Span (mm)				
Measured At Ring No.				
Deflection (mm)	0			
Percent Deflection				
Floor		N	N	(Floor is breaking up in at least one spot where the bevel joins the barrel U/S end. 1991/09/25)
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams		5	5	
Separation (mm)	15			
Longitudinal Seams		5	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		X	X	
Corrosion By Soil (Y/N)				
Corrosion By Water (Y/N)				
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 5944, Rise (mm): 3277, Type: AP)				
Fish Passage Adequacy		7	7	
Baffle		N	N	
(Type : )				
Waterway Adequacy		7	7	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
<b>Barrel General Rating</b>		<b>5</b>	<b>5</b>	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		N		
End Treatment (Concrete, Steel, Others, None)	CONCRETE			
Headwall		7	6	
Collar		X	X	
Wingwalls		4	5	Wide vertical crack on NE wingwall.
(Shape : <b>FLARE</b> )				
Cutoff Wall		N	N	
Bevel End		X	X	
Heaving (mm)	0			
Invert Above/Below Stream Bed				
Above/Below (mm)	0			
Scour Protection		N	N	
(Type : <b>NONE</b> )				
(Avg. Rock Size(mm) : )				
Scour/Erosion		N	N	(Scour hole silted in, D/S pool approx 18m x 6m x 0.4m.-27-May-2009) Snow covered.
Beavers (Y/N)	No			
<b>Downstream End General Rating</b>		<b>4</b>	<b>4</b>	GR carried forward.
Structure Usage				
		Last	Now	Explanation of Condition
<b>Channel (U/S and D/S)</b>				
Alignment		5	5	Makes sharp bend off D/S end to the West.
Bank Stability		4	4	Sloughing/vertical banks d/s.
HWM (m below Top of Culvert)				
Drift (Y/N)	Yes			
Channel Bottom Degrading/Aggrading				
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : <b>NONE</b> )				
(Fish Compensation Measure 2 : <b>NONE</b> )				
<b>Channel General Rating</b>		<b>4</b>	<b>4</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION	2013	Remove beaver dam from inlet					
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>55.6/55.6</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>56.7/56.5</b>	Est. Repl. Yr	2027	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Wade Nanninga		Previous Assistant's Name				
Next Inspection Date	10-Oct-2014		Previous Inspection Date	25-Jan-2011			
Inspection Cycle (Default) (months)	21						
Comment							