

Bridge Culvert Inspection				
Bridge File Number	77050 -1 Bridge Culvert		Form Type	CUL1
Year Built	1992		Lot No.	2
Bridge or Town Name	HINTON		Inspector Name	Todd Warshawski
Located Over	COLD CREEK, 8.11.141.2, WATERCRS-ST		Inspector Class	BR CLS B
Located On	40:28 C1 44.074		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	30-Oct-2012
Legal Land Location	SW SEC 28 TWP 50 RGE 25 W5M		Data Entry By	Theresa Lacusta
Longitude, Latitude	-117:36:30, 53:20:32		Data Entry Date	19-Nov-2012
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Eric Carcoux
Contract Main. Area	CMA13		Review Date	13-Nov-2012
Clear Roadway/Skew	12.9 / -10 deg. (LHF)		Dept. Reviewer Name	Brent Herrick
AADT/Year	490 / 2011 (A)		Dept. Review Date	20-Nov-2012
Road Classification	RAU-211.8-110		Follow-Up By	
Detour Length (km)	20			

Bridge Culvert Information								
Number of Culverts		1						
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	3990	SP	71.3	152X51	4.0	ROUND
Special Features								
Special Features Comment								

Utilities (Located at)			
Utility Attachments			
Telephone	West r/w.		Gas
Power	4 wire East r/w.		Municipal
Others			Problem (Y/N) No
Remarks	File tag in place.		

Approach Road / Embankment				
		Last	Now	Explanation of Condition
Horizontal Alignment		7	7	Gradual curves & grades.
Vertical Alignment		8	8	
Roadway Width (m)	12.900			
Embankment		4	N	Ditch erosion, SE ditch 500mm deep x 1000mm width. Partially filled in from clearing operation.-Sept/2010.
Sideslope (_ :1)	3.0			
(Height of Cover(m) : 5.6)				
Guardrail (Y/N)	Yes			Minor strike damage, still functional.
Approach Road / Embankment General Rating		7	7	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		E		
End Treatment (Concrete, Steel, Others, None)	CONCRETE			
Headwall		8	8	
Collar		6	6	Wide transverse cracks in collar. 3 per side.
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		7	N	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		8	7	
Heaving (mm)	100			
Invert Above/Below Stream Bed	BELOW			(05/Oct/2007)
Above/Below (mm)	500			
Scour Protection		7	N	Settlement of riprap along sides of bevel upto 300mm. -Sep, 2010
(Type : RIP RAP)				Under snow
(Avg. Rock Size(mm) : 400)				
Scour/Erosion		7	N	
Beavers (Y/N)	No			
Upstream End General Rating		6	7	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1 , Primary Span, Location Code: MAIN , Span (mm):				, Rise (mm): 3990 , Type: SP)
Barrel Last Accessible Date	30-Oct-2012			Level 2 completed 10-Sep-2010 Rings 1-10 appear to be vertically ellipsed.
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		4	4	
Measured Rise (mm)				Estimated from survey. 10-Sep-2010
Measured At Ring No.	13			
Sag (mm)	300			
Percent Sag	8			
Sidewall		5	5	
Measured Span (mm)	4260			
Measured At Ring No.	13			
Deflection (mm)	270			
Percent Deflection	1			
Floor		N	N	Floor covered in rock wash.
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	Yes			
Circumferential Seams		8	8	
Separation (mm)	0			
Longitudinal Seams		5	5	Poorly nested in places at ring 13 due to distortion from deflections & sagging.
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams				Inward deflection on several seams in rhings 2-10.
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	Yes			2N
Longitudinal Stagger (Y/N)	Yes			
Coating		6	6	White rust on pieces from improper storage. Stains at both holes.
Corrosion By Soil (Y/N)	Yes			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 3990, Type: SP)				
Fish Passage Adequacy		8	8	
Baffle		X	X	
(Type :)				
Waterway Adequacy		8	8	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		4	4	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		W		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		7	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	1000			
Scour Protection		7	N	Under snow.
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 400)				
Scour/Erosion		5	N	
Beavers (Y/N)	No			
Downstream End General Rating		7	5	GR carried fwd from 10-Sep-2010
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		6	6	
Bank Stability		5	5	Upstream banks are eroded near vertical.
HWM (m below Top of Culvert)				HWM not visible.
Drift (Y/N)	Yes			Large trees across channel at inlet.-photo
Channel Bottom Degrading/Aggrading				
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		5	6	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION	2013	Remove debris at inlet.					
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	44.4/44.4	Sufficiency Rating (Last/Now) (%)	61.7/61.2	Est. Repl. Yr	2030	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection	Monitor seam distortion.		Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Arnold Assenheimer		Previous Assistant's Name	Melanie Johnson			
Next Inspection Date	30-Jul-2014		Previous Inspection Date	10-Sep-2010			
Inspection Cycle (Default) (months)	21						
Comment							