

Bridge Inspection									
Bridge File Number	80644 E-2 Bridge				Form Type	PSR			
Year Built/Year Supstr	1992/1992				Lot No.	4			
Bridge or Town Name	VEGREVILLE				Inspector Name	Jason Saly			
Located Over	VERMILION RIVER, 6.5, WATERCRS-ST				Inspector Class	BR CLS A			
Located On	16:24 R1 23.205				Assistant Name				
Water Body Cl./Year					Assistant Class				
Navigabil. Cl./Year					Inspection Date	19-Jul-2012			
Legal Land Location	NE SEC 7 TWP 52 RGE 14 W4M				Data Entry By	Marcia Chavez			
Longitude, Latitude	-112:02:56, 53:28:36				Data Entry Date	10-Aug-2012			
Road Authority	Alberta Transportation (AIT)				Reviewer Name	John O'Brien			
Contract Main. Area	CMA14				Review Date	28-Jul-2012			
Clear Roadway/Skew	12.5 / 20 deg. (RHF)				Dept. Reviewer Name	Andrew Smikles			
AADT/Year	5,740 / 2011 (A)				Dept. Review Date	13-Aug-2012			
Road Classification	RAD-412.4-120				Follow-Up By				
Detour Length (km)	1								
Allowable Load (t):	Single	CS1 28	Semi	CS2 49	Train	CS3 62	----> On Critical Spans ---->Critical Member		
Design Loading:	CS750						----> Primary Span		

Posting Information									
Required Load Posting (t)	Single		Semi		Truck Train				
Posted Loading (t)	Single		Semi		Truck Train				
Posted:	Lane	EB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No	
Posted:	Lane	WB	At Junction (Y/N)		In Advance (Y/N)		At Bridge (Y/N)		
Remarks									
Hazard Marker At Bridge (Y/N)	Yes								
Remarks									
Other Sign Types									

Utilities (Located at)									
Utility Attachments									
Telephone					Gas				
Power	10 wire OH 75 m S. of EBL c.l				Municipal				
Others					Problem (Y/N)	No			
Remarks									

Approach Road									
			Last	Now	Explanation of Condition				
Horizontal Alignment			8	8	Pothole starting to form at E abut in S lane.				
Vertical Alignment			9	8					
Roadway Width (m)		13.700			Not thrie beam.				
Approach Bump			6	6					
Guardrail (Y/N)		Yes							
Guardrail			6	6					
Length (m)		65.000							
Current Standard (Y/N)		No							
Termination Type		TURNED DOWN ENDS							
Drainage			8	7					
Approach Road General Rating			8	8					

Superstructure					
Bridge Component		Last	Now	Explanation of Condition	
(Primary Span : DBC, 1 Spans, Lengths(m): 40, A-Ident Number:)					
Special Features					
Special Feature			X		
(Type :)					
Special Feature			X		
(Type :)					
Wearing Surface/Deck Top Detail Ratings					
	N (%)	1 (%)	2 (%)	3 (%)	
Last	60	0	0	0	
Now	0.0	0.0	0.0	0.0	
Wearing Surface			5	4	There are transv. & random cracks reflecting through the ACP & seal coat. ACP deterioration along the gutters.
(Material Type : ACP - CONVENTIONAL CHIP SEAL COAT)					
(Thickness(mm) : 50)					
Lateral Connection Problem (Y/N)		No			
Deck Top			N	N	
Deck Rideability			7	7	
Deck Joints			8	7	Fixed Expansion
Temperature (deg. C)					
(Expansion Type : GLAND (WABO-MAUER, TRANSFLEX, ETC))					
(Fixed Type : GLAND (WABO-MAUER, TRANSFLEX, ETC))					
Gap Size (mm)		Gap Location			
74		W. abut			
67		E. abut			
Deck Drainage			5	5	
Drains Clogged (Y/N)		No			
Curbs/Median			6	5	Vertical flex & transv. cracks every est 1.0m on curbs. The accident damage repair to the curb was left uncoated at S curb at 3rd post from W.
(Curb Type : Standard)					
Scaling (Percent Area)		0			
Bridge Rail			8	8	
(Type : GALVANIZED STEEL BRIDGE TUBE)					
Bridge Rail Posts			8	7	
(Type : GALVANIZED POST STEEL; GALVANIZED POST STEEL)					
Bridge Rail/Posts Coating			7	7	
(Type : GALVANIZED)					
Sidewalk			X	X	
Girder Detail Ratings					
	N (count)	1 (count)	2 (count)	3 (count)	
Last	0	0	0	0	
Now	0	0	0	0	
Girders			5	5	Coating on N. fascia is approximately 3% peeled. Typical hairline cracks in block ends.
Cracking (Y/N)		Yes			
Spalling (Percent Area)		0			
(Number Of Girders : 11)					

Superstructure				
Bridge Component		Last	Now	Explanation of Condition
(Primary Span : DBC, 1 Spans, Lengths(m): 40, A-Ident Number:)				
Diaphragms/Cross Frame		8	8	
Bearings		8	8	E abut W abut
Temperature (deg. C)				
(Expansion Type : REINFORCED NEOPRENE BEARING WITH TEFLON AND STAINLESS STEEL)				
(Fixed Type : REINFORCED NEOPRENE BEARING WITH TEFLON AND STAINLESS STEEL)				
Coating Adequate (Y/N)	Yes			
Functioning (Y/N)	Yes			
Deck Underside		8	8	
Stains (Percent Area)	0			
Span Alignment Problems				
Vertical (Y/N)	No			
Horizontal (Y/N)	No			
Superstructure General Rating		5	5	
Substructure				
Bridge Component		Last	Now	Explanation of Condition
Abutments				
Bearing Seats/Caps		8	7	
(Type : CONCRETE)				
Backwalls/Breastwalls		8	8	
Wingwalls		7	7	
Piles		N	N	
Paint/Coating		8	8	
Abutment Stability		8	8	
Scour/Erosion		7	7	
Piers/Bents				
(Type :)				
Bearing Seats/Caps		X	X	
(Type :)				
(Total Number of Bearing Piles :)				
Pier Shaft/Piles		X	X	
Bracing/Struts/Sheathing		X	X	
Nose Plate		X	X	
Paint/Coating		X	X	
(Colour Description :)				
(Colour Code :)				
Pier Stability		X	X	
Scour		X	X	
Debris (Y/N)	No			
Substructure General Rating		8	7	

Structure Usage				
		Last	Now	Explanation of Condition
Channel				
(U/S Direction : S)				
(D/S Direction : N)				
Alignment		7	7	
Bank Stability		7	7	
HWM (m below Top of Curb)				HWM not visible. 2 beaver dams S of EB bridge.
Drift (Y/N)		Yes		
Slope Protection (Type : RIP RAP; RIP RAP)		8	7	Well vegetated.
Guidebank/Spurs		X	X	
Adequacy of Opening		9	9	
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		7	7	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
REPAIR/REPLACE BRIDGE RAIL							
GALVANIZE/PAINT BRIDGE RAIL							
SEAL CURBS							
PATCH DECK							
SEAL DECK							
OVERLAY DECK							
REPAIR/REPLACE DECK JOINTS							
RESET/ PAINT BEARINGS							
WASHING							
SHOTCRETE REPAIRS							
REPAIR ABUTMENT SCOUR/EROSION							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	72.2/66.7	Sufficiency Rating (Last/Now) (%)	66.1/63.9	Est. Repl. Yr	2044	Maint. Req. (Y/N)	No
Special Comments for Next Inspection	WB structure to be considered for ACP replacement maybe cost effective to replace ACP on both structures.		Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Owen Salava		Previous Assistant's Name				
Next Inspection Date	19-Apr-2014		Previous Inspection Date	16-Dec-2010			
Inspection Cycle (Default) (months)	21						
Comment							