

Bridge Inspection									
Bridge File Number	09905 -1 Bridge				Form Type	TH PT PSR PCS			
Year Built/Year Supstr	1950/1950				Lot No.	1			
Bridge or Town Name	ATHABASCA				Inspector Name	Arnold Assenheimer			
Located Over	ATHABASCA RIVER, 8.11, WATERCRS-ST				Inspector Class	BR CLS A			
Located On	813:02 C1 1.095				Assistant Name	Wade Nanninga			
Water Body Cl./Year					Assistant Class	BR CLS B			
Navigabil. Cl./Year					Inspection Date	06-Jan-2011			
Legal Land Location	NW SEC 21 TWP 66 RGE 22 W4M				Data Entry By	Theresa Lacusta			
Longitude, Latitude	-113:16:29, 54:43:41				Data Entry Date	03-Feb-2011			
Road Authority	Alberta Transportation (AIT)				Reviewer Name	Stew Hagan			
Contract Main. Area	CMA10				Review Date	13-Jan-2011			
Clear Roadway/Skew	7.3 /				Dept. Reviewer Name	Brent Herrick			
AADT/Year	2,300 / 2009 (A)				Dept. Review Date	08-Feb-2011			
Road Classification	RAU-209-110				Follow-Up By				
Detour Length (km)	100								
Allowable Load (t):	Single		Semi		Train		----> On Critical Spans ---->Critical Member		
Design Loading:	HS20				----> Primary Span				

Posting Information												
Required Vert. Clearance Posting (m)												
Posted Vertical Clearance (Y/N)	Yes											
Posted:	Lane	NB	On Bridge (m)	5.6	In Advance (Y/N)	Yes	Lane	SB	On Bridge (m)	5.6	In Advance (Y/N)	Yes
Remarks	Measured 5.85m both sides.											
Required Load Posting (t)	Single				Semi				Truck Train			
Posted Loading (t)	Single				Semi				Truck Train			
Posted:	Lane	NB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No				
Posted:	Lane	SB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No				
Remarks	Required.											
Hazard Marker At Bridge (Y/N)	Yes											
Remarks	Not in line with truss, approx 300mm out of line, not at ends fo bridge.											
Other Sign Types	Slippery When Wet, One Truck, Be Prepared to Stop, 35 kmh. Narrow bridge, 60km/h.											

Utilities (Located at)									
Utility Attachments									
Telephone	Along U/S side, West r/w.				Gas				
Power	30m crossing road @ South approach.				Municipal				
Others					Problem (Y/N)	Yes			
Remarks	Looped to allow for future slide. Cable exposed, hanging at North. Broken conduit both ends.								

Approach Road				
		Last	Now	Explanation of Condition
Horizontal Alignment		5	5	OK for speed limit. 6% grade.
Vertical Alignment		5	5	
Roadway Width (m)	9.000			No thrie beam. SE section bent. Missing splice bolts.
Approach Bump		5	5	
Guardrail (Y/N)	Yes			
Guardrail		3	4	
Length (m)	68.600			
Current Standard (Y/N)	No			
Termination Type	Turned Down			
Drainage		6	6	

Approach Road					
			Last	Now	Explanation of Condition
Approach Road General Rating			5	5	
Superstructure					
Bridge Component			Last	Now	Explanation of Condition
(Primary Span : TH, 8 Spans, Lengths(m): 30.5-61-61-61-30.5-15.2-15.2-4.9, A-Ident Number: A0180-02;A0180-03;A0180-04;A0180-01;A0180-05)					
Special Features					
Special Feature				X	TH - spans 5,6, & 7.
(Type :)					
Special Feature				X	
(Type :)					
Wearing Surface/Deck Top Detail Ratings					
	N (%)	1 (%)	2 (%)	3 (%)	
Last	0	0	0	0	
Now					
Wearing Surface/Deck Top			4	4	5% rotten/split ends with missing lag screws (loose planks).
(Material Type : UNTREATED TIMBER)					
(Plank Thickness(mm) : 75)					
(Plank Width(mm) : 300)					
Deck Rideability			5	5	
Deck Joints			X	N	(Expansion plates are loose and banging when traffic rides over. Missing bolts and lags at north abutment SBL- photo. 17/June/2004) Paved over.
Temperature (deg. C)		0			
(Expansion Type : SLIDING PLATES)					
(Fixed Type :)					
Gap Size (mm)		Gap Location			
0					
0					
Curbs/Wheel Guards			7	N	Snow covered.
(Curb Type : Standard)					
(Type : TREATED TIMBER)					
(Thickness(mm) : 150)					
(Width(mm) : 300)					
Bridge Rail			4	3	Missing rail bolt-NBL. Double layer. Localized creases in all TH spans W and E rail. Do not meet standard triple layer. All splices missing bolts. 2 rail blocks missing split/rotted. Rail scratched/nicked & rusting.
(Type : GALVANIZED STEEL FLEX BEAM)					
Bridge Rail Posts/Blocking			3	3	
(Type : TREATED TIMBER;TREATED TIMBER)					
Bridge Rail/Posts Coating			4	4	
(Type : GALVANIZED)					
Sidewalk			X	X	

Superstructure							
Bridge Component				Last	Now	Explanation of Condition	
(Primary Span : TH, 8 Spans, Lengths(m): 30.5-61-61-61-30.5-15.2-15.2-4.9, A-Ident Number: A0180-02;A0180-03;A0180-04;A0180-01;A0180-05)							
Wide Load Damage (Y/N)	Yes					HLD to - S2, S3 & S4. L10 & U9 nicked South side. Nicks from WLD. Could not confirm all dimensions of dents/notches due to traffic and narrow bridge. S5 L0U1W - 2 20mm notches, 15x500mm dent inside flange near U1. S5 I0U1E - 2 20mm notches. S5 U3L4W - 5x300mm dent. S5 U5L6W - 5x450mm dent. S5 U7L6W - 7mm notch. S5 U6LW, U7L7W - 5mm notches at chest height. S7 U5L5W - 16x300mm dent adn 5mm notch. Web has slight buckle at connection. Buckle on U/S corner near bearing from earth pressure, minor.-31-May-2008 Missing 3 bolts at S5 L10W 9 bays x 10 bay/span x 3 spans. Not accessible to measure.	
High Load Damage (Y/N)	Yes						
Top Chord				4	4		
Batter Posts				4	4		
Sway Bracings				4	4		
Diagonals				5	5		
Verticals				4	4		
Portals				5	5		
Connections				5	5		
Floor Beams				5	5		
Bottom Chord				5	5		
(No. of Stringers : 270;Null;Null)							
Stringer Detail Ratings							
	N (count)	1 (count)	2 (count)	3 (count)			
Last							
Now							
Stringers				6	6		
(Type : STEEL)							
(Width(mm) :)							
(Depth(mm) :)							
(Spacing(mm) : 853)							
Paint Condition				3	3	Rust blisters and scaling in splash zone, pitting.	
(Colour Description :)							
(Colour Code :)							
Touchup Required (Y/N)	No						
Bearings				3	3	No anchor bolt in P1 & P3.-31-May-2008 Missing AB in AZ. Bearings are all non-functional due to corrosion, and to distortion due to earth pressures. Roller nests are jammed against anchor bolts or skewed due to being frozen. Disc and dome bearings dislodged.-31-May-2008 iewed from ice-piers snow covered.	
Temperature (deg. C)	23						
(Expansion Type : ROLLER NEST BEARING)							
(Fixed Type : DISC & DOME BEARING)							
Functioning (Y/N)	No						
Sub Deck/Deck Underside				4	4	Timber clips are loose. South hill pushed against truss. Sub deck clamped down near west abutment, loose chips beyond clamps. Loose planks indicate potential rot, or crushing at pier and joint locations. Crushing caused by movement of S hill.	
(Material Type : TREATED TIMBER)							
(Plank Thickness(mm) : 100)							
(Plank Width(mm) : 300)							
Defects (Percent Area)	2						
Span Alignment Problems							
Vertical (Y/N)	No						
Horizontal (Y/N)	Yes						
Superstructure General Rating				3	3		
Superstructure							
Bridge Component				Last	Now	Explanation of Condition	
(Secondary Span : PT)							
Special Features							
Special Feature					5	Span 4 & 8. Span 8 only; bars are corroded. Special feature - post tension (dwyidag bars)	
(Type : EXT LONGIT POST TENS)							
Special Feature					X		
(Type :)							

Superstructure					
Bridge Component		Last	Now	Explanation of Condition	
(Secondary Span : PT)					
Wearing Surface/Deck Top Detail Ratings					
	N (%)	1 (%)	2 (%)	3 (%)	
Last	0	0	0	1	
Now	0.0	0.0	0.0	1.0	
Wearing Surface/Deck Top			3	3	Loose plank end S8. Some planks split.
(Material Type : UNTREATED TIMBER)					
(Plank Thickness(mm) : 75)					
(Plank Width(mm) : 300)					
Deck Rideability			6	6	
Deck Joints			N	N	(Loose cover plate at West abutment & over P5, slapping under traffic. 07Aug2007) Paved over.
Temperature (deg. C)		0			
(Expansion Type : SLIDING PLATES)					
(Fixed Type :)					
Gap Size (mm)		Gap Location			
Curbs/Wheel Guards			4	N	One split blocking @ SE corner - S8.-31-May-2008
(Curb Type : Standard)					
(Type : TREATED TIMBER)					
(Thickness(mm) : 150)					
(Width(mm) : 300)					
Bridge Rail			4	4	Double layer. Missing splice bolts, typical. Minor nicks/scratches.
(Type : GALVANIZED STEEL FLEX BEAM)					
Bridge Rail Posts/Blocking			4	4	
(Type : TREATED TIMBER;TREATED TIMBER)					Some rust perforations.
Bridge Rail/Posts Coating			5	5	
(Type : GALVANIZED)					
Sidewalk			X	X	
Wide Load Damage (Y/N)		No		Missing bolts adn gusset plate at L6E is buckling S4.	
Top Chord			6	6	Rusting, blistering. S4 L0W - missing 4 bolts, S4 L6W - missing 4 bolts, S4 L6E - missing 2 bolts at FB connection. 9 bay x 6 bay/span x 2 span. Not accessible to measure.
Batter Posts			4	5	
Diagonals			7	7	
Verticals			7	7	
Connections			4	4	
Floor Beams			5	5	
Bottom Chord			5	5	
Lateral Bracings			6	6	
(No. of Stringers : 108;Null)					
Stringer Detail Ratings					
	N (count)	1 (count)	2 (count)	3 (count)	
Last					
Now					
Stringers			6	6	
(Type : STEEL)					
(Width(mm) :)					
(Depth(mm) :)					
(Spacing(mm) : 853)					

Superstructure					
Bridge Component		Last	Now	Explanation of Condition	
(Secondary Span : PT)					
Paint Condition		3	3	Corroding. Silver.	
(Colour Description :)					
(Colour Code :)					
Touchup Required (Y/N)	No				
Bearings		3	3	Girders jammed together. Cracked/spalled South bearing pad on P3. Bearings are all non-funtional due to corrosion and to distortion due to earth pressures. Roller nests are jammed against anchor bolts or skewed due to being frozen. Disc and dome bearings dislodged. Two anchor bolts missing.-31-May-2008	
Temperature (deg. C)	18				
(Expansion Type : ROLLER NEST BEARING)					
(Fixed Type : DISC & DOME BEARING)					
Functioning (Y/N)	No				
Sub Deck/Deck Underside		4	4	Cracked ends, loose clips. Loose strip deck planks may indicate rot in subdeck.	
(Material Type : TREATED TIMBER)					
(Plank Thickness(mm) : 100)					
(Plank Width(mm) : 300)					
Defects (Percent Area)	3				
Span Alignment Problems					
Vertical (Y/N)	No				
Horizontal (Y/N)	No				
Superstructure General Rating		3	3		

Superstructure					
Bridge Component		Last	Now	Explanation of Condition	
(Secondary Span : PM)					
Special Features					
Special Feature			X	Span 2 & 3.	
(Type :)					
Special Feature			X		
(Type :)					
Wearing Surface/Deck Top Detail Ratings					
	N (%)	1 (%)	2 (%)	3 (%)	
Last	0	0	0	0	
Now					
Wearing Surface		6	6		
(Material Type : ACP)					
(Thickness(mm) : 50)					
Lateral Connection Problem (Y/N)	Yes				
Deck Top		N	N		
Deck Rideability		7	7		
Deck Joints		N	N	Paved over.	
Temperature (deg. C)	0				
(Expansion Type : SLIDING PLATES)					
(Fixed Type :)					
Gap Size (mm)	Gap Location				
25	Pier 5				

Superstructure						
Bridge Component		Last	Now	Explanation of Condition		
(Secondary Span : PM)						
Deck Drainage		7	7			
Drains Clogged (Y/N)	No					
Curbs/Median		4	4	Exposed rebar on a curb, scaling, cracked E curb S2.		
(Curb Type : Standard)						
Scaling (Percent Area)	15					
Bridge Rail		4	4	Single layer. Missing splice bolts, typical. Missing/loose nuts on 25% of post anchor bolts. Dirty.		
(Type : GALVANIZED STEEL FLEX BEAM)						
Bridge Rail Posts		3	3			
(Type : GALVANIZED POST STEEL; GALVANIZED POST STEEL)						
Bridge Rail/Posts Coating		7	7			
(Type : GALVANIZED)						
Sidewalk		X	X			
Girder Detail Ratings						
	N (count)	1 (count)	2 (count)	3 (count)		
Last	0	0	0	0		
Now						
Girders		4	4	Corrosin stains, minor. Curb girder with spot corrosion - both spans. Shallow delams in G9 of both spans.		
Cracking (Y/N)	No					
Spalling (Percent Area)	0					
(Number Of Girders : 18)						
Diaphragms/Cross Frame		X	X			
Bearings		5	4	P3 - Neoprene Strip. P2 - 100 x 300 timbers on flat stacked 4 high.-split/cracked and leaning.		
Temperature (deg. C)	0					
(Expansion Type : ROLLER NEST BEARING)						
(Fixed Type : DISC & DOME BEARING)						
Coating Adequate (Y/N)	Yes					
Functioning (Y/N)	Yes					
Deck Underside		N	N			
Stains (Percent Area)						
Span Alignment Problems						
Vertical (Y/N)	No					
Horizontal (Y/N)	No					
Superstructure General Rating		4	4			
Superstructure						
Bridge Component		Last	Now	Explanation of Condition		
(Secondary Span : HC)						
Special Features						
Special Feature			X	S1		
(Type :)						
Special Feature			X			
(Type :)						
Wearing Surface/Deck Top Detail Ratings						
	N (%)	1 (%)	2 (%)	3 (%)		
Last	0	0	0	0		
Now						

Superstructure							
Bridge Component		Last	Now	Explanation of Condition			
(Secondary Span : HC)							
Wearing Surface		6	6	Longitudinal crack in ACP.			
(Material Type : ACP)							
(Thickness(mm) : 50)							
Lateral Connection Problem (Y/N)	Yes						
Deck Top		N	N				
Deck Rideability		7	7				
Deck Joints		N	N				
Bump (Y/N)	No						
Deck Drainage		7	7				
Drains Clogged (Y/N)	No						
Curbs/Median		4	4	Cracked E curb. Scaling, rebar exposed. Delams along E curb.			
(Curb Type : Standard)							
Scaling (Percent Area)	25						
Bridge Rail		4	4	Single layer. Spliced incorrectly. Rail transition truss to precast poor. Missing/loose nuts on 50% of posts.			
(Type : GALVANIZED STEEL FLEX BEAM)							
Bridge Rail Posts		3	3				
(Type : GALVANIZED POST STEEL)							
Bridge Rail/Posts Coating		7	7				
(Type : GALVANIZED)							
Sidewalk		X	X				
Girder Detail Ratings							
	N (count)	1 (count)	2 (count)	3 (count)	S1 G6 has spall and wide cracks in both legs with sound concrete around exposed rebar. S1 G7 has wide crack with sound concrete in one leg and spall with sound concrete in the other leg. G8 WLC 1 leg sound concrete.		
Last	0	0	0	2			
Now	0	0	0	2			
Girders		3	3	Small crawl space between roof slab & girder. West end of girders supported by 100 x 300 timber stacked 5 high on flat sitting on concrete slab. Grout deteriorated G1 W curb.-31-May-2008			
Last Complete Inspection Date	06-Jan-2011						
Cracking (Y/N)	Yes						
Spalling (Percent Area)	5						
Lift or Connector Pocket Grouted (Y/N)	Yes						
(Number Of Girders : 9)							
Span Alignment Problems							
Vertical (Y/N)		No		The south hill pushes the bridge.			
Horizontal (Y/N)		Yes					
Superstructure General Rating		3	3				
Substructure							
Bridge Component		Last	Now	Explanation of Condition			
Abutments							
(Extended Backwall Piles (Y/N) : N)							
(Extended Backwall Piles Spacing(mm) :)							

Substructure									
Bridge Component		Last	Now	Explanation of Condition					
(Total Number of Caps/Corbels : 1:1)				S abutment not visible.					
Bearing Seats/Caps/Corbels Detail Ratings									
	N (count)	1 (count)	2 (count)				3 (count)		
Last	0	0	0				0		
Now									
Bearing Seats/Caps/Corbels			5				5		
(Type : CONCRETE)									
(Depth(mm) :)									
(Width(mm) :)									
Backwalls/Breastwalls			4				4		
Greatest Height (m)		0.50		N breastwall, heavy scaling. N abutment. Tops of ww at North scaling.					
Wingwalls			5				5		
(Total Number of Bearing Piles : 0:0)									
Piles Detail Ratings									
	N (count)	1 (count)	2 (count)				3 (count)		
Last	1	0	0				0		
Now	1	0	0				0		
Piles			N				N		
Paint/Coating			X				X		
Abutment Stability			4				4		
Scour/Erosion			7				4		
			Erosion gully at N & S headslopes.						
Piers/Bents									
(Type : PIER-SOLID)				4 river piers, 1 conc. pier, 2 pile piers. Pier 6 missing part of the nose and concrete abraded exposing rebar.					
(Total Number of Caps/Corbels : 19:1:1:1:1:1)									
Bearing Seats/Caps/Corbels Detail Ratings									
	N (count)	1 (count)	2 (count)				3 (count)		
Last	0	0	0				1		
Now	0	0	0				2		
Bearing Seats/Caps/Corbels			3				3		
(Type : CONCRETE)									
(Total Number of Bearing Piles : 14:5:0:0:0:0)									
Piles Detail Ratings							P2, P3 have pinned bearings @ base of piles/columns. Spalled/delam @ base of P3, typical both columns.		
	N (count)	1 (count)	2 (count)	3 (count)					
Last	0	0	0	0					
Now									
Pier Shaft/Piles			4	4					
Greatest Height (m)		12.60							
Bracing/Struts/Sheathing			5	5					
Nose Plate			3	3					
Paint/Coating			4	4					
(Colour Description : BLUE)									
(Colour Code : 15182)									
Pier Stability			4	4					
Scour			N	N					
Debris (Y/N)		No							

Substructure				
Bridge Component		Last	Now	Explanation of Condition
Substructure General Rating		3	3	
Structure Usage				
		Last	Now	Explanation of Condition
Channel				
(U/S Direction : W)				
(D/S Direction : E)				
Alignment		7	7	
Bank Stability		4	4	South hill slides putting entire bridge under stress.
HWM (m below Top of Curb)				HWM not visible.
Drift (Y/N)	No			
Slope Protection		7	7	
(Type : NATURAL; NATURAL)				
Guidebank/Spurs		X	X	
Adequacy of Opening		8	8	
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		4	4	

Maintenance Recommendations									
OTHER ACTION									
OTHER ACTION									
Structural Condition Rating (Last/Now) (%)		33.3/33.3	Sufficiency Rating (Last/Now) (%)		36.2/36.2	Est. Repl. Yr	2020	Maint. Req'd. (Y/N)	Yes
Special Comments for Next Inspection	Monitor girders for any deterioration from current condition. Monitor South headslope movements.			Department Comments					
Maintenance Reviewed By				Date			Estimated Total	0	
Proposed Long-Term Strategy									
On 3-Year Program (Y/N)									
Proposed Action									
Previous Inspector's Name	Randy Bredo			Previous Assistant's Name	Bryce Clayton				
Next Inspection Date	06-Apr-2014			Previous Inspection Date	31-May-2008				
Inspection Cycle (Default) (months)	39								
Comment									