



Photo S10A - 1 – Looking northbound from the south end of the site. The pattern and extent of the cracking in the road surface is similar to the conditions observed in 2009.



Photo S10A - 2 – Looking southbound from the north end of the site. Successive overlays have caused a steep drop to form at the edge of the road surface and have reduced the shoulder width. A guardrail may be required.