



**Photo S22-1** – Looking northbound from the east end of the site. The road surface has recently been milled which makes it difficult to compare the condition at the time of the inspection to past observations. The pattern and extent of the cracks in the road surface are similar to what was noted in 2009.



**Photo S22-2** – Looking northbound from the centre of the site.



**Photo S22-3** – Looking northbound from near the west end of the site. The cracking that has formed since the milling (or was exposed by the milling), follows the same pattern as past observation .s