



Photo S32-1 (top) – June 2010

Facing north towards the landslide area from the east slope crest. The site appears mostly unchanged from the 2009 inspection. The fenceline and highway are visible on the right hand side of the photo.

Photo S32-2 (bottom left) – June 2010

Facing north at the headscarp area where the slide is closest to the road. The scarp was approximately 1.7 m from the fenceline at the time of the inspection.



Photo S32-3 (bottom right) – June 2010

The scarp is continuing to retrogress, as indicated by the freshly slumped strip of soil with turf intact. This area is south from Photo S32-2 and further offset from the highway.

